

PHOTOGRAPHIC RECORD OF EXISTING ROOF



Client: Hopwood Hall College
Project: Conversion of Former Chapel
Reference: HCO-SEV-ZZ-ZZ-RP-A-09105
Date: October | 2025



REVISION

PROJECT TITLE	CONVERSION OF FORMER CHAPEL
PROJECT NUMBER	20765
CLIENT	HOPWOOD HALL COLLEGE
DOCUMENT TITLE	RECORD OF EXISTING ROOF
DOCUMENT NO.	HCO-SEV-XX-XX-RP-A-09105
DATE	01/10/25
AUTHOR	RS
REVISION	P01

REV	DESCRIPTION	DATE	AUTHOR	CHCKD
P01	Issued for Planning	06/10/25	RS	RS

CONTENTS

- 1.0 INTRODUCTION
- 2.0 KEY PLAN
- 3.0 PHOTOGRAPHIC RECORD



Aerial View (Image credit: Castle Keep Surveys)

1.0 INTRODUCTION

This document has been prepared to accompany an application to discharge the following Planning conditions in relation to a Listed Building Consent for works to the Grade II Listed former Chapel at Hopwood Hall College, ref.

24/00547/FUL

24/00548/LBC



Condition 10:

Prior to any works to the roof, a photographic survey of the roof shall be carried out and a sample and methodology for the replacement of the existing copper roof shall be submitted to and approved in writing by the Local Planning Authority. For the avoidance of doubt, this shall include details of new insulation. The re-roofing shall be undertaken in accordance with the approved details retained thereafter.



Aerial View (Image credit: Castle Keep Surveys)

2.0 KEY PLAN



EXISTING ROOF PLAN

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View towards Zone 1 (Image credit: Castle Keep Surveys)



View towards Zone 2 (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS




View towards Zone 3 (Image credit: Castle Keep Surveys)



View towards Zone 4 (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View towards Zone 5 (Image credit: Castle Keep Surveys)



View towards Zone 6 (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View towards Zone 7 (Image credit: Castle Keep Surveys)




View towards Zone 8 (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View of Glazed Lantern (Image credit: Castle Keep Surveys)



View of Glazed Lantern (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View of Glazed Lantern (Image credit: Castle Keep Surveys)



View of Glazed Lantern (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View of Glazed Lantern (Image credit: Castle Keep Surveys)



View of Glazed Lantern (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View of Glazed Lantern (Image credit: Castle Keep Surveys)



View of Glazed Lantern (Image credit: Castle Keep Surveys)

3.0 PHOTOGRAPHIC RECORD

3.1 GENERAL PHOTOGRAPHS



View towards Zone 9 (Image credit: Castle Keep Surveys)



View towards Glazed Lantern (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Parapet Gutter (Image credit: Seven Architecture)



View showing Parapet Gutter (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Copper Roof Covering (Image credit: Seven Architecture)



View showing Parapet Gutter (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Parapet Gutter (Image credit: Seven Architecture)



View showing Parapet Gutter Drainage Outlet (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Existing Copper Roof Covering (Image credit: Seven Architecture)



View showing Existing Copper Roof Covering (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Glazed Lantern (Image credit: Seven Architecture)




View showing Copper Cladding to Glazed Lantern (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Glazed Lantern (Image credit: Seven Architecture)



View showing Copper Cladding to Glazed Lantern (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



View showing Door within Glazed Lantern (Image credit: Seven Architecture)



View showing Glazed Lantern (Image credit: Seven Architecture)

3.0 PHOTOGRAPHIC RECORD

3.2 DETAILED PHOTOGRAPHS



Close Up View showing Glazed Lantern (Image credit: Seven Architecture)



Close Up View showing Glazed Lantern (Image credit: Seven Architecture)