



Remnant hardstanding in former Tack Lea works building.



Former dyeworks looking towards Naden Brook (see visible building across watercourse). Hardstanding and scrub vegetation.

Hardstanding and scrub vegetation.



BUILDING 1 & 2 SITE 2



SITE 2 - EXISTING EXTERIOR BUILDING 1



SITE 2 - EXISTING EXTERIOR BUILDING 1



SITE 2 - EXISTING EXTERIOR BUILDING 1



SITE 2 - EXISTING EXTERIOR BUILDING 2



SITE 2 - EXISTING EXTERIOR BUILDING 2



SITE 2 - EXISTING EXTERIOR BUILDING 2



FORMER BOILER HOUSE AND GARAGE



SITE 2 - EXTERIOR OF OUTBUILDING



Former dyeworks looking towards Naden Brook (see visible building across watercourse). Hardstanding and scrub vegetation.


Hardstanding and scrub vegetation.



View northwest of Shepherd Mill from the site entrance. Woodhouse Mill Brook present beyond trees in the distance and Naden Brook at a lower level to the left of photograph.



Hardstanding present on Shepherd Mill.



Aerial photographic plate showing the site and boundary woodland.



PLOTS KEY PLAN

Client	M. HALL
Project	Norden, Rochdale
Drawing	Existing Location Plan
Status	Information
Scale	1:1250 at A3
Date	02.11.2020
Drawn	MS
Project No.	1059
Drawing No.	1059-TG-A-XX-00-DR-A-0201
Revision	B