







ARCHITECTURE

Home extension
2426
103 Hartley Lane

New York Street, Manchester, M1 4BT.
www.m1architecture.co.uk
Telephone: 0330 311 9695

Site Plan 1:200@A3
Existing and Proposed

01.



ARCHITECTURE

New York Street, Manchester, M1 4BT.
www.m1architecture.co.uk
Telephone: 0330 311 9695

Home extension

103 Hartley Lane

2426

01.

Site Plan 1:200@A3
Existing and Proposed




Front Elevation


Side Elevation

Rear Elevation


Sectional Side Elevation



Ground floor



First floor



Loft structure



ARCHITECTURE

New York Street, Manchester, M1 4BT.
www.m1architecture.co.uk
Telephone: 0330 311 9695

Home extension
103 Hartley Lane


2426

01.


Floor Plans & Elevations

1:100@A3

Existing



Front Elevation




Side Elevation

- New double glazed Velux windows to client specification.
- Roof tiles to match existing.
- New double glazed External doors to client specification.
- Facing brickwork to match existing. Brickwork details to match existing.



Rear Elevation



Ground floor



ARCHITECTURE

New York Street, Manchester, M1 4BT.
www.m1architecture.co.uk
Telephone: 0330 311 9695

Home extension

2426

02.

Floor Plans 1:100@A3
Proposed

This drawing is the property of M1 Architecture and copyright is reserved by them.

This drawing is not to be copied or disclosed by or to any unauthorized person without the prior written consent of M1 Architecture Ltd.

All dimensions are to be checked on site prior to construction, manufacture of any components and ordering of materials and equipment.

Any discrepancies are to be reported to the architects.

All materials and workmanship to be accordance with the current British Standards and codes of practice.

This drawing is to be read in conjunction with all relevant Architectural Structural Engineers, Mechanical Engineers, Electrical Engineers and Specialists drawings and specifications.

All drainage to be inspected and approved by building control.

Direction of Joists were not available during the survey therefore it is the responsibility of the contractor to check the existing structure and its mechanism of support.