

Week 7– W/E 27.09.2024 – Stonework repairs, copings, brickwork raking out and re-pointing



Mortar samples for the stonework. Initial to the left and preferred to the right



Dismantled entrance gable buttress being re-built and tied in for future stability..



Completed coping, flashing detail and pointing to the meeting room roof.




Copings to the flat roof parapet prepared and drilled to receive locating dowels.



Reading room gable raked out ready for re-pointing.



Meeting room windows uncovered to reveal areas of rot.



Chimney repaired and pointed. Final flashing detail to be completed..



Copings and gutter flashing, facing the Old Police Station, flashed and re-installed. Brickwork raked out ready for re-pointing.

