


Week 3– Stage Floor lifted to reveal oriel window support frame




Additional access control to the rear following unauthorized access to the scaffolding




Additional hoarding – scaffold on-going




Access routes closed off



Detailed survey by architect of existing oriel window support structure



Sketched and photographs issued to the Structural Engineer for comment and recommendations



--.