

Week 2 – Stage Floor lifted to reveal oriel window support frame




Floor boards removed and steel frame base uncovered and surveyed



Internal beams supporting the previous remedial support frame and the original construction



Steelwork added around 2000 to give additional support to the window



Mortar sample for the brickwork.



Scaffolding to the rear and side of the building



Scaffolding to the front of the building.