


TECHNICAL AUDIT SITE INSPECTION REPORT

Planning ref Number	23/01280/FUL	Inspections Required:	6 Monthly
Address:	Longley Hey Farm Halifax Rd Littleborough OL15 OLB	Inspection No:	1
Description:	Path Dilapidation- Ref to Condition 4	Date:	11/06/24
		Time on site:	9.00am
Inspection Type:	PreCommencement ☒ Substructure ☐ Drainage ☐ Damp proofing ☐ Superstructure ☐ Fire ☐ Services ☐ Intermediate ☐ Stage ☒ Completion ☐		
Weather:	Overcast 10 Deg	Photographs:	Yes
		Inspection Made with Contractor / Developer:	Yes
Developer / Contractor Details:	Organisation / Developer: Mr Mick Slicker Site Contact Name: - Site Contact Email / mick@fourwayprojects.co.uk Tel Number / 07985699898		
Summary of Visit:	Farm track is used as vehicle access alongside a footpath as a right of way through part. The path is made up of hardcore in areas and existing tarmac in areas. No obstructions are apparent.		

1.00	Observations	Current Status
------	--------------	----------------

.01 Path make up and current state.

Information required





2.00	Other matters arising	
	NEXT VISIT	
	January 2025	