

Existing Vent Photographs
Photographs - January 2024




Image 01/04 -
Section of Exhibition boarding removed to reveal locaton of typical vent (gallery 04).



Image 02/04 -
Closer look at vent position, brickwork opening and grille height. Grille sits directly behind existing brickwork meaning (cold) air needs to rise in order to enter space. S/o in brickwork for air movement is located at a higher level to external grille.



Image 03/04 -
Photograph from within cavity looking at ventilation grille.



Image 04/04 -
External photograph looking at a typical ventilation grille condition.