

Image 01 - Gallery 02
Photograph c.2024



Notes:
Pipework exposed, but hidden by exhibition boards projection/shadow gap detail to base of walls. Exhibition boards are projecting further into the space than shown in historic photos. Rear partition moved to be in line with final truss to create a larger store.

Image 02 - Gallery 02
Photograph c.2024



Notes:
Closer view of rear partition moved to be in line with final truss to create a larger store and additional door to the right hand side compared to the original design.

Image 03 - Gallery 03
Photograph c.2024



Notes:
Pipework exposed, but hidden by exhibition boards projection/shadow gap detail to base of walls. No sign of the original heating panelling detail.

Image 04 - Gallery 04
Photograph c.2024



Notes:
Pipework exposed, but hidden by exhibition boards projection / shadow gap detail to base of walls. Existing extract ventilation visible at roof level.

