

Existing Wall Coverings Condition (Exhibition Boards Removed)
Photographs - February 2024 onwards



Image 01/04 -
Example area around escape door where existing wall coverings have been removed (historically). The exposed brickwork was uncovered following the exhibition boards removal.



Image 02/04 -
Example area where existing wall coverings came loose following exhibition board removal due to deteriorated fixing points / general poor condition. Brickwork and (one of many) existing ventilation point became exposed.



Image 03/04 -
Close up image of existing cut through wall coverings for historic metal frame fixing points throughout gallery spaces. Historic cutting of wall covering has meant T&G / boarding has become less secure and is in poor condition as visible in images.



Image 04/04 -
Image highlighting numerous locations where T&G has been cut to allow for metal frame fixing into brickwork behind (image from Gallery 3). Non-original overboarding included to support T&G behind due to poor condition.