




- Assessment Boundary
- Infrastructure

Turbine Locations

Infrastructure Layout
- 
- Floating Track

Peatland Condition Assessment

Actively Eroding

Modified

Modified with Near-Natural Features Retained

Target Notes

© Crown copyright and database rights 2026 Ordnance Survey 0100031673.

Project Name:

SCOUT MOOR II

Figure 14.11:

Peatland Condition Assessment

