

- Institute new rainwater goods in powder coated aluminium
- Repoint with lime mortar and general fabric repair throughout
- Replace windows and doors as needed
- Institute coordinated security bar scheme to window and door openings throughout

