

Photograph 21 – Cellar area to Office



Photograph 22 – Cellar area to Office – Timber Props to floor



Photograph 23 – First floor support beams to Office



Photograph 24 – Opening to South East Wall



Photograph 25 – Random stone inner leaf - Office



Photograph 26 – Hip rafter within roof space to Office



Photograph 27 – Hip rafter within roof space to Office



Photograph 28 – Chimney within roofspace to Office



Photograph 29 – Underside of roof truss to Office



Photograph 30 – Internal Cracking to South East wall of Office



Photograph 31 – Floor Slab to Warehouse



Photograph 32 – General View of Warehouse



Photograph 33 – Cast Iron Column replacement to Warehouse



Photograph 34 – Exposed column foundation in Warehouse



Photograph 35 – South West elevation to Warehouse



Photograph 36 – Rusting steelwork to South West elevation of Warehouse



Photograph 37 – Rusting steelwork to South East elevation of Warehouse



Photograph 38 – Area of removed 1st floor to Warehouse



Photograph 39 - North Light roof to Warehouse



Photograph 40 - Rusting Steelwork to Warehouse



Photograph 41 - Lateral Movement of Parapet to Warehouse



Photograph 42 - Rusting steelwork to 1st floor lintels of Warehouse



Photograph 43 - Rusting roof steelwork to Warehouse



Photograph 44 - Leaking Roof / Rotten roof timbers to Warehouse