

Genera

- ### Rainwater Goods/Ironmongery
- Ensure all existing rainwater goods are adequately fixed back to the building with stainless steel fixings and all are blockage free. Allow to repair/replace any damaged sections of pipe as appropriate (to be scheduled when scaffold erected allowing closer inspection). Include to re-decorate all cast iron sections
 - All existing metal work (vents etc.) to be prepared and re-painted as part of works

RF

— —

1

Leaded windows

