



The Drain Unblocking Company,

83-87 Fielding
Street
Middleton
Manchester
M24 6BG

Date 23/01/25

Site Report

Site Inspection Report: Investigation of Line Redundancy

We attended the site to expose a manhole in order to ascertain whether a particular line is redundant. During the investigation, we excavated down to a depth of approximately 1.5m and gained access to a concealed manhole, which was covered by a concrete slab.

Upon breaking through the slab, we discovered that the manhole descends an additional 1.3m approximately. Upon inspection, it was observed that the line leading from off-boundary to MH2 appears to be redundant. The line is heavily filled with debris, preventing the passage of a camera beyond 8m.

Given the extent of debris and the inability to progress further, it is evident that the line has not been in use for a significant amount of time. While the line has not collapsed, the debris buildup strongly suggests that upstream blockages would have occurred if the line were still active.


In our professional opinion, the line leading from off-boundary to MH2 is redundant and, therefore, falls outside the jurisdiction of United Utilities.

SEE PIC BELOW

E-mail: info@thedrainunblockingcompany.com

Tel: 07375521027

Company Number: 11241567



E-mail: info@thedrainunblockingcompany.com

Tel: 07375521027

Company Number: 11241567



E-mail: info@thedrainunblockingcompany.com

Tel: 07375521027

Company Number: 11241567



E-mail: info@thedrainunblockingcompany.com

Tel: 07375521027

Company Number: 11241567



David Arnfield

0161 738 1993

07375 521 027

E-mail: info@thedrainunblockingcompany.com

Tel: 07375521027

Company Number: 11241567



E-mail: info@thedrainunblockingcompany.com

Tel: 07375521027

Company Number: 11241567