



North East Elevation
1:100



South East Elevation
1:100

Refer to ESD report 5410 Structural
Repairs & methodology

Denotes mortar to be repointed and
masonry rebuilt as required.

P1	PRELIMINARY ISSUE	SC	BR	08/08/25
REV	DESCRIPTION	BY	CHK	DATE

EDGE
CIVIL & STRUCTURAL CONSULTANCY

Edge Structural Design Limited
info@edgestructuraldesign.com | 0161 620 9988 | edgestructuraldesign.com

Client Grandstream Properties Ltd

Project Silver Hill Farm
Rochdale

Drawing Title Farmhouse
Elevations sheet 1

Project No. 5410

Drawing No. 016

Revision P1

PRELIMINARY