DO NOT SCALE, IF IN DOUBT ASK. DO NOT INTERROGATE CAD BASE


GENERAL NOTES

1. REFER TO DRAWING 220 FOR NOTES AND DETAILS

KEY


- A — DENOTES AREA OF CORRODED STEEL (REFER TO REPAIR DETAIL A)
- B — DENOTES AREA OF LOOSE CONCRETE (REFER TO REPAIR DETAIL B)
- C — DENOTES AREA OF DAMP CONCRETE / CONCRETE WITH SURFACE DEGRADATION (REFER TO REPAIR DETAIL C)

EXTENT OF REPAIRS TO BE CONFIRMED. FINAL EXTENT OF WORKS TO BE CONFIRMED FOLLOWING CONCRETE CARBONATION & CHLORINATION TESTS, COVER METER TESTS, REMOVAL OF ROOF COVERING, HIGH LEVEL SURVEY.




ELEVATION 4
SCALE - 1:100

*



ELEVATION 3
SCALE - 1:100



REV.	DATE.	REVISION.	BY.	CHK.
–		FIRST ISSUE.	CD	SJ

Hopwood College

Milnrow Chapel

Proposed Concrete Repairs
Elevations Sheet 2 of 2

Goodson Associates
Tel: +44 (0)113 369 7925
Fax: -
Email: leeds@goodsons.com
Web: www.goodsons.com
Consulting Civil, Structural & Transportation Engineers
Fountain House, 4 South Parade,
Leeds, LS1 5QX
Also at Aberdeen, Edinburgh and Glasgow.

PRELIMINARY

DATE CREATED:	May 2024	SCALE:	1:100 @ A1
CONTRACT No: P15715	DRAWING No: 211	REV: -	