

Photograph 1 – South West Elevation (Front) to Hare Hill Road



Photograph 2 – South West Elevation (Front) to Office



Photograph 3 – South West Elevation (Front) to Warehouse



Photograph 4 – North West Elevation to Office



Photograph 5 – North East Elevation (Rear) to Office



Photograph 6 – North East Elevation (Rear) to Warehouse



Photograph 7 – Lateral movement to parapet



Photograph 8 – Stepped cracking to RHS of window



Photograph 9 – Stepped cracking to LHS of window



Photograph 10 – Outward movement of stone to between windows



Photograph 11 – Delamination of stone facings to Warehouse



Photograph 12 – Delamination of stone facings to Office



Photograph 13 – Delamination of stone quoins to Office



Photograph 14 – Cracking to stone quions to Office



Photograph 15 – Enlarged window opening to Office



Photograph 16 – Former Canopy steelwork to Office



Photograph 17 – Cut back stone steps to Office



Photograph 18 – South East Party Wall



Photograph 19 – North East elevation (Rear) to warehouse



Photograph 20– Strapping to brick Pikes