
Proposed work to Wardle Community Church graveyard conservation area and No2 Vineyard Cottage, Knowl Syke Street, Wardle

Potential work to commence after 6 week period

Beechwood Tree Services North West Ltd
Richard Lees
07939752035
Richard_lees@live.co.uk




No	Tree Species	Condition	Recommend Work
1	Ash	Signs of decline/canopy	Fell
2	Willow	Multi stem/fair/dead wooding	Dead wood/ remove branches
3	Silver Birch	Fair	Dead wooding
4	Willow	Ok	Dead wooding
5	Willow	Poor/ bark missing	Fell
6	Large Ash	Fair given age (check cavity)	Dead wood/ remove limb over street
7	4 stem Syc	Ok/Leggy	Fell
8	2 Syc/ 2 Birch	Ok/ Leggy	Fell
9	Syc	Ok/ Leggy/. Growing from grave	Fell
10	Syc	Ok/ next to headstone	Fell
11	Elderberry	Poor/ Rotten	Fell
12	—————	—————	—————
13	Willow	Ok	Remove lower overhanging branches from lane
14	Hawthorn	Poor	Fell
15	Ash	Poor/ Dieback	Fell (over hanging vehicles)
16	Ash	Fair/ Slight decline	Deadwood/ Fell?
17	Ash	Ok	Dead wood
18	Ash	Poor/ Severe dieback	Fell
19	Silver Birch	Ok	Dead wood
20	Syc 6 stem	Ok	Lift lower branches over car park
21	Pine	Poor specimen	Fell
22	5 stem Ash	Tall leggy	Fell/ Damaging wall
23	Holly	Ok	Fell? / Damaging grave
24	Holly	Ok	Remove? / Growing from grave
25	Holly	Ok	Remove? / Next to gravestone
26	Ash	Ok/ Leggy	Remove/ Next to wall
27	Ash	Ok/ Leggy	Remove/ Next to wall
28	Ash	Ok/Leggy	None
29	Ash	Ok/ Leggy	Remove/ Next to wall
30	Syc	Ok	None

Mr Martin Walker – 2 Vineyard Cottage, Knowl Syke Street, Wardle
01706 377524

No	Tree Species	Condition	Recommend work
31	Yew	Ok	Too big blocking light (fell)
32	Beech	Ok	Reduce back from chimney and conservatory. Lift/ dead wood


1


2/4


3



5


6


7


8



9


10


11



13




15



16


17


18


19



20


21


22


23


24


25


26/27/28/29


31


32


32