

Miss Rebecca Siddall

Milton Street, Middleton

Phase 1 Desk Study Report (Preliminary Risk Assessment)

OCTOBER 2020

GENERAL NOTES


Title: Phase 1 Desk Study Report (Preliminary Risk Assessment): Milton Street, Middleton

Client: Miss R Siddall

Date: October 2020

Status: Final

Author John Harrison BEng (Hons) FGS

Signature 

Date: October 2020

CONTENTS

1 INTRODUCTION 1
1.1 Objective 1
1.2 Development proposals 1
1.3 Scope 1
1.4 Limitations 2
2 THE SITE 3
2.1 Site location and description 3
2.2 Site walkover 3
2.3 Ground conditions 4
2.3.1 Geology 4
2.3.2 Radon 4
2.3.3 Landfilling and land reclamation 4
2.3.4 Ground gas 5
2.4 Mining and quarrying 5
2.5 Hydrogeology 5
2.5.1 Aquifer characteristics 5
2.5.2 Vulnerability of groundwater resources 5
2.5.3 Licensed groundwater abstraction 5
2.6 Hydrology 6
2.6.1 Surface watercourses 6
2.6.2 Surface water abstractions 6
2.6.3 Site drainage 6
2.7 History of site and surrounding area 6
2.8 Sensitive Land Uses 7
3 INITIAL CONCEPTUAL MODEL 8
3.1.1 Summary of potential contaminant sources 8
3.1.2 Sensitive receptors 8
3.1.3 Summary of plausible pathways 8
3.1.4 Potentially complete pollutant linkages 9
4 PHASE 1 GEOTECHNICAL APPRAISAL 10
4.1 Foundations 10
4.2 Excavation Stability 10
5 CONCLUSIONS AND RECOMMENDATIONS 11
5.1 Phase 1 Environmental Considerations 11
5.2 Phase 1 Geotechnical Assessment 11

TABLES

Table 1: Site setting 3
Table 2: Geology at the site 4
Table 3: Summary of historical development 6
Table 4: Potential sources and types of contamination 8
Table 5: Risk estimation for potentially complete pollutant linkages 9

FIGURES

Figure 1 Site location plan

Figure 2 Site features plan

Figure 3 Proposed development plan

APPENDICES

Appendix A Summary of legislation and policy relating to contaminated land

Appendix B Site photographs and walkover checklist

Appendix C Environmental Database Report

Appendix D Risk assessment methodology

1 INTRODUCTION

This Phase 1 Desk Study Report (Preliminary Risk Assessment) for land at Milton Street, Middleton was commissioned by Miss Rebecca Siddall.

1.1 Objective

The objective of the work is to provide the client with geo-environmental information to support the redevelopment of the site.

In addition, the report is also to satisfy Rochdale Borough Council Planning Permission (20/00567/FUL) Condition 9.

1.2 Development proposals

It is understood that the intention is to develop the site with two semi-detached plots (4 dwellings) with gardens and driveways, a proposed layout is shown on Figure 3.

1.3 Scope

The scope of this assessment has been developed in accordance with relevant British Standards and authoritative technical guidance as referenced through the report. The assessment of the contamination status of the site is in line with the technical approach presented in the new LCRM (October 2020) and predecessor guidance in CLR 11 Model Procedures for the Management of Land Contamination (Environment Agency, 2004) and in general accordance with BS 10175: 2011 + A2 2017 (BSI, 2017). It is also compliant with relevant planning policy and guidance.

A brief summary of relevant legislation and policy relating to contaminated land is given in Appendix A.

The scope of works for the assessment has included the following:

Desk Study:

- review of the history of development on the site and surroundings, including a study of historical ordnance Survey mapping and other sources of historical information via an environmental database report

- assessment of local geology, hydrogeology and surface water setting, including the identification of potential geological hazards including mining etc.

- review of relevant information held by appropriate statutory authorities, e.g. local authority Environmental Health Departments and Environment Agency, obtained from the environmental database report

- completion of a site reconnaissance survey to assess the visual condition of the site

- development of an initial conceptual site model (CSM) identifying potential contaminant linkages for potential contaminants, completion of a preliminary risk assessment (PRA) and identification of key uncertainties and assumptions in the CSM

- preliminary consideration of geotechnical constraints and hazards

- identification of the need for further action, e.g. intrusive investigations, if any.

1.4 Limitations

The study aims principally to identify and assess the potential risks and liabilities associated with contamination of the ground, on and in the vicinity of the site. While this includes consideration of current operations and housekeeping on the site, the report does not constitute a comprehensive environmental audit of the site, as covered under ISO 14001.

The study was designed generally to meet the objectives of a preliminary (phase 1) investigation, as defined by BS 10175:2011 (BSI, 2017).

This report should be considered in the light of any changes in legislation, statutory requirement or industry practices that have occurred subsequent to the date of issue.

The opinions expressed in this report, and the comments and recommendations given, are based on the information obtained from the desk assessment and the site reconnaissance survey.

2 THE SITE

2.1 Site location and description

The site is located on Milton Street, Middleton at National Grid reference 386810, 406190, as shown on Figure 1.

The area around the site is residential, as detailed in Table 1.

Table 1: Site setting

To the north:	Terraced housing
To the east:	Milton Street, former nursery now residential development.
To the south:	Terraced housing
To the west:	Terraced housing

The site covers an area of 0.08 hectares and currently comprises open ground. The site is roughly rectangular in shape and is accessed to the east of Milton Street.

The site was once occupied by offices belonging to the Citizen Advice Bureaux, the buildings has been recently demolished and all demolition material removed from site.

The topography of the site relatively level.

Site features are shown on Figure 2.

2.2 Site walkover

The site was visited on 9th October 2020 to undertake a site walkover. Photographs and the site walkover checklist are provided in Appendix B.

No potentially contaminative activities were identified on site during the site reconnaissance survey.

The site was once occupied by an office building which has now been demolished and the site cleared. Some brick and concrete rubble was present across the surface of the site.

No evidence of oil spillages, storage of chemicals or hydrocarbons were identified during the site walkover.

Japanese knotweed was not identified during the site visit.

2.3 Ground conditions

2.3.1 Geology

Published records (British Geological Survey, October 2020) for the area indicated the geology of the site to be characterised by the succession recorded in Table 2.

Table 2: Geology at the site

Geological unit	Description
Glaciofluvial Sheet Deposits	Sand and gravel
Pennine Lower Coal Measures	Undifferentiated Mudstone, Siltstone and Sandstone
Source: British Geological Survey website, October 2020	

2.3.2 Radon

The site is located in an area with less than 1% of homes above the Action Level as defined by the Documents of the National Radiological Protection Board (Radon Atlas of England and Wales, NRPB-W26-2002).

No radon protective measures are required within new buildings at this site.

2.3.3 Landfilling and land reclamation

Evidence has been sought to identify any landfilling or land reclamation operations, past and present, which have taken place in the vicinity of the site. The sources of information referenced in this element of the desk study include:

- environmental database report
- old Ordnance Survey maps and plans
- geological maps

Three historic landfill sites are located to the north of the site, details are provided below;

- D069, Mirefield Drive – 70m north of the site
- D068, Mellalieu Street Playing Fields – 220m north of the site
- D100, Land off Higher Wood Street – 240m north of the site.

Given the age and size of the historic landfill sites and the potential risk of ground gas is considered to be low.

No other landfill sites are located within 250m of the site.

A historic reservoir is located 85m east of the site, the reservoir has been developed with housing and does not appear to have been backfilled.

2.3.4 Ground gas

Based on the sites geological setting and site use it is considered that the site has a very low ground gas generation potential in accordance with BS8576.

2.4 Mining and quarrying

Evidence has been sought to identify any mining and quarrying operations, past and present, which have taken place in the vicinity of the site. The sources of information referenced in this element of the desk study include:

- an environmental database report
- old Ordnance Survey maps and plans
- geological maps
- Coal Authority website

No quarries, mine entries, coal outcrops or shallow coal workings are recorded within the vicinity of the site.

2.5 Hydrogeology

2.5.1 Aquifer characteristics

The superficial deposits and bedrock underlying site have been classified by the EA as a Secondary A Aquifer. These are described by the Environment Agency as *'permeable layers capable of supporting water supplies at a local rather than strategic scale, and in some cases forming an important source of base flow to rivers. These are generally aquifers formerly classified as minor aquifers'.*

2.5.2 Vulnerability of groundwater resources

The soils beneath the site are classified as having high (H) leaching potential; soils of high leaching potential are those with little ability to attenuate diffuse source pollutants and where non-adsorbed diffuse source pollutants and liquid discharges can move rapidly to underlying strata or shallow groundwater.

2.5.3 Licensed groundwater abstraction

No current groundwater abstractions were identified within a 1km radius of the site.

2.6 Hydrology

2.6.1 Surface watercourses

The nearest water course is the River Irk located 457m to the south east.

2.6.2 Surface water abstractions

The nearest current surface water abstraction is located 611m south of the site, this is used for boiler feed water.

2.6.3 Site drainage

Surface water and foul drainage are present on site relating to the existing cottage.

2.7 History of site and surrounding area

The history of the land-use and development of the site and surrounding area has been assessed based on the following sources:

- historical maps within the environmental database from 1848 to 2020

Copies of OS and County Series maps are included in the environmental database report in Appendix C. Reference to historical maps provides invaluable information regarding the land use history of the site, but historical evidence may be incomplete for the period pre-dating the first edition and between successive maps.

The development history of the site and surrounding area from the above sources is summarised below. Historical features of interest to this PRA are highlighted in bold.

The site has remained undeveloped as shown on all historic mapping.

Table 3: Summary of historical development

Date	Land use/features on site	Land use/features in vicinity of site (of relevance to the assessment)
1848	Open ground	Open ground
1893	No change	Reservoir shown 85m to the east. Kid Clough Dye works located 100m to the south east
1909	No change	Tanks shown 100m to the south east. Terrace housing to the north and east
1923	No change	Milton Street shown to the east.

1932 - 1938	Employment Exchange Building shown on site	Evidence of filled ground located 80m and 200m north of the site (historic landfills) More residential development around the site.
1956 - 1960	No change	Filled ground to the 80m north has been developed with housing.
1965	No change	Reservoir to the east has reduced in size. Tanks no longer shown
1977	No change	Reservoir no longer shown, though banks still present.
1983	No change	Dye works no longer shown. Housing shown on reservoir area
1999	No change	No change
2020	No change	No change

2.8 Sensitive Land Uses

No SSSIs, RAMSAR or other sensitive land uses are located within 1000m of the site.

A nature reserve, Alkrington Woods, is located 600m south of the site.

3 INITIAL CONCEPTUAL MODEL

The information presented in previous sections, has been used to compile an initial conceptual model. The identified potential sources of contamination, associated contaminants and receptors have been considered with plausible pathways that may link them. The resulting potential pollutant linkages are considered below. The risk classification has been estimated in accordance with information in Appendix D.

The site was occupied by an old Citizen Advice Bureaux office, no sources of potential contamination have been identified within or close to the site.

There is the possibility of a veneer of made ground associated with the former offices on site.

3.1.1 Summary of potential contaminant sources

Potential sources and contaminants of concern are summarised in Table 4.

Table 4: Potential sources and types of contamination

Potential sources	Contaminants of concern
On-site	
Possible veneer of made ground associated with former CAB office	Heavy metals, ash, clinker, sulphates, polycyclic aromatic hydrocarbons (PAHs), ACM etc
Off-site	
Historic Landfills to the north of the site	Hazardous ground gas

3.1.2 Sensitive receptors

Sensitive receptors at this site include:

- future site occupants
- groundwater

Please note that construction workers have not been identified in the conceptual model as receptors because risks are considered to be managed through health and safety procedures including CDM regulations.

3.1.3 Summary of plausible pathways

The plausible pathways are summarised below:

- Direct contact, inhalation and indigestion

- migration of mobile contaminants though soil and groundwater
- migration of ground gas

3.1.4 Potentially complete pollutant linkages

The information presented in the above sections has been used to compile an outline conceptual model. The potential contaminants and receptors identified have been considered along with any possible pathways that might link them. The resultant pollutant linkages are considered in Table 5.

There are no potential pollutant linkages with a risk of moderate or above that may drive site investigation works.

Table 5: Risk estimation for potentially complete pollutant linkages

Potential contaminant source	Potential receptor	Possible pathway	Likelihood	Severity	Risk and justification
On site					
Possible Made ground	Future site occupants	Direct contact, inhalation and indigestion	**Unlikely**	**Medium**	**Low –** No significant made ground was identified on site and the former use as an office is considered have a very low risk of potential ground contamination.
	Groundwater	Migration of mobile contaminants though soils and groundwater			
Off site					
Historic Landfills	Future site occupants	Migration of ground gas	**Unlikely**	**Severe**	**Low –** Landfills to the north of the site are relatively old and appear to be land rising. Given the age and distance from site the risk from ground gas is considered low.
	Buildings and infrastructure				

4 PHASE 1 GEOTECHNICAL APPRAISAL

The following geotechnical assessment is based on the information obtained from desk based sources and should be considered preliminary.

4.1 Foundations

Available information indicates that the ground conditions across the site comprise granular glacial deposits. It is considered that spread foundations on medium dense sand and gravel should be suitable at this site

4.2 Excavation Stability

Medium dense granular deposits should be stable in the short term.

5 CONCLUSIONS AND RECOMMENDATIONS

5.1 Phase 1 Environmental Considerations

The proposed development comprises 4 dwellings (2 semi-detached properties) with gardens and driveways.

The review of the information and the construction of the outline conceptual model has highlighted potential pollutant linkages associated with the site.

However, the identified pollutant linkages are of low risk and do not require any further investigation.

5.2 Phase 1 Geotechnical Assessment

Ground conditions are indicated to comprise granular glacial deposits over coal measures strata.

Traditional strip/trench are likely to be feasible within the medium dense granular glacial deposits.

FIGURES

Location Plan of Former Citizens Advice Bureau (CAB) Offices , Milton Street, Middleton, M24 5TU




This Plan includes the following Licensed Data: OS MasterMap Colour PDF Location Plan by the Ordnance Survey National Geographic Database and incorporating surveyed revision available at the date of production. Reproduction in whole or in part is prohibited without the prior permission of Ordnance Survey. The representation of a road, track or path is no evidence of a right of way. The representation of features, as lines is no evidence of a property boundary. © Crown copyright and database rights, 2020. Ordnance Survey 0100031673

Scale: 1:1250, paper size: A4

35 the studio
architectural design


emapsite™
plans

Prepared by: Alex Karanikolas, 24-05-2020


Rough/Unsurfaced Ground
Trees/ shrubs
Manhole
27
N STREET




milton street




key

- gardens to be turfed or planted with shrubs
- driveways to be tarmac
- patios to be natural stone paving
- proposed new trees/ planting
- proposed hedging
- site boundary
- bins location

fence detail A 1:25



typical elevation




typical section

all timber is to be pressure impregnated with preservative to BS5529 cat a



typical plan view

wall detail B 1:25



typical front elevation



typical plan view 1:25



typical side elevation

notes

this drawing is the copyright of 35 the studio limited and not to be copied or used without prior consent.

dimensions indicated to be followed in preference to scale.

all dimensions to be checked on site prior to the commencement of any work being carried out. any discrepencies to be reported & resolved prior to work commencing.

client
rebecca siddall

project
former middleton citizens advice bureau, milton street
middleton, m24 5tu

drawing title
proposed site plan

drawing no. siddall/01 rev.

drawn by	scale	date
a.k.	1:100@A1	apr 2020

35 the studio limited
35 mayfield avenue,
adlington, chorley,
PR6 9QE

t: 07702 185 467
e: info@35thestudio.co.uk
w: www.35thestudio.co.uk

35 the studio
architectural design

APPENDIX A
SUMMARY OF LEGISLATION AND POLICY RELATING TO CONTAMINATED LAND

Part IIA of the Environmental Protection Act 1990 (EPA) and its associated Contaminated Land Regulations 2000 (SI 2000/227), which came into force in England on 1 April 2000, formed the basis for the current regulatory framework and the statutory regime for the identification and remediation of contaminated land. Part IIA of the EPA 1990 defines contaminated land as 'any land which appears to the Local Authority in whose area it is situated to be in such a condition by reason of substances in, on or under the land, that significant harm is being caused, or that there is significant possibility of significant harm being caused, or that pollution of controlled waters is being or is likely to be caused'. Controlled waters are considered to include all groundwater, inland waters and estuaries.

In August 2006, the Contaminated Land (England) Regulations 2006 (SI 2006/1380) were implemented, which extended the statutory regime to include Part IIA of the EPA as originally introduced on 1 April 2000, together with changes intended chiefly to address land that is contaminated by virtue of radioactivity. These have been replaced subsequently by the Contaminated Land (England) (Amendment) Regulations 2012, which now exclude land that is contaminated by virtue of radioactivity.

The intention of Part IIA of the EPA is to deal with contaminated land issues that are considered to cause significant harm on land that is not undergoing development (see Environmental Protection Act 1990: Part 2A Contaminated Land Statutory Guidance, April 2012). This document replaces Annex III of Defra Circular 01/2006, published in September 2006 (the remainder of this document is now obsolete).

Planning Policy

Contaminated land is often dealt with through planning because of land redevelopment. This approach was documented in Planning Policy Statement: Planning and Pollution Control PPS23, which states that it remains the responsibility of the landowner and developer to identify land affected by contamination and carry out sufficient remediation to render the land suitable for use. PPS23 was withdrawn early in 2012 and has been replaced by much reduced guidance within the National Planning Policy Framework (NPPF), reference ISBN: 978-1-5286-1033-9, February 2019.

The new framework has only limited guidance on contaminated land, as follows:

Chapter 11. Making effective use of land

117 Planning policies and decisions should promote an effective use of land in meeting the need for homes and other uses, while safeguarding and improving the environment and ensuring safe and healthy living conditions. Strategic policies should set out a clear

strategy for accommodating objectively assessed needs, in a way that makes as much use as possible of previously-developed or 'brownfield' land.

118. Planning policies and decisions should:

c) give substantial weight to the value of using suitable brownfield land within settlements for homes and other identified needs, and support appropriate opportunities to remediate despoiled, degraded, derelict, contaminated or unstable land.

Chapter 15. Conserving and enhancing the natural environment

170. Planning policies and decisions should contribute to and enhance the natural and local environment by:

e) preventing new and existing development from contributing to, being put at unacceptable risk from, or being adversely affected by, unacceptable levels of soil, air, water or noise pollution or land instability. Development should, wherever possible, help to improve local environmental conditions such as air and water quality, taking into account relevant information such as river basin management plans; and

f) remediating and mitigating despoiled, degraded, derelict, contaminated and unstable land, where appropriate.

Ground conditions and pollution

178. Planning policies and decisions should ensure that:

a) a site is suitable for its proposed use taking account of ground conditions and any risks arising from land instability and contamination. This includes risks arising from natural hazards or former activities such as mining, and any proposals for mitigation including land remediation (as well as potential impacts on the natural environment arising from that remediation);

b) after remediation, as a minimum, land should not be capable of being determined as contaminated land under Part 2A of the Environmental Protection Act 1990; and

c) adequate site investigation information, prepared by a competent person, is available to inform these assessments.

179. Where a site is affected by contamination or land stability issues, responsibility for securing a safe development rests with the developer and/or landowner.

Water Framework Directive (WFD)

The Water Framework Directive 2000/60/EC is designed to:

- enhance the status and prevent further deterioration of aquatic ecosystems and associated wetlands that depend on the aquatic ecosystems

- promote the sustainable use of water
- reduce pollution of water, especially by ‘priority’ and ‘priority hazardous’ substances
- ensure progressive reduction of groundwater pollution.

The WFD requires a management plan for each river basin be developed every six years.

Groundwater Directive (GWD)

The 1980 Groundwater Directive 80/68/EEC and the 2006 Groundwater Daughter Directive 2006/118/EC of the WFD are the main European legislation in place to protect groundwater. The 1980 Directive is due to be repealed in December 2013. The European legislation has been transposed into national legislation by regulations and directions to the Environment Agency.

Environmental Permitting Regulations (EPR)

The Environmental Permitting (England and Wales) Regulations 2010 provide a single regulatory framework that streamlines and integrates waste management licensing, pollution prevention and control, water discharge consenting, groundwater authorisations, and radioactive substances regulation. Schedule 22, paragraph 6 of EPR 2010 states: ‘the regulator must, in exercising its relevant functions, take all necessary measures - (a) to prevent the input of any hazardous substance to groundwater; and (b) to limit the input of non-hazardous pollutants to groundwater so as to ensure that such inputs do not cause pollution of groundwater.’

Priority Substances Directive (PSD)

The Priority Substances Directive 2008/105/EC is a ‘Daughter’ Directive of the WFD, which sets out a priority list of substances posing a threat to or via the aquatic environment. The PSD establishes environmental quality standards for priority substances, which have been set at concentrations that are safe for the aquatic environment and for human health. In addition, there is a further aim of reducing (or eliminating) pollution of surface water (rivers, lakes, estuaries and coastal waters) by pollutants on the list. The WFD requires that countries establish a list of dangerous substances that are being discharged and EQS for them. In England and Wales, this list is provided in the River Basin Districts Typology, Standards and Groundwater threshold values (Water Framework Directive) (England and Wales) Directions 2010. In order to achieve the objectives of the WFD, classification schemes are used to describe where the water environment is of good quality and where it may require improvement.

APPENDIX B
SITE PHOTOGRAPHS AND WALKOVER CHECKLIST

PHOTOGRAPHIC LOG

Photo no.	**Date:**
1	09/10/20

Direction photo taken:

View north

Description:

General site view



Photo No.	**Date:**
2	09/10/20

Direction photo taken:

View South

Description:

View across site level surface following recent clearance works



Photo No.	Date:	
3	09/10/20	
Direction photo taken: Looking West		
Description: View along southern boundary		

Photo No.	Date:	
4	09/10/20	
Direction photo taken: Looking East		
Description: View along northern boundary.		

WALKOVER SURVEY CHECKLIST: GEOSCIENCES

SITE NAME	NGR
Milton Street, Middleton	386810, 406190

These inspections can provide useful information on:

- Potential geotechnical hazards
- Suitable and appropriate locations for investigation
- The groundwater and surface water environments
- Potentially sensitive receptors (targets) including issues that require further investigation, e.g. ecology surveys
- Potential sources of contaminants
- Nature of contamination
- Potential migration routes (pathways)

Mark locations of features described on a map and give them a reference number.

Describe features in as much detail as possible. Continue on the back of the checklist if necessary, using the feature letter for reference. Take photos of site and relevant features in immediate surrounding area.

The walkover survey can also provide information for the environmental consultant in planning the site investigation.

Points that should be addressed in a walkover survey are as follows:

Features	Description	Photo no.	Map ref.
a) Describe materials exposed in nearby road or railway cuttings, in pits and quarries and natural exposures of soils and rocks near to the site. *This will give an indication of the geology beneath the site*	Sandy soil noted on the site		
b) Describe surrounding properties/land use and name occupiers. Type of boundary demarcation (if any) on each side. *This will identify any potential sources of contamination from adjacent sites and any sensitive receptors*	Site is located in a residential area		
c) Describe present land use. Are there areas of hardstanding (if yes describe location, types and condition)? *Especially crops, for consideration of appropriate timing for further investigation, compensation and reinstatement. Also note hardstanding, obstructions etc. Note any old buildings/ivy covered trees as these may be used by owls or bats*	Site has been recently cleared	1 to 4	

WALKOVER SURVEY CHECKLIST Continued

Features	Description	Photo no.	Map ref.
d) Describe the site in terms of ground slopes and changes in slope. Is there any evidence of subsidence or landslip/slope erosion? *Old scarps or hummocky ground may be evidence of previous landslips that could be reactivated. A terraced appearance may be indicative of superficial solifluction movement or cambering. Trees that are leaning may indicate instability or general slope movement.*	Site is relatively level.	1 to 4	
e) Describe the types and condition of surface vegetation. *Nettles may indicate an old cesspit for example or unhealthy vegetation may indicate the presence of phytotoxic fill or landfill gas. Note invasive weeds, e.g. Japanese knotweed.*	No vegetation. No evidence of Japanese knotweed		
f) Note the number, location, height and species of trees and hedges. *This is important in terms of shrinking and swelling ground. Trees and hedgerows may be protected; their condition should be noted along with any restrictions they will impose for site access.* *It is important to note any areas with the potential for nesting birds, roosting bats, water voles and badger setts.*	Some trees and shrubs on site boundaries	1 to 4	
g) Describe any evidence of animal activity. *For example obvious animal paths or areas of excavations and burrows.*	None noted		
h) Describe any damage to existing structures on site or adjacent to the site *For example, cracks in buildings both on the site and in the neighbourhood, and other evidence of settlement or differential settlement.* *Note presence of any suspected asbestos-containing materials (ACM)*	None noted		
i) Note the remains of structures that have been demolished. Look for evidence of remnants of any historical structures. *This will provide valuable information on the location of previous foundations, processes etc.* *Note presence of any suspected asbestos-containing materials (ACM)*	None noted		

WALKOVER SURVEY CHECKLIST Continued

Features	Description	Photo no.	Map ref.
j) Note any abrupt changes in ground level. Is there evidence of Made Ground/fill on site *May indicate that minerals have been worked in surface excavations. May indicate cut and fill.*	None noted – some brick and concrete from site clearance works		
k) Note any surface hollows. *Which may indicate the presence of solution features or swallow holes in rocks such as chalk limestone, gypsum and salt, or collapsed underground workings in these materials. May also indicate badger setts or other wildlife activity.*	None noted		
l) In areas of country underlain by coal or other minerals note any hummocky ground. *Which may be the remnants of spoil tips and surface depressions that may indicate collapsed shallow workings. Areas of general unevenness may be evidence of waste disposal activities.*	None noted		
m) Note any evidence of gas from nearby landfill sites *Can be indicated for example by poor vegetation or gas bubbles in water-filled trenches.*	None noted		
n) Are there any evidence of gas protection measures (gas membrane, gravel filled trenches, venting pipes, cowls etc)	None noted		
o) Note the location of streams, culverts, ponds, seepages and sinks and signs of previous flooding. Note direction of flow. Note where the stream is accessible for sampling. May need to take dimensions of stream. *If ponds are present on site they may contain great crested newts. Ditches, streams and rivers that border or run through a site may contain water voles, otters or white-clawed crayfish. Presence of water features on site may prompt the need for a survey during a site investigation.*	No watercourses near to the site		
p) All surface waters should be examined for evidence of contamination. *For example, oil sheen, silt, solid matter, discoloured sediment.*	None noted		

Features	Description	Photo no.	Map ref.
q) Note site drainage. Are there any drain covers/soakaways (if yes describe locations). Are there any outfalls to surface watercourses? Are there any interceptors/lagoons/effluent treatment plants?	Site drainage manhole noted at front of site		
r) Describe storage of fuels and chemicals. Are there any drums/containers (if yes, describe quantity, full/empty, stored on hardstanding/softstanding, bunded)? *Is there evidence of underground fuel tanks (if yes, describe locations, how many, volumes, bunding, used/disused, condition)?*	None noted		
s) Note any discoloured ground. *This may provide evidence of contamination.*	None noted		
t) Accidents: In the event of a large spillage would runoff affect any vulnerable watercourses/culverts? *Are emergency procedures/equipment in place?*	None noted		
u) Waste: Are there any waste skips on site? Are waste storage facilities adequate? Is there any litter/fly-tipped material?	No waste materials stored on site.		
v) Are there any electricity substations on or adjacent to site?	None noted		
w) Identify any old structures, pipework etc. wherever possible and, if safe, inspect for evidence of stored waste. *Old tanks may contain oil. Old electricity transformers should be noted. Asbestos risk should be assessed together with the need for a specialist hazardous materials survey.*	None noted		
x) Examine surrounding areas for evidence of contamination which could migrate onto the site. *For example a leaking oil tank on an adjacent site.*	None noted		
y) Note the presence of any underground structures, services, mine workings, tunnels etc *From a safety point of view for development of the site and also as they may provide contaminant migration routes.*	None noted		
z) Note any anecdotal information in past uses of the site. *Local street names etc. can provide indicators of past industry or ground problems*	None		

WALKOVER SURVEY CHECKLIST Continued

Features	Description	Photo no.	Map ref
aa) Description of buildings on site. Is there any evidence of asbestos construction materials, e.g. roofing, insulation materials. Do any of the buildings have basements? Do any of the buildings have a boiler room? (if yes describe fuel type and storage arrangements)	No buildings on site		
bb) Identify potential access routes to the site for plant for the site investigation *Excavators and drilling rigs may be required for the next stage of the investigation, or if the access is limited window sampling techniques may need to be specified. Note any specific obstructions such as unsafe/unstable ground, protected trees or hedgerows, or protected buildings.*	Access not required for SI work		
cc) Evidence of buried services (water, gas, electricity, telephone, cable, television, pipelines) *Both for safety considerations and in the case of water as supply for further investigation. As well as danger, there is the question of considerable expense, which can arise from an inadequate knowledge of the location of buried services. The locations and heights of overhead cables may be important when considering the movement of site equipment.*	No services noted		

Walkover survey completed

Name: John Harrison

Date: 09.10.20

Notes:

APPENDIX C
ENVIRONMENT DATABASE REPORT

Envirocheck® Report:

Datasheet

Order Details:

Order Number:
262182483_1_1

Customer Reference:
2020/001

National Grid Reference:
386810, 406190

Slice:
A

Site Area (Ha):
0.08

Search Buffer (m):
1000

Site Details:

Former Citizens Advice Bureau, Milton Street
Middleton
M24 5TU

Client Details:

Mr J Harrison
John Harrison
50 Godwins Way
Stamford Bridge
York
YO411DB

Envirocheck®
LANDMARK INFORMATION GROUP

Contents

Report Section	Page Number
Summary	-
Agency & Hydrological	1
Waste	30
Hazardous Substances	34
Geological	35
Industrial Land Use	37
Sensitive Land Use	58
Data Currency	59
Data Suppliers	64
Useful Contacts	65

Introduction

The Environment Act 1995 has made site sensitivity a key issue, as the legislation pays as much attention to the pathways by which contamination could spread, and to the vulnerable targets of contamination, as it does the potential sources of contamination.
For this reason, Landmark's Site Sensitivity maps and Datasheet(s) place great emphasis on statutory data provided by the Environment Agency/Natural Resources Wales and the Scottish Environment Protection Agency; it also incorporates data from Natural England (and the Scottish and Welsh equivalents) and Local Authorities; and highlights hydrogeological features required by environmental and geotechnical consultants. It does not include any information concerning past uses of land. The datasheet is produced by querying the Landmark database to a distance defined by the client from a site boundary provided by the client.
In this datasheet the National Grid References (NGRs) are rounded to the nearest 10m in accordance with Landmark's agreements with a number of Data Suppliers.

Copyright Notice

© Landmark Information Group Limited 2020. The Copyright on the information and data and its format as contained in this Envirocheck® Report ("Report") is the property of Landmark Information Group Limited ("Landmark") and several other Data Providers, including (but not limited to) Ordnance Survey, British Geological Survey, the Environment Agency/Natural Resources Wales and Natural England, and must not be reproduced in whole or in part by photocopying or any other method. The Report is supplied under Landmark's Terms and Conditions accepted by the Customer.
A copy of Landmark's Terms and Conditions can be found with the Index Map for this report. Additional copies of the Report may be obtained from Landmark, subject to Landmark's charges in force from time to time. The Copyright, design rights and any other intellectual rights shall remain the exclusive property of Landmark and /or other Data providers, whose Copyright material has been included in this Report.
© Environment Agency & United Kingdom Research and Innovation 2020. © Natural Resources Wales & United Kingdom Research and Innovation 2020.

Natural England Copyright Notice

Site of Special Scientific Interest, National Nature Reserve, Ramsar, Special Protection Area, Special Conservation Area, Marine Nature Reserve data (derived from Ordnance Survey 1:10000 raster) is provided by, and used with the permission of, Natural England who retain the copyright and Intellectual Property Rights for the data.

Scottish Natural Heritage Copyright

Contains SNH information licensed under the Open Government Licence v3.0.

Ove Arup Copyright Notice

The Mining Instability data was obtained on licence from Ove Arup & Partners Limited (for further information, contact mining.review@arup.com). No reproduction or further use of such Data is to be made without the prior written consent of Ove Arup & Partners Limited. The supplied Mining Instability data is derived from publicly available records and other third party sources and neither Ove Arup & Partners nor Landmark warrant the accuracy or completeness of such information or data.

Stantec Copyright Notice

The cavity data presented has been extracted from the PBA (now Stantec UK Ltd) enhanced version of the original DEFRA national cavity databases. Stantec UK Ltd retain the copyright & intellectual property rights in the data. Whilst all reasonable efforts are made to check that the information contained in the cavity databases is accurate we do not warrant that the data is complete or error free. The information is based upon our own researches and those collated from a number of external sources and is continually being augmented and updated by Stantec UK Ltd. In no event shall Stantec UK Ltd or Landmark be liable for any loss or damage including, without limitation, indirect or consequential loss or damage arising from the use of this data.

Radon Potential dataset Copyright Notice

Information supplied from a joint dataset compiled by The British Geological Survey and Public Health England.

Natural Resources Wales Copyright Notice

Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Contains Ordnance Survey Data. Ordnance Survey Licence number 100019741. Crown Copyright and Database Right. Contains Natural Resources Wales information © Natural Resources Wales and Database Right. All rights Reserved. Some features of this information are based on digital spatial data licensed from the Centre for Ecology & Hydrology © NERC (CEH). Defra, Met Office and DARD Rivers Agency © Crown copyright. © Cranfield University. © James Hutton Institute. Contains OS data © Crown copyright and database right 2020. Land & Property Services © Crown copyright and database right.

Report Version v53.0

Envirocheck®
LANDMARK INFORMATION GROUP®

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Agency & Hydrological					
BGS Groundwater Flooding Susceptibility	pg 1	Yes	Yes	Yes	n/a
Contaminated Land Register Entries and Notices					
Discharge Consents	pg 3		5	5	28
Prosecutions Relating to Controlled Waters			n/a	n/a	n/a
Enforcement and Prohibition Notices					
Integrated Pollution Controls					
Integrated Pollution Prevention And Control	pg 13			1	2
Local Authority Integrated Pollution Prevention And Control					
Local Authority Pollution Prevention and Controls	pg 13			1	7
Local Authority Pollution Prevention and Control Enforcements					
Nearest Surface Water Feature	pg 14		Yes		
Pollution Incidents to Controlled Waters	pg 14			7	27
Prosecutions Relating to Authorised Processes					
Registered Radioactive Substances					
River Quality	pg 20			1	3
River Quality Biology Sampling Points					
River Quality Chemistry Sampling Points					
Substantiated Pollution Incident Register	pg 21				1
Water Abstractions	pg 21			1	5 (*9)
Water Industry Act Referrals					
Groundwater Vulnerability Map	pg 24	Yes	n/a	n/a	n/a
Groundwater Vulnerability - Soluble Rock Risk			n/a	n/a	n/a
Bedrock Aquifer Designations	pg 24	Yes	n/a	n/a	n/a
Superficial Aquifer Designations	pg 24	Yes	n/a	n/a	n/a
Source Protection Zones					
Extreme Flooding from Rivers or Sea without Defences				n/a	n/a
Flooding from Rivers or Sea without Defences				n/a	n/a
Areas Benefiting from Flood Defences				n/a	n/a
Flood Water Storage Areas				n/a	n/a
Flood Defences				n/a	n/a
OS Water Network Lines	pg 25			6	33

Envirocheck®
LANDMARK INFORMATION GROUP

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Waste					
BGS Recorded Landfill Sites	pg 30				1
Historical Landfill Sites	pg 30		3		1
Integrated Pollution Control Registered Waste Sites					
Licensed Waste Management Facilities (Landfill Boundaries)					
Licensed Waste Management Facilities (Locations)	pg 31				6
Local Authority Landfill Coverage	pg 32	1	n/a	n/a	n/a
Local Authority Recorded Landfill Sites					
Registered Landfill Sites					
Registered Waste Transfer Sites	pg 32			1	
Registered Waste Treatment or Disposal Sites	pg 33			1	
Hazardous Substances					
Control of Major Accident Hazards Sites (COMAH)	pg 34				1
Explosive Sites					
Notification of Installations Handling Hazardous Substances (NIHHS)					
Planning Hazardous Substance Consents	pg 34				3
Planning Hazardous Substance Enforcements					
Geological					
BGS 1:625,000 Solid Geology	pg 35	Yes	n/a	n/a	n/a
BGS Recorded Mineral Sites	pg 35				3
CBSCB Compensation District			n/a	n/a	n/a
Coal Mining Affected Areas	pg 35	Yes	n/a	n/a	n/a
Mining Instability	pg 35	Yes	n/a	n/a	n/a
Man-Made Mining Cavities					
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential for Collapsible Ground Stability Hazards	pg 35	Yes		n/a	n/a
Potential for Compressible Ground Stability Hazards				n/a	n/a
Potential for Ground Dissolution Stability Hazards				n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 35	Yes		n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 35	Yes		n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards				n/a	n/a
Radon Potential - Radon Affected Areas			n/a	n/a	n/a
Radon Potential - Radon Protection Measures			n/a	n/a	n/a

Envirocheck®
LANDMARK INFORMATION GROUP

Summary

Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Industrial Land Use					
Contemporary Trade Directory Entries	pg 37		9	62	155
Fuel Station Entries	pg 57				5
Gas Pipelines					
Underground Electrical Cables					
Sensitive Land Use					
Ancient Woodland					
Areas of Adopted Green Belt					
Areas of Unadopted Green Belt					
Areas of Outstanding Natural Beauty					
Environmentally Sensitive Areas					
Forest Parks					
Local Nature Reserves	pg 58				1
Marine Nature Reserves					
National Nature Reserves					
National Parks					
Nitrate Sensitive Areas					
Nitrate Vulnerable Zones	pg 58	1			
Ramsar Sites					
Sites of Special Scientific Interest					
Special Areas of Conservation					
Special Protection Areas					
World Heritage Sites					

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A13SE (SE)	0	1	386812 406192
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	162	1	386700 406050
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SE (E)	176	1	387000 406192
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (S)	177	1	386800 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A13SE (S)	179	1	386850 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (S)	184	1	386750 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	204	1	386700 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (E)	226	1	387050 406200
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SE (E)	226	1	387050 406192
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SE (E)	228	1	387050 406150
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	232	1	386650 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (S)	233	1	386750 405950
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	237	1	386600 406050
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (NE)	244	1	387050 406300
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NW (N)	247	1	386750 406450
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (NE)	261	1	387000 406400
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NE (E)	276	1	387100 406200
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SE (E)	276	1	387100 406192
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (E)	280	1	387100 406250
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SE (E)	287	1	387100 406100
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (NE)	297	1	387050 406400
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	307	1	386550 406000

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (W)	310	1	386500 406100
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NE (NE)	311	1	387100 406350
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	326	1	386500 406050
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13NE (NE)	332	1	387050 406450
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A14SW (E)	335	1	387150 406100
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	338	1	386550 405950
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13NE (NE)	341	1	387000 406500
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A18SW (N)	342	1	386800 406550
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SW (SW)	349	1	386500 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A18SW (N)	357	1	386700 406550
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A18SE (N)	365	1	386950 406550
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A13SW (SW)	376	1	386500 405950
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A8NW (S)	377	1	386800 405800
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A18SE (N)	392	1	386812 406600
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A12SE (SW)	392	1	386450 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A18SW (NW)	397	1	386600 406550
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A13SW (SW)	409	1	386500 405900
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14NW (E)	426	1	387250 406200
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A14SW (E)	426	1	387250 406192
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A14SW (E)	427	1	387250 406150
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A12NE (NW)	456	1	386450 406500
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A12SE (SW)	460	1	386400 405950

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A12SE (W)	468	1	386350 406050
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding to Occur at Surface	A14NW (E)	476	1	387300 406200
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A14SW (E)	476	1	387300 406192
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A12SE (SW)	484	1	386350 406000
	BGS Groundwater Flooding Susceptibility Flooding Type: Potential for Groundwater Flooding of Property Situated Below Ground Level	A14NW (E)	485	1	387300 406300
	BGS Groundwater Flooding Susceptibility Flooding Type: Limited Potential for Groundwater Flooding to Occur	A17SE (NW)	490	1	386450 406550
1	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Wood Street Cso 148 Wood Street, Middleton, Manchester, Greater Manchester, M24 4bb Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982644 Permit Version: 4 Effective Date: 5th March 2020 Issued Date: 5th March 2020 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A13NW (W)	215	2	386587 406232
1	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Wood Street Cso 148 Wood Street, Middleton, Manchester, Greater Manchester, M24 4bb Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01ROC0168 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 1st January 1995 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Trib River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 100m	A13NW (W)	222	2	386580 406235
1	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Wood Street Cso 148 Wood Street, Middleton, Manchester, Greater Manchester, M24 4bb Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982644 Permit Version: 3 Effective Date: 20th May 2005 Issued Date: 20th May 2005 Revocation Date: 5th March 2020 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995)** Positional Accuracy: Located by supplier to within 10m	A13NW (W)	223	2	386580 406240

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
1	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Wood Street Cso 148 Wood Street, Middleton, Manchester, Greater Manchester, M24 4bb Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982644 Permit Version: 2 Effective Date: 9th March 2005 Issued Date: 9th March 2005 Revocation Date: 19th May 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 10m	A13NW (W)	223	2	386580 406240
1	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Wood Street Cso 148 Wood Street, Middleton, Manchester, Greater Manchester, M24 4bb Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016982644 Permit Version: 1 Effective Date: 28th November 1994 Issued Date: Not Supplied Revocation Date: 8th March 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 100m	A13NW (W)	223	2	386580 406240
2	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Long Street Combined Sewer Overflow Long Street, Cso Is Located On The Roundabout, Middleton / Manchester, Greater Manchester, M24 6un Authority: Environment Agency, North West Region Catchment Area: Irk Reference: 016993581 Permit Version: 1 Effective Date: 20th May 2005 Issued Date: 20th May 2005 Revocation Date: 10th December 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: The River Irk **Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995)** Positional Accuracy: Located by supplier to within 10m	A13SE (SE)	273	2	387040 406010
2	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Long Street Combined Sewer Overflow Long Street, Cso Is Located On The Roundabout, Middleton / Manchester, Greater Manchester, M24 6un Authority: Environment Agency, North West Region Catchment Area: Irk Reference: 01roc0124 Permit Version: 3 Effective Date: 17th March 2005 Issued Date: 17th March 2005 Revocation Date: 19th May 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 10m	A13SE (SE)	273	2	387040 406010

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
3	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Long Street Combined Sewer Overflow Long Street, Cso Is Located On The Roundabout, Middleton / Manchester, Greater Manchester, M24 6un Authority: Environment Agency, North West Region Catchment Area: Irk Reference: 016993581 Permit Version: 2 Effective Date: 11th December 2019 Issued Date: 11th December 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Clvrt'D Section The River Irk **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A8NE (SE)	462	2	387140 405841
3	**Discharge Consents** Operator: United Utilities Water Limited Property Type: WWTW/SEWAGE TREATMENT WORKS (WATER COMPANY) Location: The Market Place Mn26, Rochdale, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01ROC0124 Permit Version: 2 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 16th March 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Unknown Receiving Water: Unknown **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 100m	A8NE (SE)	470	2	387140 405830
3	**Discharge Consents** Operator: United Utilities Water Limited Property Type: WWTW/SEWAGE TREATMENT WORKS (WATER COMPANY) Location: The Market Place Mn26, Rochdale, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01roc0124 Permit Version: 1 Effective Date: 1st April 1991 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Not Supplied Receiving Water: Not Supplied **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A8NE (SE)	470	2	387140 405830
4	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: John Lee Fold Cso 2 John Lee Fold, Middleton, Manchester, Greater Manchester, M24 2lr Authority: Environment Agency, North West Region Catchment Area: Irk Reference: 016982900 Permit Version: 5 Effective Date: 20th May 2005 Issued Date: 20th May 2005 Revocation Date: 29th October 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook **Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995)** Positional Accuracy: Located by supplier to within 10m	A14NW (E)	546	2	387370 406200

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
4	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: John Lee Fold Cso 2 John Lee Fold, Middleton, Manchester, Greater Manchester, M24 2lr Authority: Environment Agency, North West Region Catchment Area: Irk Reference: 016982900 Permit Version: 4 Effective Date: 9th March 2005 Issued Date: 9th March 2005 Revocation Date: 19th May 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 10m	A14NW (E)	546	2	387370 406200
4	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: John Lee Fold Cso 2 John Lee Fold, Middleton, Manchester, Greater Manchester, M24 2lr Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016982900 Permit Version: 3 Effective Date: 11th May 1995 Issued Date: Not Supplied Revocation Date: 8th March 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook Trib River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 100m	A14NW (E)	546	2	387370 406200
4	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: John Lee Fold Cso 2 John Lee Fold, Middleton, Manchester, Greater Manchester, M24 2lr Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982900 Permit Version: 1 Effective Date: 1st April 1991 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook Trib River Irk **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A14NW (E)	546	2	387370 406200
4	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: John Lee Fold Cso 2 John Lee Fold, Middleton, Manchester, Greater Manchester, M24 2lr Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982900 Permit Version: 2 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 10th May 1995 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook Trib River Irk **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A14NW (E)	546	2	387370 406200

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
4	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: John Lee Fold Cso 2 John Lee Fold, Middleton, Manchester, Greater Manchester, M24 2lr Authority: Environment Agency, North West Region Catchment Area: Irk Reference: 016982900 Permit Version: 6 Effective Date: 30th October 2019 Issued Date: 30th October 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A14NW (E)	547	2	387371 406195
5	**Discharge Consents** Operator: H Pickup & Sons Property Type: WWTW (NOT WATER CO) (NOT STP AT A PRIVATE PREMISES) Location: H Pickup And Sons Swo, 6 Boarshaw Road, Middleton, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016991160 Permit Version: 1 Effective Date: 1st November 1994 Issued Date: Not Supplied Revocation Date: 1st November 1994 Discharge Type: Discharge Of Other Matter-Surface Water Discharge Environment: Freshwater Stream/River Receiving Water: Whitbrook **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 100m	A14NW (E)	584	2	387400 406300
5	**Discharge Consents** Operator: Middleton Transport Ltd Property Type: LAND TRANSPORT + VIA PIPELINES/FREIGHT Location: Middleton Transport Ltd Swo, John Lee Road, Middleton, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016991252 Permit Version: 1 Effective Date: 1st November 1994 Issued Date: Not Supplied Revocation Date: 1st November 1994 Discharge Type: Discharge Of Other Matter-Surface Water Discharge Environment: Freshwater Stream/River Receiving Water: Trub (Whit) Brook **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 100m	A14NW (E)	584	2	387400 406300
6	**Discharge Consents** Operator: Robert Mcbride Group Property Type: MAKING OF CHEMICALS + CHEMICAL PRODUCTS Location: Robert Mcbride Ltd Swo, Middleton Way, Middleton, Greater Manchester, M24 4dp Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016991122 Permit Version: 1 Effective Date: 1st October 1994 Issued Date: Not Supplied Revocation Date: 30th November 1994 Discharge Type: Discharge Of Other Matter-Surface Water Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 100m	A8NW (S)	618	2	386780 405560

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
7	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Boardshaw Road Cso 125 Boarshaw Road, Middleton, Manchester, Greater Manchester, M24 6ar Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016950217 Permit Version: 2 Effective Date: 11th December 2019 Issued Date: 11th December 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook, Trib Of River Irk **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A14NW (E)	657	2	387449 406410
8	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Spring Vale Combined Sewer Overflow Opposite 54 Spring Vale, Middleton, Manchester, Greater Manchester, M24 2hs Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982642 Permit Version: 4 Effective Date: 9th January 2020 Issued Date: 9th January 2020 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A14SE (E)	691	2	387502 406044
8	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Hanson St Bridge Sso, 50m U/S Hanson Street Bridge, Middleton, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016950433 Permit Version: 1 Effective Date: 6th September 1983 Issued Date: Not Supplied Revocation Date: 27th February 2013 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Surrendered under EPR 2010** Positional Accuracy: Located by supplier to within 100m	A14SE (E)	698	2	387510 406050
8	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Spring Vale Combined Sewer Overflow Opposite 54 Spring Vale, Middleton, Manchester, Greater Manchester, M24 2hs Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982642 Permit Version: 3 Effective Date: 20th May 2005 Issued Date: 20th May 2005 Revocation Date: 8th January 2020 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995)** Positional Accuracy: Located by supplier to within 10m	A14SE (E)	722	2	387530 406030

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
8	**Discharge Consents** Operator: United Utilities Water Plc (?) Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Spring Vale Combined Sewer Overflow Opposite 54 Spring Vale, Middleton, Manchester, Greater Manchester, M24 2hs Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016982642 Permit Version: 2 Effective Date: 9th March 2005 Issued Date: 9th March 2005 Revocation Date: 19th May 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 10m	A14SE (E)	722	2	387530 406030
8	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Spring Vale Combined Sewer Overflow Opposite 54 Spring Vale, Middleton, Manchester, Greater Manchester, M24 2hs Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016982642 Permit Version: 1 Effective Date: 30th September 1994 Issued Date: Not Supplied Revocation Date: 8th March 2005 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 100m	A14SE (E)	722	2	387530 406030
8	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Spring Vale Combined Sewer Overflow Opposite 54 Spring Vale, Middleton, Manchester, Greater Manchester, M24 2hs Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01ROC0166 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 1st January 1995 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 100m	A14SE (E)	723	2	387530 406025
9	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Kirkway Combined Sewer Overflow Rear Of Army Cadet Hq, Ashton Lane, Wince Brook, Middleton, M24 1bn Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016950343 Permit Version: 2 Effective Date: 15th May 2002 Issued Date: 15th May 2002 Revocation Date: 10th December 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Wince Brook **Status: Modified (Water Resources Act 1991, Schedule 10 as amended by Environment Act 1995)** Positional Accuracy: Located by supplier to within 10m	A9NW (SE)	720	2	387240 405590

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
9	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Kirkway Combined Sewer Overflow Rear Of Army Cadet Hq, Ashton Lane, Wince Brook, Middleton, M24 1bn Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016950343 Permit Version: 1 Effective Date: 2nd March 1982 Issued Date: Not Supplied Revocation Date: 14th May 2002 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Wince Brook **Status: Pre National Rivers Authority Legislation where issue date < 01/09/1989** Positional Accuracy: Located by supplier to within 10m	A9NW (SE)	720	2	387240 405590
9	**Discharge Consents** Operator: United Utilities Water Plc Property Type: Sewerage Network - Sewers - Water Company Location: Sso Downstream Of Kirkway, Middleton, Greater Manchester Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 0169500343 Permit Version: 2 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Wince Brook **Status: Consent revoked or revised: New Consent issued (Section 37(1))** Positional Accuracy: Located by supplier to within 10m	A9NW (SE)	720	2	387240 405590
9	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Kirkway Combined Sewer Overflow Rear Of Army Cadet Hq, Ashton Lane, Wince Brook, Middleton, M24 1bn Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 0169500343 Permit Version: 1 Effective Date: 1st April 1991 Issued Date: Not Supplied Revocation Date: 31st December 1994 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Not Supplied Receiving Water: Not Supplied **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 10m	A9NW (SE)	720	2	387240 405590
9	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Kirkway Combined Sewer Overflow Rear Of Army Cadet Hq, Ashton Lane, Wince Brook, Middleton, M24 1bn Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 016950343 Permit Version: 3 Effective Date: 11th December 2019 Issued Date: 11th December 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Wince Brook, Trib Of River Irk **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A9NW (SE)	726	2	387247 405588

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
10	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Boardshaw Road Cso 125 Boarshaw Road, Middleton, Manchester, Greater Manchester, M24 6ar Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016950217 Permit Version: 1 Effective Date: 31st July 1981 Issued Date: Not Supplied Revocation Date: 10th December 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook **Status: Pre National Rivers Authority Legislation where issue date < 01/09/1989** Positional Accuracy: Located by supplier to within 100m	A14NE (E)	744	2	387520 406470
10	**Discharge Consents** Operator: North West Water Limited Property Type: Not Given Location: Off Boardshaw Road, Mn33, ROCHDALE Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: ROC0141 Permit Version: Not Supplied Effective Date: Not Supplied Issued Date: Not Supplied Revocation Date: Not Supplied Discharge Type: Sewage Effluent Discharge-Storm Effluent Discharge Environment: Unknown Receiving Water: Not Supplied **Status: Not Supplied** Positional Accuracy: Located by supplier to within 100m	A14NE (E)	757	2	387530 406480
11	**Discharge Consents** Operator: Robert Mcbride Group Property Type: MAKING OF CHEMICALS + CHEMICAL PRODUCTS Location: Robert Mcbride Ltd Swo, Middleton Way, Middleton, Greater Manchester, M24 4dp Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 016991141 Permit Version: 1 Effective Date: 1st October 1994 Issued Date: Not Supplied Revocation Date: 1st October 1994 Discharge Type: Discharge Of Other Matter-Surface Water Discharge Environment: Freshwater Stream/River Receiving Water: River Irk **Status: Authorisation revoked** Positional Accuracy: Located by supplier to within 100m	A8SW (S)	833	2	386500 405400
12	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Boarshaw Road Cso 203 Boarshaw Road, Middleton, Manchester, Greater Manchester, M24 2wq Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01roc0013 Permit Version: 2 Effective Date: 14th April 2009 Issued Date: 14th April 2009 Revocation Date: 4th February 2016 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook River Irk **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A19SE (NE)	890	2	387590 406660

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
12	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Boarshaw Road Cso 203 Boarshaw Road, Middleton, Manchester, Greater Manchester, M24 2wq Authority: Environment Agency, North West Region Catchment Area: Not Given Reference: 01ROC0013 Permit Version: 1 Effective Date: 1st January 1995 Issued Date: Not Supplied Revocation Date: 13th April 2009 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook River Irk **Status: Post National Rivers Authority Legislation where issue date > 31/08/1989** Positional Accuracy: Located by supplier to within 100m	A19SE (NE)	890	2	387590 406660
12	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Boarshaw Road Cso 203 Boarshaw Road, Middleton, Manchester, Greater Manchester, M24 2wq Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01roc0013 Permit Version: 4 Effective Date: 14th October 2019 Issued Date: 14th October 2019 Revocation Date: Not Supplied Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A19SE (NE)	897	2	387595 406666
12	**Discharge Consents** Operator: United Utilities Water Limited Property Type: STORM TANK/CSO ON SEWERAGE NETWORK (WATER COMPANY) Location: Boarshaw Road Cso 203 Boarshaw Road, Middleton, Manchester, Greater Manchester, M24 2wq Authority: Environment Agency, North West Region Catchment Area: Not Supplied Reference: 01roc0013 Permit Version: 3 Effective Date: 5th February 2016 Issued Date: 5th February 2016 Revocation Date: 13th October 2019 Discharge Type: Public Sewage: Storm Sewage Overflow Discharge Environment: Freshwater Stream/River Receiving Water: Whit Brook **Status: Varied under EPR 2010** Positional Accuracy: Located by supplier to within 10m	A19SE (NE)	897	2	387595 406666
13	**Prosecutions Relating to Controlled Waters** Location: Middleton Way, MIDDLETON, Greater Manchester, M24 Prosecution Text: EA News Release 06/08/1997, Allowing trade effluent, namely household detergent, to be discharged into the River Irk. Prosecution Act: WRA91 s85 Hearing Date: 6th July 1997 Verdict: Guilty Fine: 7500 Cost: 687.85 Positional Accuracy: Manually positioned within the geographical locality	A8NW (S)	533	2	386720 405650
14	**Prosecutions Relating to Controlled Waters** Location: River Irk, Manchester Prosecution Text: Discharging bleach into a watercourse Prosecution Act: Wra91 S85(1) Hearing Date: 1st July 2010 Verdict: Guilty Fine: 6600 Cost: 4822 Positional Accuracy: Manually positioned within the geographical locality	A8NW (S)	634	2	386787 405544

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
15	**Integrated Pollution Prevention And Control** Name: Vitafoam Ltd Location: Oldham Road, Middleton, Manchester, M24 2DB Authority: Environment Agency, North West Region Permit Reference: BS3271IT Original Permit Ref: Bs3271it Effective Date: 10th October 2006 **Status: Superseded By Variation** Application Type: Application App. Sub Type: New Positional Accuracy: Automatically positioned to the address Activity Code: 4.1 A(1) (D) Activity Description: Organic Chemicals; Toluene Di-Isocyanate Etc Use >1 T/12 Months If Release To Air Primary Activity: Y Activity Code: 4.1 B a) (ii) Activity Description: Organic Chemicals: Use of >5T of Diphenyl MDI/Other Di-Isocyanate/Partly Polymerised Di-Isocyanates/Prepolymers Containing >5T of These Monomers in any 12mth Period Release To Air of Di-Isocyanate Primary Activity: N	A8NE (S)	475	2	386926 405713
16	**Integrated Pollution Prevention And Control** Name: Robert Mcbride Ltd Location: Middleton Site, Robert Mcbride Ltd, Middleton Way,,Middleton, MANCHESTER, Lancashire, M24 4DP Authority: Environment Agency, North West Region Permit Reference: SP3436TW Original Permit Ref: Kp3933mx Effective Date: 2nd August 2010 **Status: Surrender Effective** Application Type: Surrender App. Sub Type: Whole Positional Accuracy: Automatically positioned to the address Activity Code: 4.1 A(1) (A) (XI) Activity Description: Organic Chemicals; Surface-Active Agents Primary Activity: Y	A8NW (S)	601	2	386694 405586
16	**Integrated Pollution Prevention And Control** Name: Robert Mcbride Ltd Location: Middleton Way, Middleton, MANCHESTER, M24 4DP Authority: Environment Agency, North West Region Permit Reference: KP3933MX Original Permit Ref: Kp3933mx Effective Date: 28th June 2007 **Status: Superseded By Variation** Application Type: Application App. Sub Type: New Positional Accuracy: Automatically positioned to the address Activity Code: 4.1 A(1) (A) (XI) Activity Description: Organic Chemicals; Surface-Active Agents Primary Activity: Y	A8NW (S)	601	2	386694 405586
17	**Local Authority Pollution Prevention and Controls** Name: Tyro Cleaners Ltd Location: Middleton Gardens, Middleton, Rochdale, M24 Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: 118/11 Dated: Not Supplied Process Type: Local Authority Pollution Prevention and Control Description: PG6/46 Dry cleaning **Status: Permitted** Positional Accuracy: Located by supplier to within 10m	A13SE (S)	299	3	386912 405892
18	**Local Authority Pollution Prevention and Controls** Name: Tesco Petrol Station Location: Barton Road, Middleton, Manchester, M24 1HB Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: Not Supplied Dated: Not Supplied Process Type: Local Authority Pollution Prevention and Control Description: PG1/14 Petrol filling station **Status: Permitted** Positional Accuracy: Manually positioned to the address or location	A8NE (SE)	510	3	387027 405710
19	**Local Authority Pollution Prevention and Controls** Name: Geometric Furniture Ltd Location: Townley Street, Middleton Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: P105/05 Dated: 6th August 2001 Process Type: Local Authority Air Pollution Control Description: PG6/33 Wood coating **Status: Authorised** Positional Accuracy: Located by supplier to within 10m	A14SW (E)	514	3	387304 405993

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
20	**Local Authority Pollution Prevention and Controls** Name: R Mcbride Ltd Location: Middleton Way, Middleton, MANCHESTER, Lancashire, M24 4DP Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: 83 Dated: Not Supplied Process Type: Local Authority Pollution Prevention and Control Description: Part B process (no specific reference) **Status: Transferred to IPPC** Positional Accuracy: Manually positioned to the address or location	A8NW (S)	586	3	386700 405600
21	**Local Authority Pollution Prevention and Controls** Name: Vw Audi Used Spares Ltd Location: Spring Vale, Middleton, Manchester, M24 2hq Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: 128/07 Dated: Not Supplied Process Type: Local Authority Pollution Prevention and Control Description: PG1/1Waste oil burners, less than 0.4MW net rated thermal input **Status: Permitted** Positional Accuracy: Manually positioned to the address or location	A14SW (E)	657	3	387452 405986
22	**Local Authority Pollution Prevention and Controls** Name: Alkrington Service Station Location: Manchester New Road, MIDDLETON, Lancashire, M24 1DE Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: 98/09 Dated: Not Supplied Process Type: Local Authority Air Pollution Control Description: PG1/14 Petrol filling station **Status: Authorised** Positional Accuracy: Manually positioned to the address or location	A8NE (S)	660	3	386897 405522
23	**Local Authority Pollution Prevention and Controls** Name: Middleton Service Station Location: 191 Oldham Road, MIDDLETON, Lancashire, M24 2LD Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: 102/09 Dated: Not Supplied Process Type: Local Authority Air Pollution Control Description: PG1/14 Petrol filling station **Status: Authorised** Positional Accuracy: Automatically positioned to the address	A14SW (E)	712	3	387486 405915
24	**Local Authority Pollution Prevention and Controls** Name: Middleton Service Station Location: Manchester Old Road, MIDDLETON, Lancashire, M24 4EB Authority: Rochdale Metropolitan Borough Council, Environmental Health Department Permit Reference: Not Given Dated: Not Supplied Process Type: Local Authority Air Pollution Control Description: PG1/14 Petrol filling station **Status: Authorised** Positional Accuracy: Automatically positioned to the address	A7SW (SW)	965	3	386117 405496
	Nearest Surface Water Feature	A13SW (W)	234	-	386573 406118
25	**Pollution Incidents to Controlled Waters** Property Type: Cattle (Dairy) Farming: Other Location: Foam On The Irk At, MIDDLETON Authority: Environment Agency, North West Region Pollutant: Sewage - Treated Effluent Note: Foam; Irk; Foam In Stw Final Effluent Incident Date: 18th October 1997 Incident Reference: 97611814 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Other Cause Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	377	2	386800 405800

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
26	**Pollution Incidents to Controlled Waters** Property Type: Spillage; Accident In Transit Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Chemicals - Unknown Note: River Irk; Fabric Finisher Incident Date: 3rd July 1993 Incident Reference: 93611376 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (SW)	427	2	386600 405800
27	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: None Affected; None Pollution Found Incident Date: 18th July 1996 Incident Reference: 96611590 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A14SW (SE)	467	2	387200 405900
28	**Pollution Incidents to Controlled Waters** Property Type: Private Sewage (Non-PLC): Sewerage Systems Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Foam Note: Wince Bk; Sewage Incident Date: 9th January 1995 Incident Reference: 95610032 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: High Flow Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	477	2	386800 405700
28	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Wince Brook, Manchester New Road Authority: Environment Agency, North West Region Pollutant: Sewage - Treated Effluent Note: White Foam On The Brook Incident Date: 24th January 1998 Incident Reference: SO980157 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Other Cause Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	482	2	386805 405695
28	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: No Pollution Found Incident Date: 18th August 1995 Incident Reference: 95612136 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	482	2	386800 405695
29	**Pollution Incidents to Controlled Waters** Property Type: Garage Premises Location: Wince Brook, John Lee Fold, MIDDLETON Authority: Environment Agency, North West Region Pollutant: Oils - Other Fuel Oil Note: Not Supplied Incident Date: 17th February 1998 Incident Reference: SO980306 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Poor Operational Practice Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A14NW (E)	485	2	387300 406300

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
30	**Pollution Incidents to Controlled Waters** Property Type: Private Sewage (Non-PLC): Sewerage Systems Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Storm Sewage Note: Whit Bk Incident Date: 27th October 1994 Incident Reference: 94612370 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Blocked Sewer Incident Severity: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 100m	A14NW (NE)	514	2	387300 406400
31	**Pollution Incidents to Controlled Waters** Property Type: Boats/Ships Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: None Incident Date: 2nd July 1994 Incident Reference: 94611439 Catchment Area: Irk Receiving Water: Groundwater Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A14SW (SE)	551	2	387300 405900
32	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Sewage - Treated Effluent Note: River Irk Incident Date: 11th November 1994 Incident Reference: 94612471 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	577	2	386800 405600
32	**Pollution Incidents to Controlled Waters** Property Type: No Premises Identified Location: Behind Robert Mcbride, Middleton Way, MIDDLETON, Greater Manchester Authority: Environment Agency, North West Region Pollutant: Organic Chemicals : Oils: Mixed / Unidentified / Waste Note: Not Supplied Incident Date: 14th June 1999 Incident Reference: 28504 Catchment Area: Irk Receiving Water: River Stretch (Freshwater) Cause of Incident: Other Cause Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 10m	A8NW (S)	582	2	386805 405595
33	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Unknown Sewage Note: Not Supplied Incident Date: 25th September 1995 Incident Reference: 95612403 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	585	2	386705 405600
33	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Sewage - Treated Effluent Note: River Irk Incident Date: 25th September 1992 Incident Reference: 92611739 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	586	2	386700 405600

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
33	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Foam Note: Not Supplied Incident Date: 30th November 1995 Incident Reference: 95612858 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	590	2	386705 405595
33	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Foam Note: River Irk Incident Date: 26th November 1992 Incident Reference: 92611995 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NW (S)	591	2	386700 405595
34	**Pollution Incidents to Controlled Waters** Property Type: Private Sewage (Non-PLC): Sewerage Systems Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Unknown Sewage Note: Wince Brook Incident Date: 9th April 1993 Incident Reference: 93610750 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NE (S)	604	2	387000 405600
34	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Other Note: River Irk Incident Date: 5th February 1995 Incident Reference: 95610225 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Fire Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NE (S)	608	2	387000 405595
35	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Oils - Kerosene Fuel Oil Note: Wince Brook Incident Date: 4th May 1995 Incident Reference: 95611025 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A9NW (SE)	608	2	387200 405700
36	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Rubble/Litter Or Solids Note: Wince Brook; Household Refuse Incident Date: 16th December 1991 Incident Reference: 91611993 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8NE (SE)	640	2	387100 405600

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
37	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Chemicals - Detergents/Surfactant Note: River Irk Incident Date: 9th June 1993 Incident Reference: 93611170 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	677	2	386800 405500
37	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Unknown Sewage Note: River Irk Incident Date: 29th June 1995 Incident Reference: 95611598 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	682	2	386800 405495
38	**Pollution Incidents to Controlled Waters** Property Type: Chemical industry Location: Irk, MIDDLETON Authority: Environment Agency, North West Region Pollutant: Chemicals - Detergents/Surfactant Note: Foam Incident Date: 15th January 1998 Incident Reference: SO980115 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Unknown Incident Severity: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	684	2	386705 405500
38	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Chemicals - Detergents/Surfactant Note: River Irk Incident Date: 9th March 1993 Incident Reference: 93610437 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	685	2	386700 405500
38	**Pollution Incidents to Controlled Waters** Property Type: Spillage; Accident - Static Site Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Chemicals - Detergents/Surfactant Note: River Irk and Irwell; Household Detergent Incident Date: 10th November 1996 Incident Reference: 96612324 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Accidental Spillage/Leakage Incident Severity: Category 1 - Major Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	689	2	386705 405495
38	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Chemicals - Detergents/Surfactant Note: River Irk Incident Date: 25th September 1995 Incident Reference: 95612398 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Ineffective Pumping Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A8SW (S)	690	2	386700 405495

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
39	**Pollution Incidents to Controlled Waters** Property Type: Private Sewage (Non-PLC): Sewerage Systems Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Sewage Debris/Litter Note: Wincle Bk Incident Date: 29th June 1994 Incident Reference: 94611426 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A9NW (SE)	689	2	387400 405800
40	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Oils - Other Fuel Oil Note: Whit Bk Incident Date: 19th November 1994 Incident Reference: 94612533 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Miscellaneous/Other Pollution Type Incident Severity: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 100m	A19SE (NE)	837	2	387500 406700
41	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Surface Water Outfall Location: Sewage On Outfall To Whit Brook, Clough Road , MIDDLETON Authority: Environment Agency, North West Region Pollutant: Crude Sewage Note: Not Supplied Incident Date: 7th December 1998 Incident Reference: SO982208 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Wrong Connection Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A19SE (NE)	917	2	387600 406695
41	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Not Given Note: Whit Brook Incident Date: 12th August 1993 Incident Reference: 93611596 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Not Given Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A19SE (NE)	919	2	387600 406700
42	**Pollution Incidents to Controlled Waters** Property Type: Other Location: Wince Brook Down Stream , Greengate, MIDDLETON Authority: Environment Agency, North West Region Pollutant: Miscellaneous - Colour Note: Creamy White; Wince Brook; Colouration Incident Date: 9th November 1997 Incident Reference: 97611886 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A14NE (E)	924	2	387700 406500
43	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Greater Manchester Authority: Environment Agency, North West Region Pollutant: Unknown Note: Whit Beck; None Pollution Found Incident Date: 9th August 1995 Incident Reference: 95612031 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Other Incident/Unknown Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A19NE (NE)	968	2	387500 406900

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
44	**Pollution Incidents to Controlled Waters** Property Type: Not Given Location: Barrels In Boarshaw Lodge, MIDDLETON Authority: Environment Agency, North West Region Pollutant: Rubbish Note: Not Supplied Incident Date: 7th December 1998 Incident Reference: SO982122 Catchment Area: Irk Receiving Water: Pond/Lake Cause of Incident: Other Cause Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A19SE (NE)	976	2	387600 406800
45	**Pollution Incidents to Controlled Waters** Property Type: Industrial: Other Location: Bridge Street, MIDDLETON Authority: Environment Agency, North West Region Pollutant: Oils - Black Fuel Oil Note: Oil In Irk Incident Date: 26th July 1998 Incident Reference: SO981328 Catchment Area: Irk Receiving Water: Freshwater Stream/River Cause of Incident: Accidental Spillage/Leakage Incident Severity: Category 3 - Minor Incident Positional Accuracy: Located by supplier to within 100m	A14NE (E)	976	2	387800 406200
46	**Pollution Incidents to Controlled Waters** Property Type: Water Company Sewage: Sewage Treatment Works Location: Location Description Not Available Authority: Environment Agency, North West Region Pollutant: Sewage - Treated Effluent Note: River Irk Incident Date: 13th January 1995 Incident Reference: 95610065 Catchment Area: Irk Receiving Water: Not Given Cause of Incident: Inadequate Construction Incident Severity: Category 2 - Significant Incident Positional Accuracy: Located by supplier to within 100m	A14NE (E)	981	2	387800 406300
	River Quality Name: Irk GQA Grade: River Quality E Reach: Royton Stw To Wince Bk Estimated Distance (km): 4.5 Flow Rate: Flow less than 1.25 cumecs Flow Type: River Year: 2000	A8NE (SE)	476	2	387078 405776
	River Quality Name: Whit (Trub) Bk GQA Grade: River Quality D Reach: Qsl At Castleton Stw To Irk Estimated Distance (km): 4.5 Flow Rate: Flow less than 0.31 cumecs Flow Type: River Year: 2000	A14SW (E)	525	2	387325 406021
	River Quality Name: Wince Bk GQA Grade: River Quality F Reach: Qsl At Foxdenton Lane To Irk Estimated Distance (km): 3.7 Flow Rate: Flow less than 0.31 cumecs Flow Type: River Year: 2000	A8NE (S)	670	2	387034 405541
	River Quality Name: Irk GQA Grade: River Quality E Reach: Wince Bk To Moston Bk Estimated Distance (km): 10.3 Flow Rate: Flow less than 2.5 cumecs Flow Type: River Year: 2000	A8SE (S)	744	2	386989 405452

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
47	**Substantiated Pollution Incident Register** Authority: Environment Agency - North West Region, South Area Incident Date: 14th April 2009 Incident Reference: 669886 Water Impact: Category 2 - Significant Incident Air Impact: Category 4 - No Impact Land Impact: Category 4 - No Impact Positional Accuracy: Located by supplier to within 10m Pollutant: Inorganic Chemicals : Alkalis Pollutant: Organic Chemicals/Products: Surfactants And Detergents	A8SW (S)	717	2	386652 405476
48	**Water Abstractions** Operator: Greater Manchester Council Licence Number: 2569005056 Permit Version: Not Supplied Location: River Irk, Middleton, MANCHESTER Authority: Environment Agency, North West Region Abstraction: Cooling Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 118 Yearly Rate (m3): 32504 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A14SW (SE)	470	2	387200 405895
49	**Water Abstractions** Operator: Robert McBride Limited; Middleton Licence Number: 2569005003 Permit Version: Not Supplied Location: Borehole, Leater Street, Middleton , MANCHESTER Authority: Environment Agency, North West Region Abstraction: Manufacturing Abstraction Type: Not Supplied Source: Groundwater Daily Rate (m3): 109 Yearly Rate (m3): 27276 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A8NW (S)	582	2	386800 405595
50	**Water Abstractions** Operator: H B Plastics Limited Licence Number: 2569005051 Permit Version: Not Supplied Location: River Irk At Townley Mills, MIDDLETON, Lancashire Authority: Environment Agency, North West Region Abstraction: Cooling Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 36 Yearly Rate (m3): 5682 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A14SW (E)	603	2	387400 406000
51	**Water Abstractions** Operator: B M Coatings Limited Licence Number: 2569005009 Permit Version: Not Supplied Location: Wince Brook At Premises, Tonge Mill, Oldham Road, MIDDLETON Authority: Environment Agency, North West Region Abstraction: Cooling Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 14 Yearly Rate (m3): 655 Details: Licence Status: Lapsed Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A8NE (S)	610	2	387005 405595

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
52	**Water Abstractions** Operator: Robert Mcbride Ltd Licence Number: 2569005035 Permit Version: 100 Location: Reservoir Fed By Surface Drainage At Middleton, Manchester(T Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: Boiler Feed Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 1091 Yearly Rate (m3): 288671 Details: Premises At Cheetham Street Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 2007 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A8NW (S)	611	2	386600 405600
52	**Water Abstractions** Operator: Robert Mcbride Ltd Licence Number: 2569005035 Permit Version: 100 Location: Reservoir Fed By Surface Drainage At Middleton, Manchester(T Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Cheetham Street Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st April 2007 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A8NW (S)	611	2	386600 405600
	Water Abstractions Operator: The New North Manchester Golf Club Ltd Licence Number: 2569005055 Permit Version: 101 Location: Reservoir Fed By Surface Drainage At North Manchester Golf C Authority: Environment Agency, North West Region Abstraction: Golf Courses: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: North Manchester Golf Course Authorised Start: 01 April Authorised End: 31 October Permit Start Date: 1st April 2008 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A7NW (SW)	1019	2	385900 405700
	Water Abstractions Operator: North Manchester Golf Club Licence Number: 2569005055 Permit Version: 100 Location: Reservoir Fed By Surface Drainage At North Manchester Golf Club Authority: Environment Agency, North West Region Abstraction: Golf Courses: Spray Irrigation - Direct Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 45 Yearly Rate (m3): 2273 Details: North Manchester Golf Course Authorised Start: 01 April Authorised End: 31 October Permit Start Date: 21st February 1977 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A7NW (SW)	1019	2	385900 405700

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Senior Service Ltd Licence Number: 2569005025 Permit Version: Not Supplied Location: River Irk, MIDDLETON Authority: Environment Agency, North West Region Abstraction: Cooling Abstraction Type: Not Supplied Source: Surface Daily Rate (m3): 182 Yearly Rate (m3): 50915 Details: Licence Status: Revoked Authorised Start: Not Supplied Authorised End: Not Supplied Permit Start Date: Not Supplied Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 100m	A15NE (E)	1479	2	388300 406300
	Water Abstractions Operator: Vita Cellular Foams (Uk) Limited Trading As Vitafoam Limited Licence Number: 2569005001 Permit Version: 103 Location: Borehole At Premises Don Mill, Don Street, Middleton Authority: Environment Agency, North West Region Abstraction: Petrochemicals: Non-Evaporative Cooling Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Don Mill, Don Street Authorised Start: 01 April Authorised End: 31 March Permit Start Date: 29th April 2010 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A15NE (E)	1489	2	388312 406242
	Water Abstractions Operator: Vitafoam Ltd Licence Number: 2569005001 Permit Version: 102 Location: Borehole At Premises Don Mill Don Street Middleton Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Don Mill, Don Street Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 1st January 2007 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A15NE (E)	1497	2	388320 406240
	Water Abstractions Operator: Eastland Compounding Ltd Licence Number: 2569005001 Permit Version: 101 Location: Borehole At Premises Don Mill Don Street Middleton Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Don Mill, Don Street Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 31st March 2004 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A15NE (E)	1497	2	388320 406240

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Water Abstractions Operator: Vitacom Ltd Licence Number: 2569005001 Permit Version: 100 Location: Borehole At Premises, Don Mill, Don Street, Middleton Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Groundwater Daily Rate (m3): 2182 Yearly Rate (m3): 545520 Details: Premises At Don Mill, Don Street Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 18th January 1966 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A15NE (E)	1497	2	388320 406240
	Water Abstractions Operator: Eastland Compounding Ltd Licence Number: 2569005006 Permit Version: 101 Location: R Irk At Premises, Don Mill, Don Street, Middleton Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): Not Supplied Yearly Rate (m3): Not Supplied Details: Premises At Don Street, Middleton Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 31st March 2004 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A15NE (E)	1637	2	388460 406240
	Water Abstractions Operator: Vitacom Ltd Licence Number: 2569005006 Permit Version: 100 Location: R Irk At Premises, Don Mill, Don Street, Middleton Authority: Environment Agency, North West Region Abstraction: Other Industrial/Commercial/Public Services: General Cooling (Existing Licences Only) (Low Loss) Abstraction Type: Water may be abstracted from a single point Source: Surface Daily Rate (m3): 1309 Yearly Rate (m3): 327312 Details: Premises At Don Street, Middleton Authorised Start: 01 January Authorised End: 31 December Permit Start Date: 23rd November 1998 Permit End Date: Not Supplied Positional Accuracy: Located by supplier to within 10m	A15NE (E)	1637	2	388460 406240
	Groundwater Vulnerability Map Combined Classification: Secondary Superficial Aquifer - Low Vulnerability Combined Vulnerability: Low Combined Aquifer: Productive Bedrock Aquifer, Productive Superficial Aquifer Pollutant Speed: Low Bedrock Flow: Well Connected Fractures Dilution: >550 mm/year Baseflow Index: <40% Superficial Patchiness: >90% Superficial Thickness: >10m Superficial Recharge: Low	A13SE (SE)	0	4	386812 406192
	Groundwater Vulnerability - Soluble Rock Risk None				
	Bedrock Aquifer Designations Aquifer Designation: Secondary Aquifer - A	A13SE (SE)	0	4	386812 406192
	Superficial Aquifer Designations Aquifer Designation: Secondary Aquifer - A	A13SE (SE)	0	4	386812 406192

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Extreme Flooding from Rivers or Sea without Defences None				
	Flooding from Rivers or Sea without Defences None				
	Areas Benefiting from Flood Defences None				
	Flood Water Storage Areas None				
	Flood Defences None				
53	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 26.1 Watercourse Level: Underground Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A14SW (SE)	457	5	387231 405970
54	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 105.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A14SW (SE)	457	5	387233 405974
55	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 501.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A8NE (SE)	461	5	387114 405819
56	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 193.9 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A14SW (SE)	476	5	387240 405945
57	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 1.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A9NW (SE)	478	5	387169 405847
58	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 2.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A9NW (SE)	479	5	387171 405846
59	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 625.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Whit Brook Catchment Name: Mersey Primacy: 1	A14SW (E)	525	5	387332 406045

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
60	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 129.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A14SW (E)	545	5	387332 405980
61	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 221.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A8NE (SE)	604	5	387128 405655
62	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 226.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A8NE (S)	610	5	386846 405568
63	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 1.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A8NE (S)	611	5	386842 405567
64	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 1.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A8NE (SE)	611	5	387054 405611
65	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 83.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A8NW (S)	612	5	386775 405565
66	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 29.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A8NE (S)	612	5	386841 405566
67	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 154.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A8NE (S)	636	5	386826 405542
68	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 9.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A14SW (E)	650	5	387452 406011

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
69	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 531.7 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A14SW (E)	656	5	387460 406017
70	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 681.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: River Irk Catchment Name: Mersey Primacy: 1	A8SW (S)	669	5	386720 405513
71	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 60.0 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SW (W)	707	5	386093 406159
72	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 192.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SE (SW)	712	5	386139 405913
73	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 6.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A9NW (SE)	716	5	387244 405597
74	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 163.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A9NW (SE)	716	5	387244 405597
75	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 22.3 Watercourse Level: Underground Permanent: True Watercourse Name: Whit Brook Catchment Name: Mersey Primacy: 1	A14NE (NE)	774	5	387541 406499
76	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 144.5 Watercourse Level: On ground surface Permanent: True Watercourse Name: Whit Brook Catchment Name: Mersey Primacy: 1	A14NE (NE)	794	5	387555 406516
77	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 70.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A9NW (SE)	856	5	387386 405531

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
78	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 18.9 Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A7NW (SW)	877	5	386027 405764
79	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 18.2 Watercourse Level: Underground Permanent: True Watercourse Name: Whit Brook Catchment Name: Mersey Primacy: 1	A19SE (NE)	891	5	387599 406647
80	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 193.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Whit Brook Catchment Name: Mersey Primacy: 1	A19SE (NE)	894	5	387593 406664
81	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 28.1 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A7NW (SW)	895	5	386013 405751
82	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 1.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A9NW (SE)	901	5	387456 405535
83	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 1.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A9NW (SE)	902	5	387458 405535
84	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 790.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Wince Brook Catchment Name: Mersey Primacy: 1	A9NW (SE)	902	5	387458 405535
85	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 19.6 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A9NW (SE)	904	5	387459 405534
86	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 13.3 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SW (W)	907	5	385912 405990

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
87	**OS Water Network Lines** Watercourse Form: Lake Watercourse Length: 111.2 Watercourse Level: On ground surface Permanent: True Watercourse Name: Asker Dam Catchment Name: Mersey Primacy: 1	A12SW (W)	908	5	385915 405977
88	**OS Water Network Lines** Watercourse Form: Reservoir Watercourse Length: 66.4 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A7NW (SW)	920	5	385996 405730
89	**OS Water Network Lines** Watercourse Form: Inland river Watercourse Length: 100.7 Watercourse Level: Underground Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A12SW (W)	936	5	385917 405867
90	**OS Water Network Lines** Watercourse Form: Reservoir Watercourse Length: 49.9 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A7NW (SW)	960	5	385932 405767
91	**OS Water Network Lines** Watercourse Form: Reservoir Watercourse Length: 56.8 Watercourse Level: On ground surface Permanent: True Watercourse Name: Not Supplied Catchment Name: Mersey Primacy: 1	A7NW (SW)	983	5	385931 405717

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
92	**BGS Recorded Landfill Sites** Site Name: Manchester Old Road Location: MIDDLETON, Gt Manchester Authority: British Geological Survey, National Geoscience Information Service Ground Water: No threat to ground water Surface Water: No threat to surface water Geology: N/A Positional Accuracy: Positioned by the supplier Boundary Accuracy: Moderate	A7SE (SW)	843	-	386297 405500
93	**Historical Landfill Sites** Licence Holder: Not Supplied Location: Mirefield Drive, Middleton, Manchester, Greater Manchester Name: Mirfield Drive Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16038 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste Type: Not Supplied EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: D069	A13NW (N)	72	2	386812 406280
94	**Historical Landfill Sites** Licence Holder: Not Supplied Location: Mellalieu Street, Middleton, Manchester, Greater Manchester Name: Mellalieu Street Playing Fields Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16023 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste Type: Not Supplied EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: D068	A13NE (N)	221	2	386860 406426
95	**Historical Landfill Sites** Licence Holder: Not Supplied Location: Higher Wood Street, Middleton, Manchester, Greater Manchester Name: Land off Higher Wood Street Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16012 First Input Date: Not Supplied Last Input Date: Not Supplied Specified Waste Type: Not Supplied EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: Not Supplied BGS Ref: Not Supplied Other Ref: D100	A13NW (N)	241	2	386765 406446
96	**Historical Landfill Sites** Licence Holder: Rochdale Metropolitan Borough Council Location: Manchester Old Road, Middleton, Manchester, Greater Manchester Name: Land off Manchester Old Road Operator Location: Not Supplied Boundary Accuracy: As Supplied Provider Reference: EAHLD16124 First Input Date: 31st December 1967 Last Input Date: 9th September 1974 Specified Waste Type: Deposited Waste included Inert, Industrial, Commercial, Household and Special Waste, and Liquid Sludge EA Waste Ref: 0 Regis Ref: Not Supplied WRC Ref: 4200/9655 BGS Ref: 2596 Other Ref: D055	A7SE (SW)	835	2	386302 405507

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
97	**Licensed Waste Management Facilities (Locations)** Licence Number: 103157 Location: 6 Morton Street, Middleton, Manchester, M24 6AN Operator Name: Mr Wayne Kenny And Mr Stephen Ramsey Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Vehicle Depollution Facility <5000 tps **Licence Status: Issued** Issued: 28th October 2011 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SW (E)	502	2	387325 406150
98	**Licensed Waste Management Facilities (Locations)** Licence Number: 53677 Location: Townley Street, Middleton, Manchester, M24 1AT Operator Name: G M Waste Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Surrendered** Issued: 1st February 1995 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: 14th May 2003 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SW (SE)	509	2	387270 405932
99	**Licensed Waste Management Facilities (Locations)** Licence Number: 50460 Location: Hanson Street, Middleton, Manchester, M24 2HW Operator Name: Middleton Waste And Recycling Limited Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: HCI Waste TS + treatment **Licence Status: Revoked** Issued: 17th February 2007 Last Modified: 15th November 2013 Expires: Not Supplied Suspended: Not Supplied Revoked: 3rd June 2015 Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SW (E)	593	2	387413 406111
100	**Licensed Waste Management Facilities (Locations)** Licence Number: 50138 Location: Land/premises At, Spring Vale, Middleton, Manchester, M24 2HQ Operator Name: Suez Recycling And Recovery U K Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Household, Commercial And Industrial Transfer Stations **Licence Status: Transferred** Issued: 26th March 2003 Last Modified: 26th May 2009 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SW (SE)	615	2	387393 405944
101	**Licensed Waste Management Facilities (Locations)** Licence Number: 100068 Location: Land/ Premises At, Spring Vale, Middleton, Manchester, M24 2HR Operator Name: V W & Audi Used Spares Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: End of Life Vehicles **Licence Status: Issued** Issued: 26th November 2007 Last Modified: Not Supplied Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: Not Supplied IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A14SW (E)	660	2	387454 405983

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
102	**Licensed Waste Management Facilities (Locations)** Licence Number: 101689 Location: Units 1-5 Linkway Trading Estate, Grimshaw Lane, Middleton, Manchester, M24 2AU Operator Name: The Waste Exchange (U K) Ltd Operator Location: Not Supplied Authority: Environment Agency - North West Region, South Area Site Category: Physical Treatment Facilities **Licence Status: Surrendered** Issued: 6th August 2010 Last Modified: 24th June 2011 Expires: Not Supplied Suspended: Not Supplied Revoked: Not Supplied Surrendered: 11th August 2014 IPPC Reference: Not Supplied Positional Accuracy: Located by supplier to within 10m	A9NE (SE)	959	2	387590 405600
	Local Authority Landfill Coverage Name: Rochdale Metropolitan Borough Council - Has no landfill data to supply		0	3	386812 406192
103	**Registered Waste Transfer Sites** Licence Holder: Greater Manchester Waste Ltd Licence Reference: 00887 Site Location: Middleton C.A.Site, Townley Street, Middleton, Manchester, Greater Manchester Operator Location: PO Box 151, Higher Swan Lane, BOLTON, Lancashire, BL3 3WW Authority: Environment Agency - North West Region, South Area Site Category: Civic Amenity Max Input Rate: Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Operational as far as is knownOperational Dated: 1st February 1995 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Approximate location provided by supplier Boundary Quality: Not Supplied Authorised Waste: Asbestos Gmwda Group 1 - Non/V.Slow Decomp.Wast Gmwda Group 2 - Slow Decomp./Slight So Gmwda Group 3 - Decomp./Sol.Waste = No Gmwda Group 5 - Chemical/Toxic Waste Max.Waste Permitted By Licence Prohibited Waste: Acid Tars Clinical - Grp A As In Hse '92 Distillation Residues Dyestuffs Waste Foundry Sand Incinerator Residues Industrial Effluent Treatment Sludge Interceptor Pit Wastes Laboratory Chemicals Pharmaceuticals Polymeric Material, Products/Scrap Printing Industry Wastes/Ink Prod'Ts Of Incomplete Polymerisation Sewage Tank Cleaning Sludge Used Filter Mat'Ls/Cake/Screenings	A14SW (SE)	467	2	387200 405900

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
104	**Registered Waste Treatment or Disposal Sites** Licence Holder: G.M.W.D.A. Licence Reference: R/006 Site Location: Middleton Incinerator, Bridge Street, Middleton, Manchester, Greater Manchester Operator Location: Blackfriars House, Parsonage, MANCHESTER, Greater Manchester, M3 2JA Authority: Environment Agency - North West Region, South Area Site Category: Incineration Max Input Rate: Large (Equal to or greater than 75,000 and less than 250,000 tonnes per year) Waste Source Restrictions: No known restriction on source of waste Licence Status: Licence lapsed/cancelled/defunct/not applicable/surrenderedCancelled Dated: 22nd June 1979 Preceded By Licence: Not Given Superseded By Licence: Not Given Positional Accuracy: Manually positioned to the address or location Boundary Quality: Not Supplied Authorised Waste: Animal And Food Wastes Cellulose Wastes (Natural/Synth.) Contaminated Materials $ Empty Used Containers Fine Chemicals And Biocides Fuels, Oils, Greases House, Com + Ind.Waste Household + Commercial Waste Interceptor Waste, Tar, Paint Etc $ Miscellaneous Wastes Organic Acids + Related Cmpds Organic Compounds Polymeric Material, Products/Scrap Polymeric Materials And Precursors Scrap Rubber (Including Tyres) Toxic Metal Compounds Waste Treated Timber	A14SW (SE)	454	2	387191 405911

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
105	**Control of Major Accident Hazards Sites (COMAH)** Name: Robert Mcbride Limited Location: Middleton Head Office, Irkvale Works, Middleton Way, Middleton, Manchester, M24 4dp Reference: Not Supplied Type: Upper Tier **Status: Active** Positional Accuracy: Manually positioned to the address or location	A8NW (S)	601	6	386694 405586
106	**Planning Hazardous Substance Consents** Name: Robert Mcbride Ltd Location: Middleton Way, Middleton, Rochdale, M24 4dp Authority: Rochdale Metropolitan Borough Council Application Ref: 13/01119/HAZ Hazardous Substance: Unknown at time of report Maximum Quantity: 0 Application date: 17th October 2013 **Decision: Deemed Consent GrantedGranted** Positional Accuracy: Manually positioned to the address or location	A8NW (S)	601	7	386694 405586
106	**Planning Hazardous Substance Consents** Name: Robert Mcbride Ltd Location: Middleton Way, Rochdale, M24 4DP Authority: Rochdale Metropolitan Borough Council Application Ref: D53337 Hazardous Substance: Unknown at time of report Maximum Quantity: 0 Application date: 21st July 2010 **Decision: Deemed Consent GrantedGranted** Positional Accuracy: Manually positioned to the address or location	A8NW (S)	601	7	386694 405586
106	**Planning Hazardous Substance Consents** Name: Robert Mcbride Ltd Location: Middleton Way, Rochdale, M24 4dp Authority: Rochdale Metropolitan Borough Council Application Ref: 10/D53337 Hazardous Substance: Combination of Dangerous Substances Maximum Quantity: 0 Application date: 4th June 2010 **Decision: Unknown at time of reportUnknown** Positional Accuracy: Manually positioned to the address or location	A8NW (S)	601	7	386694 405586

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS 1:625,000 Solid Geology Description: Pennine Lower Coal Measures Formation And South Wales Lower Coal Measures Formation (Undifferentiated)	A13SE (SE)	0	1	386812 406192
107	**BGS Recorded Mineral Sites** Site Name: Brook Hill Sand Pit Location: Middleton, Lancashire Source: British Geological Survey, National Geoscience Information Service Reference: 96879 Type: Opencast **Status: Ceased** Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Quaternary Geology: Glaciofluvial Deposits, Devensian Commodity: Sand Positional Accuracy: Located by supplier to within 10m	A14NW (E)	562	1	387353 406397
108	**BGS Recorded Mineral Sites** Site Name: High Barn Sand Pit Location: Middleton, Lancashire Source: British Geological Survey, National Geoscience Information Service Reference: 96880 Type: Opencast **Status: Ceased** Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Quaternary Geology: Till, Devensian Commodity: Sand Positional Accuracy: Located by supplier to within 10m	A12NE (W)	644	1	386179 406377
109	**BGS Recorded Mineral Sites** Site Name: Little Park Sand Pit Location: Middleton, Lancashire Source: British Geological Survey, National Geoscience Information Service Reference: 96892 Type: Opencast **Status: Ceased** Operator: Unknown Operator Operator Location: Not Supplied Periodic Type: Quaternary Geology: Glaciofluvial Deposits, Devensian Commodity: Sand Positional Accuracy: Located by supplier to within 10m	A9NW (SE)	739	1	387366 405675
	Coal Mining Affected Areas Description: In an area which may be affected by coal mining activity. It is recommended that a coal mining report is obtained from the Coal Authority. Contact details are included in the Useful Contacts section of this report.	A13SE (SE)	0	8	386812 406192
	Mining Instability Mining Evidence: Inconclusive Coal Mining Source: Ove Arup & Partners Boundary Quality: As Supplied	A13SE (SE)	0	-	386812 406192
	Non Coal Mining Areas of Great Britain No Hazard				
	Potential for Collapsible Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192
	Potential for Compressible Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192
	Potential for Ground Dissolution Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192
	Potential for Landslide Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192
	Potential for Running Sand Ground Stability Hazards Hazard Potential: Very Low Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192
	Potential for Shrinking or Swelling Clay Ground Stability Hazards Hazard Potential: No Hazard Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Radon Potential - Radon Affected Areas Affected Area: The property is in a Lower probability radon area (less than 1% of homes are estimated to be at or above the Action Level). Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192
	Radon Potential - Radon Protection Measures Protection Measure: No radon protective measures are necessary in the construction of new dwellings or extensions Source: British Geological Survey, National Geoscience Information Service	A13SE (SE)	0	1	386812 406192

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
110	**Contemporary Trade Directory Entries** Name: Robert Andrews Location: Crystal House, Sadler Street, Middleton, Manchester, M24 5UJ Classification: Upholstery Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A13SE (E)	131	-	386953 406152
110	**Contemporary Trade Directory Entries** Name: Ella & Me Ltd Location: Sadler Street, Middleton, Manchester, M24 5UJ Classification: Lingerie & Hosiery Manufacturers & Wholesalers **Status: Active** Positional Accuracy: Automatically positioned in the proximity of the address	A13SE (E)	131	-	386953 406152
110	**Contemporary Trade Directory Entries** Name: Pearl Textiles Location: Crystal House, Sadler Street, Middleton, Manchester, M24 5UJ Classification: Lace Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (SE)	141	-	386952 406120
111	**Contemporary Trade Directory Entries** Name: North West Fascias & Soffits Location: 25, Durnford Street, Middleton, Manchester, M24 5UD Classification: Fascias and Soffits **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (E)	142	-	386964 406227
112	**Contemporary Trade Directory Entries** Name: Middelton Car Body Centre Location: Car Body Centre, Whittaker Street, Middleton, M24 4BL Classification: Car Body Repairs **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SE (S)	203	-	386819 405974
112	**Contemporary Trade Directory Entries** Name: Car Body Centre Location: Car Body Centre, Whittaker Street, Middleton, M24 4BL Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (S)	203	-	386819 405974
112	**Contemporary Trade Directory Entries** Name: Snowgene Products Location: Whittaker St, Middleton, Manchester, M24 4BL Classification: Cleaning Materials & Equipment **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A13SW (S)	221	-	386772 405958
113	**Contemporary Trade Directory Entries** Name: S Linen Location: Water Street, Middleton, Manchester, M24 5UG Classification: Clothing & Fabrics - Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SE (SE)	212	-	386949 406006
114	**Contemporary Trade Directory Entries** Name: A B C Blinds & Carpets Location: 10c, Wood Street, Middleton, Manchester, Lancashire, M24 5TF Classification: Blinds, Awnings & Canopies **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (SE)	229	-	386909 405964
115	**Contemporary Trade Directory Entries** Name: D A P Design & Print Location: 46-48 Long Street, Middleton, Manchester, Greater Manchester, M24 6UQ Classification: Printers **Status: Active** Positional Accuracy: Automatically positioned to the address	A13SE (E)	262	-	387083 406140
115	**Contemporary Trade Directory Entries** Name: The Print Works Location: Optima House, 2, Cemetery Street, Middleton, Manchester, M24 6UP Classification: Printers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (E)	279	-	387091 406098
116	**Contemporary Trade Directory Entries** Name: Traditional Timber Location: 10, Mellalieu Street, Middleton, Manchester, M24 5DN Classification: Windows - Sash **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	270	-	387013 406400

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
116	**Contemporary Trade Directory Entries** Name: Traditional Timber Sash Windows Location: 10, Mellalieu Street, Middleton, Manchester, M24 5DN Classification: Windows - Sash **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	270	-	387013 406400
117	**Contemporary Trade Directory Entries** Name: Tyro Cleaners Ltd Location: 8, Middleton Gardens, Middleton, Manchester, M24 4DF Classification: Dry Cleaners **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (S)	299	-	386912 405892
117	**Contemporary Trade Directory Entries** Name: Wright Blinds Location: 11 Fountain St, Middleton, Manchester, Lancashire, M24 1AF Classification: Blinds, Awnings & Canopies **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A8NE (S)	346	-	386940 405852
118	**Contemporary Trade Directory Entries** Name: Brighthouse Location: 24, Middleton Gardens, Middleton, Manchester, M24 4DF Classification: Electrical Goods Sales, Manufacturers & Wholesalers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SE (S)	307	-	386861 405873
119	**Contemporary Trade Directory Entries** Name: Prints Location: 50-54, Market Place, Middleton, Manchester, M24 6AF Classification: Photographic Processors **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	357	-	387156 406047
120	**Contemporary Trade Directory Entries** Name: Minster Cleaning Services Location: 2-6, Rochdale Road, Middleton, Manchester, M24 6DP Classification: Commercial Cleaning Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	370	-	387069 406484
120	**Contemporary Trade Directory Entries** Name: Minster Cleaning Services Location: 2-6, Rochdale Road, Middleton, Manchester, M24 6DP Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	370	-	387069 406484
120	**Contemporary Trade Directory Entries** Name: Minster Cleaning Services Location: 2-6, Rochdale Road, Middleton, Manchester, M24 6DP Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	370	-	387069 406484
121	**Contemporary Trade Directory Entries** Name: Elite Print Solutions Ltd Location: Rose Mill,Union St, Middleton, Manchester, Lancashire, M24 6DD Classification: Printers **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A13NE (NE)	371	-	387126 406422
121	**Contemporary Trade Directory Entries** Name: Blackrose Designs Location: Unit 1, Spring Gardens, Middleton, Manchester, M24 6DQ Classification: Fireplaces & Mantelpieces **Status: Active** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	371	-	387107 406448
121	**Contemporary Trade Directory Entries** Name: Chadderton Fabrications Location: Unit 4, Spring Gardens, Middleton, Manchester, M24 6DQ Classification: Engineers - General **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	371	-	387107 406448
121	**Contemporary Trade Directory Entries** Name: Chainbond Ltd Location: Rose Mill, Union Street, Middleton, MANCHESTER, M24 6DD Classification: Rubber & Plastic Products - Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	371	-	387126 406422

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
121	**Contemporary Trade Directory Entries** Name: Pathrun Location: Rose Mill, Union Street, Middleton, Manchester, M24 6DD Classification: Sports Equipment Manufacturers & Distributors **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	371	-	387126 406422
121	**Contemporary Trade Directory Entries** Name: Pathology Management Services Location: Rose Mill, Union Street, Middleton, Manchester, Lancashire, M24 6DD Classification: Laboratories **Status: Active** Positional Accuracy: Manually positioned to the address or location	A13NE (NE)	371	-	387126 406422
121	**Contemporary Trade Directory Entries** Name: Paradis Novo Ltd Location: Heaton Mill, Spring Gardens, Middleton, Manchester, M24 6DQ Classification: Sports Equipment Manufacturers & Distributors **Status: Active** Positional Accuracy: Automatically positioned to the address	A13NE (NE)	372	-	387107 406448
121	**Contemporary Trade Directory Entries** Name: First Agenda Location: Unit 6,Spring Gdns, Middleton, Manchester, Lancashire, M24 6DQ Classification: Packaging & Wrapping Equipment & Supplies **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A13NE (NE)	379	-	387094 406474
121	**Contemporary Trade Directory Entries** Name: Range Clean Uk Location: 10b, King Street, Middleton, Manchester, M24 6DT Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (NE)	408	-	387153 406448
122	**Contemporary Trade Directory Entries** Name: M B International Transport Services Ltd Location: 33, Beech Street, Middleton, Manchester, M24 4AW Classification: Freight Forwarders **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A13SW (SW)	383	-	386583 405862
122	**Contemporary Trade Directory Entries** Name: General Mastic Asphalt Location: 3, Michael Street, Middleton, Manchester, M24 4DX Classification: Asphalt & Coated Macadam Laying Contractors **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	404	-	386605 405824
123	**Contemporary Trade Directory Entries** Name: M K Motors Location: Corporation St, Middleton, Manchester, M24 1AQ Classification: Car Dealers **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A13SE (SE)	389	-	387119 405924
123	**Contemporary Trade Directory Entries** Name: M & L Tyres Location: Corporation St, Middleton, Manchester, M24 1AQ Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A13SE (SE)	406	-	387128 405908
124	**Contemporary Trade Directory Entries** Name: Union Leisurewear Ltd Location: Flexi Business Centre,Old Hall Street, Middleton, Manchester, Greater Manchester, M24 1AG Classification: T-Shirts **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A14SW (E)	401	-	387207 406061
124	**Contemporary Trade Directory Entries** Name: Comfy Quilts Ltd Location: Albany Mill, Old Hall Street, Middleton, Manchester, M24 1AG Classification: Bed & Mattress Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	425	-	387218 406019

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
124	**Contemporary Trade Directory Entries** Name: Comfy Quilts Ltd Location: Albany Mill, Old Hall Street, Middleton, Manchester, M24 1AG Classification: Bed & Mattress Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	425	-	387218 406019
124	**Contemporary Trade Directory Entries** Name: Customize Location: 7, Townley Street, Middleton, Manchester, M24 1AT Classification: T-Shirts **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	448	-	387255 406058
125	**Contemporary Trade Directory Entries** Name: Time Electronics Location: G47-48, Middleton Shopping Centre, Middleton, Manchester, Lancashire, M24 4EL Classification: Electrical Goods Sales, Manufacturers & Wholesalers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: La Perfumerie Location: G47-48, Middleton Shopping Centre, Middleton, Manchester, M24 4EL Classification: Perfume Suppliers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: Reflections Location: S5, Middleton Shopping Centre, Middleton, Manchester, M24 4EL Classification: Mirrors & Decorative Glass **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: Klick Photopoint Location: G18, Middleton Shopping Centre, Middleton, Manchester, Lancashire, M24 4EL Classification: Photographic Processors **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: Harveys The Jewellers Location: G24-25, Middleton Shopping Centre, Middleton, Manchester, Lancashire, M24 4EL Classification: Jewellery Manufacturers & Repairers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: Klick Location: G18, Middleton Shopping Centre, Middleton, Manchester, Lancashire, M24 4EL Classification: Photographic Processors **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: Handprint T-Shirts Location: Middleton, Manchester, Greater Manchester, M24 4EL Classification: T-Shirts **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A8NW (S)	425	-	386776 405753
125	**Contemporary Trade Directory Entries** Name: Snoopy'S Location: Middleton Shopping Centre, Middleton, Manchester, Lancashire, M24 4EL Classification: Pet Foods & Animal Feeds **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A8NW (S)	426	-	386776 405752
126	**Contemporary Trade Directory Entries** Name: Northern Radio Communications Ltd Location: 1, Lodge Street, Middleton, Manchester, M24 6AA Classification: Radio Communication Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	435	-	387252 406103

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
126	**Contemporary Trade Directory Entries** Name: Archer Blinds Ltd Location: 1 Lodge St, Middleton, Manchester, Lancashire, M24 6AA Classification: Blinds, Awnings & Canopies **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A14SW (E)	435	-	387252 406102
126	**Contemporary Trade Directory Entries** Name: Zebs Painting Location: 1, Townley Street, Middleton, Manchester, M24 1AT Classification: Painting & Decorating Supplies **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	439	-	387251 406077
126	**Contemporary Trade Directory Entries** Name: Pioneer Motor Trading Location: Unit 4 Pioneer Mill,Lodge St, Middleton, Manchester, Lancashire, M24 6AA Classification: Car Dealers - Used **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SW (E)	446	-	387261 406092
126	**Contemporary Trade Directory Entries** Name: Two Wheels Location: 12-14, Lodge Street, Middleton, Manchester, Lancashire, M24 6AL Classification: Mot Testing Centres **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	453	-	387267 406082
126	**Contemporary Trade Directory Entries** Name: Three Star Salvage Location: Pioneer Mill, Morton Street, Middleton, Manchester, M24 6AN Classification: Salvage Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	469	-	387290 406126
126	**Contemporary Trade Directory Entries** Name: C H Cowen Print Finishers Location: Lodge Street, Middleton, Manchester, M24 6AD Classification: Print Finishers **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14SW (E)	471	-	387289 406104
126	**Contemporary Trade Directory Entries** Name: Newmark Joinery Ltd Location: Lodge Street, Middleton, Manchester, M24 6AD Classification: Joinery Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14SW (E)	471	-	387289 406104
126	**Contemporary Trade Directory Entries** Name: Middleton Auto Salvage Location: Lodge Street, Middleton, Manchester, M24 6AD Classification: Salvage Dealers **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14SW (E)	471	-	387289 406104
126	**Contemporary Trade Directory Entries** Name: Greenlite (Manchester) Ltd Location: Lodge Street, Middleton, Manchester, Lancashire, M24 6AA Classification: Lighting Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	473	-	387293 406114
126	**Contemporary Trade Directory Entries** Name: Phoenix Vacuum Location: Pioneer House, 7-15, Lodge Street, Middleton, Manchester, Lancashire, M24 6AA Classification: Vacuum Cleaners, Industrial & Commercial - Manufacturers & Distributors **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A14SW (E)	473	-	387293 406114
126	**Contemporary Trade Directory Entries** Name: S T F Design & Installation Location: Unit 1,Pioneer Mill,Morton St, Middleton, Manchester, Lancashire, M24 6AN Classification: Shop Fittings Manufacturers **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A14SW (E)	479	-	387300 406129

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
126	**Contemporary Trade Directory Entries** Name: Size Wise Location: Unit 3a-5a, Brookside House, Townley Street, Middleton, Manchester, M24 1AT Classification: Kitchen Furniture Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	480	-	387288 406056
126	**Contemporary Trade Directory Entries** Name: Polaris Flight Cases Location: Brookside House,Unit 5 Townley Street, Middleton, Manchester, Greater Manchester, M24 1AT Classification: Case Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	480	-	387288 406056
126	**Contemporary Trade Directory Entries** Name: N F S Location: Pioneer Mill, Morton Street, Middleton, Manchester, M24 6AN Classification: Firefighting Equipment **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	480	-	387301 406130
126	**Contemporary Trade Directory Entries** Name: Brentex Sales Location: Pioneer Mill, Morton Street, Middleton, Manchester, M24 6AN Classification: Adhesives, Glues & Sealants **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	480	-	387301 406130
126	**Contemporary Trade Directory Entries** Name: Lodge Street Garage Location: Lodge Street, Middleton, Manchester, M24 6AA Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	505	-	387322 406094
127	**Contemporary Trade Directory Entries** Name: Clean Card Systems Location: Unit 3, Spring Gardens, Middleton, Manchester, M24 6DQ Classification: Plastic Products - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18SE (NE)	436	-	387102 406544
128	**Contemporary Trade Directory Entries** Name: Cooper Car Sales Location: Townley Street, Middleton, Manchester, M24 1AT Classification: Car Dealers **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14SW (E)	476	-	387278 406036
128	**Contemporary Trade Directory Entries** Name: James Coates Bros Ltd Location: Lodge Mill, Townley Street, Middleton, Manchester, M24 1AT Classification: Glass Fibre - Moulding **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	515	-	387305 405994
129	**Contemporary Trade Directory Entries** Name: Computer Exchange Location: Systems House, Morton Street, Middleton, Manchester, M24 6AN Classification: Computer Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	479	-	387303 406192
129	**Contemporary Trade Directory Entries** Name: Burns Rubber Ltd Location: Systems House, Morton Street, Middleton, Manchester, M24 6AN Classification: Tyre Dealers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	479	-	387303 406193
129	**Contemporary Trade Directory Entries** Name: Accidentrepairs.Com Ltd Location: Haluszczak House, Morton Street, Middleton, Manchester, M24 6AN Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14NW (E)	491	-	387315 406216

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
129	**Contemporary Trade Directory Entries** Name: Dascott Construction & Recovery Location: 4 Morton St, Middleton, Manchester, Lancashire, M24 6AN Classification: Breakdown and Recovery **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	494	-	387318 406212
129	**Contemporary Trade Directory Entries** Name: Brentex Gas Ltd Location: 1-5 Morton St, Middleton, Manchester, M24 6AX Classification: Brewery Supplies **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14NW (E)	499	-	387322 406226
129	**Contemporary Trade Directory Entries** Name: 3 Star Salvage Location: Haluszczak House, Morton Street, Middleton, MANCHESTER, M24 6AN Classification: Car Breakers & Dismantlers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	505	-	387329 406175
130	**Contemporary Trade Directory Entries** Name: Acre Ltd Location: Civic Amenities Site, Bridge Street, Middleton, Manchester, M24 1TP Classification: Recycling Centres **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	484	-	387225 405907
131	**Contemporary Trade Directory Entries** Name: Imago Group Plc Location: Balmoral House, Warwick Court, Park Road, Middleton, Manchester, M24 1AE Classification: Distribution Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (SE)	485	-	387144 405813
131	**Contemporary Trade Directory Entries** Name: Focsa Services (Uk) Ltd Location: Brook House, Oldham Road, Middleton, Manchester, Lancashire, M24 1AY Classification: Waste Disposal Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (SE)	516	-	387135 405766
132	**Contemporary Trade Directory Entries** Name: Brentex Sales Ltd Location: 1-5 Morton St, Middleton, Manchester, Lancashire, M24 6AN Classification: Adhesives, Glues & Sealants **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SW (E)	493	-	387316 406164
133	**Contemporary Trade Directory Entries** Name: Tesco Petrol Station Location: Barton Road, Middleton, Manchester, M24 1UQ Classification: Petrol Filling Stations **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (SE)	510	-	387026 405709
134	**Contemporary Trade Directory Entries** Name: Vee Bee Plastic Coatings Location: 70, Springfield Road, Middleton, Manchester, M24 5DL Classification: Plastics - Coating Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18SE (N)	515	-	386904 406716
135	**Contemporary Trade Directory Entries** Name: Doravelle Fashions Ltd Location: Unit 4, Parkfield Industrial Estate, Kemp Street, Middleton, Manchester, M24 4AA Classification: Clothing & Fabrics - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	516	-	386538 405732
135	**Contemporary Trade Directory Entries** Name: Kemp Street Mot Centre Ltd Location: Unit 10/11, Parkfield Industrial Estate, Kemp Street, Middleton, Manchester, Lancashire, M24 4AA Classification: Mot Testing Centres **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	516	-	386538 405732

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
135	**Contemporary Trade Directory Entries** Name: Bountex Ltd Location: Unit 4, Parkfield Industrial Estate, Kemp Street, Middleton, Manchester, Lancashire, M24 4AA Classification: Clothing & Fabrics - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	516	-	386538 405732
135	**Contemporary Trade Directory Entries** Name: Northern Switchgear Services Ltd Location: Unit 12, Parkfield Industrial Estate, Kemp Street, Middleton, Manchester, M24 4AA Classification: Engineering Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	516	-	386538 405732
135	**Contemporary Trade Directory Entries** Name: Mansfield Soft Furnishings Location: Unit 9, Parkfield Industrial Estate, Kemp Street, Middleton, Manchester, M24 4AA Classification: Soft Furnishings - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NW (SW)	516	-	386538 405732
136	**Contemporary Trade Directory Entries** Name: L M Clothing Location: 38-42, Townley Street, Middleton, Manchester, M24 1AS Classification: Clothing & Fabrics - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	532	-	387289 405920
136	**Contemporary Trade Directory Entries** Name: L M Clothing Location: 38-42, Townley Street, Middleton, Manchester, M24 1AS Classification: Clothing & Fabrics - Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	532	-	387289 405920
136	**Contemporary Trade Directory Entries** Name: J & P Schofield Location: 46-48, Townley Street, Middleton, Manchester, M24 1AS Classification: Vacuum Cleaners - Sales & Service **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	570	-	387313 405885
136	**Contemporary Trade Directory Entries** Name: Building & Restorations (Uk) Ltd Location: Restoration House, 46-48, Townley Street, Middleton, Manchester, M24 1AS Classification: Woodworm Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	570	-	387313 405885
136	**Contemporary Trade Directory Entries** Name: Bar Preservation Location: 46-48, Townley Street, Middleton, Manchester, M24 1AS Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	571	-	387313 405883
136	**Contemporary Trade Directory Entries** Name: Homeshield Shutters Location: 21, Townley Street, Middleton, Manchester, M24 1AT Classification: Roller Shutter Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	574	-	387333 405912
137	**Contemporary Trade Directory Entries** Name: Northern Machinery Installations Location: Church St, Middleton, Manchester, M24 2PY Classification: Machinery - Industrial & Commercial **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	539	-	387156 406632
137	**Contemporary Trade Directory Entries** Name: Hammertorq Location: Unit 3,Church St, Middleton, Manchester, Lancashire, M24 2PY Classification: Plant & Machinery Repairs **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	573	-	387167 406666

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
138	**Contemporary Trade Directory Entries** Name: Vita Cellular Foam Uk Ltd Location: Oldham Rd, Middleton, Manchester, Lancashire, M24 2DB Classification: Foam Products - Rubber & Plastics **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A8NE (S)	542	-	387003 405666
138	**Contemporary Trade Directory Entries** Name: Unique Crafts Location: Oldham Rd, Middleton, Manchester, Lancashire, M24 1QZ Classification: Soft Furnishings - Manufacturers **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A8NE (S)	554	-	386988 405648
139	**Contemporary Trade Directory Entries** Name: J J Blackledge Location: Harpoon House, Sharp Street, Middleton, Manchester, M24 1AD Classification: Cutting Tools & Machinery **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	558	-	387257 405826
139	**Contemporary Trade Directory Entries** Name: Hotprice Location: Harpoon House, Sharp Street, Middleton, Manchester, M24 1AD Classification: Fireplaces & Mantelpieces **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	558	-	387257 405826
140	**Contemporary Trade Directory Entries** Name: Flames Location: Harpoon House, Sharp Street, Middleton, Manchester, M24 1AD Classification: Fireplaces & Mantelpieces **Status: Active** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	560	-	387260 405826
140	**Contemporary Trade Directory Entries** Name: B Luft Location: 5, Sharp Street, Middleton, Manchester, M24 1AD Classification: Hats & Caps - Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	586	-	387306 405843
141	**Contemporary Trade Directory Entries** Name: Drive 2000 Location: Townley Street, Middleton, Manchester, M24 1AT Classification: Garage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	561	-	387336 405949
141	**Contemporary Trade Directory Entries** Name: W H Contracts Ltd Location: Unit 2, Townley Park, Hanson Street, Middleton, Manchester, M24 2UF Classification: Road Haulage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	564	-	387358 405997
141	**Contemporary Trade Directory Entries** Name: Drive 2000 Ltd Location: Townley Street, Middleton, Manchester, M24 1AT Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	576	-	387357 405958
141	**Contemporary Trade Directory Entries** Name: Drive 2000 Ltd Location: Townley Street, Middleton, Manchester, M24 1AT Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	576	-	387357 405958
141	**Contemporary Trade Directory Entries** Name: Middleton Scrap Metal Ltd Location: 4 Hanson st, Middleton, Manchester, Lancashire, M24 2UF Classification: Scrap Metal Merchants **Status: Active** Positional Accuracy: Manually positioned within the geographical locality	A14SW (E)	590	-	387386 405998
142	**Contemporary Trade Directory Entries** Name: Restoration Services Location: Unit, Hanson Street Works, Hanson Street, Middleton, M24 2UF Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	571	-	387394 406142

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
142	**Contemporary Trade Directory Entries** Name: Restoration Services Location: Hanson Street Works,Hanson Street, Middleton, Manchester, Greater Manchester, M24 2UF Classification: Car Body Repairs **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	571	-	387394 406142
142	**Contemporary Trade Directory Entries** Name: Family Auto Services Location: Unit 1, Hanson Street Works, Hanson Street, Middleton, M24 2UF Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	571	-	387394 406142
143	**Contemporary Trade Directory Entries** Name: Halfords Autocentre Location: Unit 7-8, Central Industrial Estate, Oldham Road, Middleton, Manchester, Lancashire, M24 1QZ Classification: Garage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	576	-	386972 405621
143	**Contemporary Trade Directory Entries** Name: Airconco Ltd Location: Central Ind Est,Oldham Rd, Middleton, Manchester, Lancashire, M24 1QZ Classification: Air Conditioning Equipment & Systems **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A8NE (S)	578	-	386991 405624
143	**Contemporary Trade Directory Entries** Name: Spectrum Coatings Ltd Location: Unit 8, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Coating Specialists **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	580	-	386961 405613
143	**Contemporary Trade Directory Entries** Name: Central Pattern Book Co Ltd Location: Unit 10, Central Industrial Estate, Oldham Road, Middleton, Manchester, Lancashire, M24 1QZ Classification: Pattern Makers - Industrial **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	587	-	386940 405602
143	**Contemporary Trade Directory Entries** Name: Airconco Ltd Location: Unit 10, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Commercial Vehicle Servicing, Repairs, Parts & Accessories **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	587	-	386940 405602
143	**Contemporary Trade Directory Entries** Name: Total Tinting Uk Ltd Location: Unit 1, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Window Tinting **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	605	-	387015 405603
143	**Contemporary Trade Directory Entries** Name: Concept Ecu Remapping Location: Unit 1, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Car Engine Tuning & Diagnostic Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	605	-	387015 405603
143	**Contemporary Trade Directory Entries** Name: Middleton Blinds Ltd Location: Unit 14, Middleton Trade Park, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Blinds, Awnings & Canopies **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	607	-	387013 405601

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
143	**Contemporary Trade Directory Entries** Name: Leitz Tooling Uk Ltd Location: Unit 5 Middleton Trade Park,Oldham Road, Middleton, Manchester, Greater Manchester, M24 1QZ Classification: Cutting Tools & Machinery **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	607	-	387013 405601
143	**Contemporary Trade Directory Entries** Name: Screwfix Location: Middleton Trade Park,Oldham Road, Middleton, Manchester, Greater Manchester, M24 1QZ Classification: Builders' Merchants **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	607	-	387013 405601
143	**Contemporary Trade Directory Entries** Name: Middleton Blinds & Shutters Location: Unit 14, Middleton Trade Park, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Blinds, Awnings & Canopies **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	607	-	387013 405601
143	**Contemporary Trade Directory Entries** Name: Leitz Tooling Uk Ltd Location: Unit 2, Central Industrial Estate, Oldham Road, Middleton, Manchester, Lancashire, M24 1QZ Classification: Cutting Tools & Machinery **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	608	-	387009 405598
143	**Contemporary Trade Directory Entries** Name: Middleton Window Blinds Ltd Location: Unit 3-4, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Blinds, Awnings & Canopies **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	608	-	386997 405595
143	**Contemporary Trade Directory Entries** Name: E Wallbank Location: Unit 4, Central Industrial Estate, Oldham Road, Middleton, MANCHESTER, M24 1QZ Classification: Photographic Equipment & Supplies - Wholesale **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	612	-	386991 405588
143	**Contemporary Trade Directory Entries** Name: Coolair J J Plunkett Ltd Location: Unit 5, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Air Conditioning Equipment & Systems **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	616	-	386983 405583
143	**Contemporary Trade Directory Entries** Name: Cool Logic Location: Unit 6, Middleton Trade Park, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Air Conditioning & Refrigeration Contractors **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	618	-	386975 405578
144	**Contemporary Trade Directory Entries** Name: Toptune Centre Location: Warwick Mill,Oldham Rd, Middleton, Manchester, Lancashire, M24 1AZ Classification: Garage Services **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A8NE (SE)	577	-	387110 405676
145	**Contemporary Trade Directory Entries** Name: Inferno Fireplaces Location: The Lodge, Oldham Road, Middleton, Manchester, M24 1AZ Classification: Fireplaces & Mantelpieces **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	582	-	387161 405702

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
146	**Contemporary Trade Directory Entries** Name: Access Cleaning Specialists Ltd Location: Access House, Hanson Street, Middleton, Manchester, M24 2HW Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	584	-	387407 406188
146	**Contemporary Trade Directory Entries** Name: Adhesive Developments Ltd Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Adhesives, Glues & Sealants **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14NW (E)	597	-	387421 406201
146	**Contemporary Trade Directory Entries** Name: Tp Tyre & Exhaust Ltd Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Mot Testing Centres **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14NW (E)	597	-	387421 406201
146	**Contemporary Trade Directory Entries** Name: A Oldham Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Slate & Slate Products **Status: Inactive** Positional Accuracy: Automatically positioned in the proximity of the address	A14NW (E)	597	-	387421 406201
146	**Contemporary Trade Directory Entries** Name: T P Tyres & Exhausts Ltd Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	599	-	387422 406233
146	**Contemporary Trade Directory Entries** Name: T P Tyres & Exhausts Ltd Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Garage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	599	-	387422 406232
146	**Contemporary Trade Directory Entries** Name: T P Tyre & Exhaust Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	599	-	387422 406233
146	**Contemporary Trade Directory Entries** Name: T P Tyre & Exhaust Location: John Lee Fold, Middleton, Manchester, M24 2LR Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (E)	599	-	387422 406233
147	**Contemporary Trade Directory Entries** Name: Central Tyre Location: Unit 11-12, Central Industrial Estate, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	595	-	386919 405590
147	**Contemporary Trade Directory Entries** Name: Middleton Shutters Location: Unit 14, Middleton Trade Park, Oldham Road, Middleton, Manchester, M24 1QZ Classification: Blinds, Awnings & Canopies **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	601	-	386907 405582
148	**Contemporary Trade Directory Entries** Name: F W H Windows Location: 29, Brassey Street, Middleton, Manchester, M24 6AU Classification: PVC-U Products - Manufacturers & Suppliers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NW (NE)	598	-	387377 406435

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
149	**Contemporary Trade Directory Entries** Name: Hanson Street M O T Centre Location: Unit 1 Hanson Street, Middleton, Manchester, Greater Manchester, M24 2YP Classification: Mot Testing Centres **Status: Active** Positional Accuracy: Manually positioned within the geographical locality	A14SW (E)	600	-	387413 406067
150	**Contemporary Trade Directory Entries** Name: Mcbride Location: Middleton Way, Middleton, Manchester, M24 4DP Classification: Chemical Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NW (S)	601	-	386694 405586
151	**Contemporary Trade Directory Entries** Name: Carp Kabin Location: 135, Oldham Road, Middleton, Manchester, Lancashire, M24 2LD Classification: Fishing & Angling Equipment - Manufacturers & Distributors **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A14SW (SE)	622	-	387363 405867
151	**Contemporary Trade Directory Entries** Name: C B R Accessories Location: 145, Oldham Road, Middleton, Manchester, M24 2LD Classification: Radio Communication Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	639	-	387387 405876
151	**Contemporary Trade Directory Entries** Name: Premier Clean (Uk) Location: 149, Oldham Road, Middleton, Manchester, M24 2LD Classification: Cleaning Services - Commercial **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	646	-	387399 405882
151	**Contemporary Trade Directory Entries** Name: Billington Bros Location: 151, Oldham Road, Middleton, Manchester, M24 2LD Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	652	-	387410 405892
151	**Contemporary Trade Directory Entries** Name: Middleton M O T Centre Ltd Location: 151, Oldham Road, Middleton, Manchester, M24 2LD Classification: Mot Testing Centres **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	652	-	387410 405892
152	**Contemporary Trade Directory Entries** Name: Absolute Zero 273 Ltd Location: 62, Towncroft Avenue, Middleton, Manchester, M24 5DB Classification: Refrigerators & Freezers - Servicing & Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18SW (N)	637	-	386787 406844
153	**Contemporary Trade Directory Entries** Name: Viridor Greater Manchester Ltd Location: Spring Vale, Middleton, Manchester, M24 2HR Classification: Waste Disposal Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	642	-	387418 405936
153	**Contemporary Trade Directory Entries** Name: Tyred & Exhausted Location: Spring Vale, Middleton, Manchester, Lancashire, M24 2HQ Classification: Garage Services **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SW (E)	653	-	387444 405972
154	**Contemporary Trade Directory Entries** Name: Adhesive Developments Ltd Location: Unit 4, John Lee Fold Warehouse, John Lee Fold, Middleton, Manchester, M24 2LR Classification: Adhesives, Glues & Sealants **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NW (E)	642	-	387466 406204

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
154	**Contemporary Trade Directory Entries** Name: Wilson Potter Brewery Location: Unit E2, Hanson Park, Hanson Close, Middleton, Manchester, M24 2QZ Classification: Brewers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	644	-	387468 406178
154	**Contemporary Trade Directory Entries** Name: M S E Services Ltd Location: Unit E2 Hanson Park,Hanson Close, Middleton, Manchester, Greater Manchester, M24 2QZ Classification: Mechanical Engineers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (E)	647	-	387471 406174
154	**Contemporary Trade Directory Entries** Name: Towermatch Ltd Location: 1, Hanson Close, Middleton, Manchester, M24 2HD Classification: Furniture Manufacturers - Home & Office **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	672	-	387495 406187
154	**Contemporary Trade Directory Entries** Name: Multiplier (Uk) Ltd Location: Unit 2, Hanson Park, Hanson Close, Middleton, MANCHESTER, M24 2QZ Classification: Radio Communication Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	678	-	387501 406190
154	**Contemporary Trade Directory Entries** Name: M D Logic Ltd Location: 10, Hanson Close, Middleton, Manchester, Lancashire, M24 2HD Classification: Road Haulage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	681	-	387505 406185
154	**Contemporary Trade Directory Entries** Name: A T L Transformers Location: Hanson Close, Middleton, Manchester, M24 2HD Classification: Transformer Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SE (E)	684	-	387508 406188
154	**Contemporary Trade Directory Entries** Name: Presslith Technical Services Location: 4, Hanson Close, Middleton, Manchester, M24 2HD Classification: Printing Engineering Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	684	-	387507 406197
154	**Contemporary Trade Directory Entries** Name: D Saville Location: Hanson Cl, Middleton, Manchester, Lancashire, M24 2HD Classification: Garage Services **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	689	-	387512 406146
154	**Contemporary Trade Directory Entries** Name: Flirmask Location: Hanson Cl, Middleton, Manchester, Lancashire, M24 2HD Classification: Manufacturers **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A14NE (E)	692	-	387516 406195
154	**Contemporary Trade Directory Entries** Name: Dps Remedials Location: 7-8, Hanson Close, Middleton, Manchester, M24 2HD Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	694	-	387518 406206
154	**Contemporary Trade Directory Entries** Name: Middleton Engineering Services Location: 16, Hanson Close, Middleton, Manchester, M24 2HD Classification: Engineering Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	701	-	387525 406170

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
154	**Contemporary Trade Directory Entries** Name: Bmu Cosmetics Location: 17, Hanson Close, Middleton, Manchester, M24 2HD Classification: Cosmetic Manufacturers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	703	-	387527 406175
154	**Contemporary Trade Directory Entries** Name: C P Covers Ltd Location: 18, Hanson Close, Middleton, Manchester, M24 2HD Classification: Firefighting Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	705	-	387529 406179
154	**Contemporary Trade Directory Entries** Name: Copier Logistics Location: 19, Hanson Close, Middleton, Manchester, Lancashire, M24 2HD Classification: Photocopiers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	709	-	387532 406184
154	**Contemporary Trade Directory Entries** Name: Hill Farm Forge Location: 20, Hanson Close, Middleton, Manchester, Lancashire, M24 2HD Classification: Wrought Ironwork **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	711	-	387534 406188
154	**Contemporary Trade Directory Entries** Name: Duster Buster Location: 21, Hanson Close, Middleton, Manchester, M24 2HD Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	713	-	387537 406192
154	**Contemporary Trade Directory Entries** Name: T & B Precision Ltd Location: Hanson Close, Middleton, Manchester, M24 2HD Classification: Precision Engineers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	732	-	387556 406190
154	**Contemporary Trade Directory Entries** Name: T J Guinan (Builders Merchants) Ltd Location: Hanson Close, Middleton, Manchester, M24 2HD Classification: Builders' Merchants **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	732	-	387556 406190
154	**Contemporary Trade Directory Entries** Name: T J Guinan (Plumbers Merchants) Ltd Location: Hanson Close, Middleton, Manchester, M24 2HD Classification: Builders' Merchants **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	732	-	387556 406190
154	**Contemporary Trade Directory Entries** Name: T J Guinan Location: Hanson Close, Middleton, Manchester, Lancashire, M24 2HD Classification: Builders' Merchants **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	732	-	387556 406190
154	**Contemporary Trade Directory Entries** Name: Saville Motors Location: Hanson Close, Middleton, Manchester, M24 2HD Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	732	-	387556 406190
155	**Contemporary Trade Directory Entries** Name: Church Street Motors Location: Church Street, Middleton, Manchester, M24 2PY Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	657	-	387193 406752
155	**Contemporary Trade Directory Entries** Name: Xpress Tyres Location: Unit 4, Church Street Industrial Estate, Middleton, Manchester, M24 2GY Classification: Tyre Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	658	-	387193 406752

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
155	**Contemporary Trade Directory Entries** Name: Middleton M O T Centre Location: 86, Rochdale Road, Middleton, Manchester, Lancashire, M24 2QA Classification: Mot Testing Centres **Status: Active** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	688	-	387176 406798
156	**Contemporary Trade Directory Entries** Name: B P Service Station Location: Manchester New Road, Middleton, Manchester, M24 1DE Classification: Petrol Filling Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8NE (S)	659	-	386898 405523
156	**Contemporary Trade Directory Entries** Name: B P Service Station Location: Manchester New Road, Middleton, Manchester, M24 1DE Classification: Petrol Filling Stations **Status: Active** Positional Accuracy: Automatically positioned to the address	A8NE (S)	659	-	386898 405523
157	**Contemporary Trade Directory Entries** Name: P N Docksey Location: 6, Kinder Way, Middleton, Manchester, M24 5DE Classification: Dairies **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18NE (N)	669	-	386877 406874
158	**Contemporary Trade Directory Entries** Name: Celect Tools Location: Unit F1, Hanson Park, Hanson Close, Middleton, MANCHESTER, M24 2QZ Classification: Tool Design, Manufacturers & Makers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SE (E)	675	-	387498 406139
159	**Contemporary Trade Directory Entries** Name: Boots Pharmacy Location: 133-137 Manchester Old Rd, Middleton, Manchester, Lancashire, M24 4DZ Classification: Chemists' & Pharmacists' Suppliers & Wholesalers **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A7NE (SW)	691	-	386437 405589
160	**Contemporary Trade Directory Entries** Name: Mr Hygenic Location: 62, Mill Fold Road, Middleton, Manchester, M24 1DF Classification: Commercial Cleaning Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	701	-	387167 405566
160	**Contemporary Trade Directory Entries** Name: Mr Hygenic Location: 62, Mill Fold Road, Middleton, Manchester, M24 1DF Classification: Carpet, Curtain & Upholstery Cleaners **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	702	-	387167 405565
160	**Contemporary Trade Directory Entries** Name: Mr Hygenic Location: 62, Mill Fold Road, Middleton, Manchester, M24 1DF Classification: Carpet, Curtain & Upholstery Cleaners **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	702	-	387167 405565
161	**Contemporary Trade Directory Entries** Name: B P Service Station Location: Oldham Road, Middleton, Manchester, M24 2LD Classification: Petrol Filling Stations **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SW (SE)	702	-	387475 405914
161	**Contemporary Trade Directory Entries** Name: Mercury Petrol Station Location: 191 Oldham Road, Middleton, Manchester, Greater Manchester, M24 2LD Classification: Petrol Filling Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	712	-	387486 405915
161	**Contemporary Trade Directory Entries** Name: Middleton Service Station Location: 191, Oldham Road, Middleton, Manchester, M24 2LD Classification: Petrol Filling Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SW (E)	712	-	387486 405915

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
162	**Contemporary Trade Directory Entries** Name: M S R Furniture & Beds Location: Geometric House, Townley Street, Middleton, Manchester, M24 1AT Classification: Furniture Manufacturers - Home & Office **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A9NW (SE)	721	-	387444 405809
163	**Contemporary Trade Directory Entries** Name: Mpm Consumer Products Location: 43, West Street, Middleton, Manchester, M24 6BE Classification: Cleaning Materials & Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	722	-	387367 406683
164	**Contemporary Trade Directory Entries** Name: White Hart Motors Location: 2, White Hart Meadow, Middleton, Manchester, Lancashire, M24 2GA Classification: Garage Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	730	-	387280 406778
164	**Contemporary Trade Directory Entries** Name: Idm Autoservices Location: Fielding Mill ,Brown St, Middleton, Manchester, M24 2PZ Classification: Garage Services **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A19SW (NE)	730	-	387279 406778
165	**Contemporary Trade Directory Entries** Name: Firehalt Ltd Location: Hanson Close, Middleton, Manchester, M24 2HD Classification: Firefighting Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	736	-	387560 406194
165	**Contemporary Trade Directory Entries** Name: Mckenna Location: Jubilee Road, Middleton, Manchester, M24 2LX Classification: Screen Process Printers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	738	-	387561 406231
165	**Contemporary Trade Directory Entries** Name: Elevated Engineering Services Ltd Location: Unit E, Jubilee Park, Hanson Close, Middleton, Manchester, M24 2UH Classification: Electric Motor Sales & Service **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	772	-	387596 406216
166	**Contemporary Trade Directory Entries** Name: M P H Prestige Ltd Location: Radclyffe Court, 96, Rochdale Road, Middleton, Manchester, M24 2QA Classification: Garage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	750	-	387234 406836
166	**Contemporary Trade Directory Entries** Name: M & S Car Sales Location: 96-100, Rochdale Road, Middleton, Manchester, M24 2QA Classification: Car Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	758	-	387237 406843
166	**Contemporary Trade Directory Entries** Name: M & S Car Sales Location: 96-100, Rochdale Road, Middleton, Manchester, M24 2QA Classification: Car Dealers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	758	-	387237 406843
167	**Contemporary Trade Directory Entries** Name: Middleton Sheet Metal Co Ltd Location: Spring Vale, Middleton, Manchester, Lancashire, M24 2HS Classification: Sheet Metal Work **Status: Active** Positional Accuracy: Automatically positioned to the address	A14SE (E)	761	-	387569 406022
167	**Contemporary Trade Directory Entries** Name: North West Metal Recyclers Ltd Location: Unit 9 Spring Vale, Middleton, Manchester, M24 2HS Classification: Scrap Metal Merchants **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A14SE (E)	762	-	387567 406010

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
168	**Contemporary Trade Directory Entries** Name: Central Transport Location: 29, Jubilee Road, Middleton, Manchester, M24 2LT Classification: Crane Hire, Sales & Service **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14NE (E)	765	-	387582 406308
168	**Contemporary Trade Directory Entries** Name: Bollard & Ward Location: Jubilee Road, Middleton, Manchester, M24 2LX Classification: Garage Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NE (E)	784	-	387605 406278
168	**Contemporary Trade Directory Entries** Name: Metcraft Lighting Location: Unit B, Jubilee Park, Hanson Close, Middleton, MANCHESTER, M24 2UH Classification: Lighting Manufacturers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NE (E)	784	-	387605 406278
168	**Contemporary Trade Directory Entries** Name: Car Dip Uk Ltd Location: Unit A, Jubilee Park, Hanson Close, Middleton, Manchester, M24 2UH Classification: Car Paint & Lacquer Manufacturers & Suppliers **Status: Active** Positional Accuracy: Automatically positioned to the address	A14NE (E)	790	-	387611 406274
169	**Contemporary Trade Directory Entries** Name: T & D Location: 165, Manchester Old Road, Middleton, Manchester, M24 4DZ Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	778	-	386370 405529
170	**Contemporary Trade Directory Entries** Name: Pictorial Design Location: 72, Hollin Lane, Middleton, Manchester, M24 5EF Classification: Stained Glass Designers & Producers **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A18NE (N)	787	-	386995 406976
171	**Contemporary Trade Directory Entries** Name: Chubb Fire Ltd Location: Parkfield House, Manchester Old Road, Middleton, Manchester, M24 4DY Classification: Firefighting Equipment **Status: Active** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	825	-	386247 405565
171	**Contemporary Trade Directory Entries** Name: Chubb Location: Parkfield House, Manchester Old Road, Middleton, Manchester, M24 4DY Classification: Firefighting Equipment **Status: Active** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	825	-	386247 405565
171	**Contemporary Trade Directory Entries** Name: Chubb Fire Ltd Location: Parkfield House, Manchester Old Road, Middleton, Manchester, M24 4DY Classification: Firefighting Equipment **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7NE (SW)	825	-	386247 405565
171	**Contemporary Trade Directory Entries** Name: T G Products Location: Parkfield House,Manchester Old Road, Middleton, Manchester, Greater Manchester, M24 4RF Classification: Firefighting Equipment **Status: Active** Positional Accuracy: Manually positioned to the address or location	A7NE (SW)	828	-	386252 405557
172	**Contemporary Trade Directory Entries** Name: A & J Discount Fencing Location: Clough Rd, Middleton, Manchester, M24 2NQ Classification: Fencing Manufacturers **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A19SW (NE)	836	-	387446 406766

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
172	**Contemporary Trade Directory Entries** Name: Junction 19 Location: Clough Rd, Middleton, Manchester, M24 2NQ Classification: Car Dealers - Used **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A19SE (NE)	850	-	387487 406739
173	**Contemporary Trade Directory Entries** Name: Clough Road M O T Centre Location: Middleton, M24 2QW Classification: Mot Testing Centres **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19NW (NE)	855	-	387364 406870
174	**Contemporary Trade Directory Entries** Name: Perfect Paint Motor Bodies Location: 5 Clough Rd, Middleton, Manchester, Lancashire, M24 2NQ Classification: Car Body Repairs **Status: Inactive** Positional Accuracy: Manually positioned to the road within the address or location	A19SE (NE)	859	-	387510 406724
175	**Contemporary Trade Directory Entries** Name: Falcon Damp Proofing & Builders Location: 14, Hembury Close, Middleton, Manchester, M24 2SX Classification: Damp & Dry Rot Control **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19SE (NE)	860	-	387619 406535
176	**Contemporary Trade Directory Entries** Name: Premier Car Centre Location: Clough Rd, Middleton, Manchester, Lancashire, M24 2NQ Classification: Car Dealers - Used **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	866	-	387339 406904
176	**Contemporary Trade Directory Entries** Name: Premier Car Centre Location: Clough Road, Middleton, Manchester, Greater Manchester, M24 2NQ Classification: Car Dealers - Used **Status: Active** Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	866	-	387339 406904
176	**Contemporary Trade Directory Entries** Name: Charlesworth Timber & Door Warehouse Location: 190 - 194 Rochdale Rd, Middleton, Manchester, Lancashire, M24 2QA Classification: Door Manufacturers - Domestic **Status: Inactive** Positional Accuracy: Manually positioned to the address or location	A19NW (NE)	897	-	387348 406936
176	**Contemporary Trade Directory Entries** Name: Minster Cleaning Services Location: 190, Rochdale Road, Middleton, Manchester, M24 2QA Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19NW (NE)	897	-	387350 406933
176	**Contemporary Trade Directory Entries** Name: Charlesworth Timber & Door Warehouse Location: 190, Rochdale Road, Middleton, Manchester, M24 2QA Classification: Door Manufacturers - Domestic **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A19NW (NE)	897	-	387350 406933
176	**Contemporary Trade Directory Entries** Name: K O M 24hr Recovery Breakdown Location: 190, Rochdale Road, Middleton, Manchester, M24 2QA Classification: Car Breakdown & Recovery Services **Status: Active** Positional Accuracy: Automatically positioned to the address	A19NW (NE)	897	-	387350 406933
177	**Contemporary Trade Directory Entries** Name: Autos North West Location: Unit 1, Boarshaw Road, Middleton, M24 2WH Classification: Car Dealers - Used **Status: Active** Positional Accuracy: Automatically positioned to the address	A19SE (NE)	870	-	387598 406604
178	**Contemporary Trade Directory Entries** Name: Carpet Cleaning Middleton Location: 12, Oak Avenue, Middleton, Manchester, M24 1DS Classification: Carpet, Curtain & Upholstery Cleaners **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8SE (S)	873	-	387145 405366

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
179	**Contemporary Trade Directory Entries** Name: Cleaners Middleton Location: 3, Lever Walk, Middleton, Manchester, M24 1DX Classification: Carpet, Curtain & Upholstery Cleaners **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A8SE (S)	903	-	386980 405288
180	**Contemporary Trade Directory Entries** Name: Heatech Location: 8, Limefield Cottages, Manchester Old Road, Middleton, Manchester, M24 4EA Classification: Boilers - Servicing, Replacements & Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7SE (SW)	940	-	386145 405503
180	**Contemporary Trade Directory Entries** Name: Middleton Service Station Location: Manchester Old Road, Middleton, Manchester, M24 4EB Classification: Petrol Filling Stations **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A7SW (SW)	965	-	386117 405496
181	**Contemporary Trade Directory Entries** Name: Big G Automotive Location: 11, High Barn Road, Middleton, Manchester, M24 1DT Classification: Garage Equipment **Status: Active** Positional Accuracy: Automatically positioned to the address	A8SE (S)	945	-	387093 405272
182	**Contemporary Trade Directory Entries** Name: Clean Getaway Location: 6, Hulbert Street, Middleton, Manchester, M24 2HY Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	950	-	387774 406186
183	**Contemporary Trade Directory Entries** Name: W G Finnigan & Son Location: 6, Esmont Drive, Middleton, Manchester, M24 5WL Classification: Washing Machines - Servicing & Repairs **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A17NE (NW)	959	-	386402 407081
183	**Contemporary Trade Directory Entries** Name: Clean Shine Home Improvements Location: 8, Burnside Crescent, Middleton, Manchester, M24 5WH Classification: Cleaning Services - Domestic **Status: Active** Positional Accuracy: Automatically positioned to the address	A17NE (NW)	978	-	386424 407111
183	**Contemporary Trade Directory Entries** Name: Hygrade Cleaning Contractors Location: 3, Esmont Drive, Middleton, Manchester, M24 5WL Classification: Commercial Cleaning Services **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A17NE (NW)	986	-	386356 407089
184	**Contemporary Trade Directory Entries** Name: Latex Foam Location: 45, Green Street, Middleton, Manchester, Lancashire, M24 2HU Classification: Foam Products - Rubber & Plastics **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	959	-	387781 406124
185	**Contemporary Trade Directory Entries** Name: Dave Stott Location: Cromer Ind Est,Hilton Fold La, Middleton, Manchester, Lancashire, M24 2LE Classification: Garage Services **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A14NE (E)	966	-	387780 406342
185	**Contemporary Trade Directory Entries** Name: I E S Workshop Services Ltd Location: Unit 27 Cromer Indust Est,Hilton Fold La, Middleton, Manchester, M24 2LE Classification: Gear Cutters **Status: Inactive** Positional Accuracy: Manually positioned within the geographical locality	A14NE (E)	969	-	387784 406340

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
186	**Contemporary Trade Directory Entries** Name: Alternative Heat Solutions Location: 236-240, Oldham Road, Middleton, Manchester, M24 2DP Classification: Heating Services - Industrial and Commercial **Status: Inactive** Positional Accuracy: Automatically positioned to the address	A14SE (E)	974	-	387779 405985
187	**Fuel Station Entries** Name: Tesco Middleton Extra Location: Barton Road , Middleton , Manchester, Greater Manchester, M24 1HB Brand: Tesco Extra Premises Type: Hypermarket **Status: Open** Positional Accuracy: Manually positioned to the address or location	A8NE (SE)	508	-	387026 405711
188	**Fuel Station Entries** Name: Alkrington Service Station Location: Manchester New Road , Middleton , Manchester, Greater Manchester, M24 1DE Brand: Low Prices Always Premises Type: Petrol Station **Status: Open** Positional Accuracy: Manually positioned to the address or location	A8NE (S)	659	-	386900 405523
189	**Fuel Station Entries** Name: Mfg Middleton Location: 191, Oldham Road , Middleton , Manchester, Greater Manchester, M24 2LD Brand: Bp Premises Type: Petrol Station **Status: Open** Positional Accuracy: Manually positioned to the address or location	A14SW (SE)	703	-	387476 405915
190	**Fuel Station Entries** Name: Middleton Service Station Location: 96, Rochdale Road , Middleton , Manchester, Greater Manchester, M24 2QA Brand: Obsolete Premises Type: Not Applicable **Status: Obsolete** Positional Accuracy: Automatically positioned to the address	A19SW (NE)	758	-	387237 406843
191	**Fuel Station Entries** Name: Rhodes Service Station Location: Manchester Old Road , Middleton , Manchester, Greater Manchester, M24 4EB Brand: Total Premises Type: Not Applicable **Status: Obsolete** Positional Accuracy: Located by supplier to within 100m	A7SE (SW)	929	-	386202 405467

Sensitive Land Use

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
192	**Local Nature Reserves** Name: Alkrington Woods Multiple Area: N Area (m2): 493961.02 Source: Natural England Designation Date: 1st January 1987	A8NE (S)	607	9	386851 405571
193	**Nitrate Vulnerable Zones** Name: River Irk (Moston Brook To River Irwell) Nvz Description: Surface Water Source: Environment Agency, Head Office	A13SE (SE)	0	4	386812 406192

Agency & Hydrological	Version	Update Cycle
Contaminated Land Register Entries and Notices		
Environment Agency - Head Office	June 2020	Annually
Salford City Council - Environmental Health Department	November 2013	Annual Rolling Update
Bury Metropolitan Borough Council - Environmental Health Department	October 2013	Annual Rolling Update
Rochdale Metropolitan Borough Council - Environmental Health Department	October 2017	Annually
Oldham Metropolitan Borough Council - Environmental Health Department	September 2013	Annual Rolling Update
Manchester City Council - Environmental Health Department	September 2014	Annual Rolling Update
Discharge Consents		
Environment Agency - North West Region	July 2020	Quarterly
Enforcement and Prohibition Notices		
Environment Agency - North West Region	March 2013	Annual Rolling Update
Integrated Pollution Controls		
Environment Agency - North West Region	October 2008	Variable
Integrated Pollution Prevention And Control		
Environment Agency - North West Region	July 2020	Quarterly
Local Authority Integrated Pollution Prevention And Control		
Bury Metropolitan Borough Council - Environmental Health Department	February 2015	Variable
Rochdale Metropolitan Borough Council - Environmental Health Department	July 2014	Variable
Oldham Metropolitan Borough Council - Environmental Health Department	March 2015	Variable
Salford City Council - Environmental Health Department	March 2015	Variable
Manchester City Council - Environmental Health Department	September 2014	Variable
Local Authority Pollution Prevention and Controls		
Bury Metropolitan Borough Council - Environmental Health Department	February 2015	Not Applicable
Rochdale Metropolitan Borough Council - Environmental Health Department	July 2014	Annual Rolling Update
Oldham Metropolitan Borough Council - Environmental Health Department	March 2015	Annual Rolling Update
Salford City Council - Environmental Health Department	March 2015	Annual Rolling Update
Manchester City Council - Environmental Health Department	September 2014	Annual Rolling Update
Local Authority Pollution Prevention and Control Enforcements		
Bury Metropolitan Borough Council - Environmental Health Department	February 2015	Variable
Rochdale Metropolitan Borough Council - Environmental Health Department	July 2014	Variable
Salford City Council - Environmental Health Department	March 2015	Variable
Oldham Metropolitan Borough Council - Environmental Health Department	September 2013	Variable
Manchester City Council - Environmental Health Department	September 2014	Variable
Nearest Surface Water Feature		
Ordnance Survey	August 2020	
Pollution Incidents to Controlled Waters		
Environment Agency - North West Region	January 2000	Not Applicable
Prosecutions Relating to Authorised Processes		
Environment Agency - North West Region	March 2013	Annual Rolling Update
Prosecutions Relating to Controlled Waters		
Environment Agency - North West Region	March 2013	Annual Rolling Update
Registered Radioactive Substances		
Environment Agency - North West Region	June 2016	
River Quality		
Environment Agency - Head Office	November 2001	Not Applicable
River Quality Biology Sampling Points		
Environment Agency - Head Office	July 2012	Annually
River Quality Chemistry Sampling Points		
Environment Agency - Head Office	July 2012	Annually
Substantiated Pollution Incident Register		
Environment Agency - North West Region - South Area	July 2020	Quarterly

Data Currency

Agency & Hydrological	Version	Update Cycle
Water Abstractions Environment Agency - North West Region	July 2020	Quarterly
Water Industry Act Referrals Environment Agency - North West Region	October 2017	Quarterly
Groundwater Vulnerability Map Environment Agency - Head Office	June 2018	As notified
Bedrock Aquifer Designations Environment Agency - Head Office	January 2018	Annually
Superficial Aquifer Designations Environment Agency - Head Office	January 2018	Annually
Source Protection Zones Environment Agency - Head Office	October 2019	Quarterly
Extreme Flooding from Rivers or Sea without Defences Environment Agency - Head Office	September 2020	Quarterly
Flooding from Rivers or Sea without Defences Environment Agency - Head Office	September 2020	Quarterly
Areas Benefiting from Flood Defences Environment Agency - Head Office	September 2020	Quarterly
Flood Water Storage Areas Environment Agency - Head Office	September 2020	Quarterly
Flood Defences Environment Agency - Head Office	September 2020	Quarterly
OS Water Network Lines Ordnance Survey	June 2020	Quarterly
BGS Groundwater Flooding Susceptibility British Geological Survey - National Geoscience Information Service	May 2013	Annually

Waste	Version	Update Cycle
BGS Recorded Landfill Sites		
British Geological Survey - National Geoscience Information Service	June 1996	Not Applicable
Historical Landfill Sites		
Environment Agency - Head Office	October 2019	Quarterly
Integrated Pollution Control Registered Waste Sites		
Environment Agency - North West Region	October 2008	Not Applicable
Licensed Waste Management Facilities (Landfill Boundaries)		
Environment Agency - North West Region - South Area	July 2020	Quarterly
Licensed Waste Management Facilities (Locations)		
Environment Agency - North West Region - South Area	July 2020	Quarterly
Local Authority Landfill Coverage		
Bury Metropolitan Borough Council	May 2000	Not Applicable
Manchester City Council - Planning Department	May 2000	Not Applicable
Oldham Metropolitan Borough Council	May 2000	Not Applicable
Rochdale Metropolitan Borough Council - Environmental Health Department	May 2000	Not Applicable
Salford City Council - Environmental Health Department	May 2000	Not Applicable
Local Authority Recorded Landfill Sites		
Bury Metropolitan Borough Council	May 2000	Not Applicable
Manchester City Council - Planning Department	May 2000	Not Applicable
Oldham Metropolitan Borough Council	May 2000	Not Applicable
Rochdale Metropolitan Borough Council - Environmental Health Department	May 2000	Not Applicable
Salford City Council - Environmental Health Department	May 2000	Not Applicable
Registered Landfill Sites		
Environment Agency - North West Region - South Area	March 2003	Not Applicable
Registered Waste Transfer Sites		
Environment Agency - North West Region - South Area	March 2003	Not Applicable
Registered Waste Treatment or Disposal Sites		
Environment Agency - North West Region - South Area	March 2003	Not Applicable
Hazardous Substances	**Version**	**Update Cycle**
Control of Major Accident Hazards Sites (COMAH)		
Health and Safety Executive	April 2018	Bi-Annually
Explosive Sites		
Health and Safety Executive	March 2017	Annually
Notification of Installations Handling Hazardous Substances (NIHHS)		
Health and Safety Executive	November 2000	Not Applicable
Planning Hazardous Substance Enforcements		
Bury Metropolitan Borough Council	February 2016	Variable
Manchester City Council - Planning Department	February 2016	Variable
Oldham Metropolitan Borough Council	February 2016	Variable
Rochdale Metropolitan Borough Council	February 2016	Variable
Salford City Council	June 2016	Variable
Planning Hazardous Substance Consents		
Bury Metropolitan Borough Council	February 2016	Variable
Manchester City Council - Planning Department	February 2016	Variable
Oldham Metropolitan Borough Council	February 2016	Variable
Rochdale Metropolitan Borough Council	February 2016	Variable
Salford City Council	June 2016	Variable

Geological	Version	Update Cycle
BGS 1:625,000 Solid Geology British Geological Survey - National Geoscience Information Service	January 2009	Not Applicable
BGS Recorded Mineral Sites British Geological Survey - National Geoscience Information Service	June 2020	Bi-Annually
CBSCB Compensation District Cheshire Brine Subsidence Compensation Board (CBSCB)	August 2011	Not Applicable
Coal Mining Affected Areas The Coal Authority - Property Searches	March 2014	Annual Rolling Update
Mining Instability Ove Arup & Partners	October 2000	Not Applicable
Non Coal Mining Areas of Great Britain British Geological Survey - National Geoscience Information Service	May 2015	Not Applicable
Potential for Collapsible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	April 2020	Annually
Potential for Compressible Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Ground Dissolution Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Landslide Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Running Sand Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Potential for Shrinking or Swelling Clay Ground Stability Hazards British Geological Survey - National Geoscience Information Service	January 2019	Annually
Radon Potential - Radon Affected Areas British Geological Survey - National Geoscience Information Service	July 2011	Annually
Radon Potential - Radon Protection Measures British Geological Survey - National Geoscience Information Service	July 2011	Annually
Industrial Land Use	**Version**	**Update Cycle**
Contemporary Trade Directory Entries Thomson Directories	July 2020	Quarterly
Fuel Station Entries Catalist Ltd - Experian	September 2020	Quarterly
Gas Pipelines National Grid	September 2020	
Underground Electrical Cables National Grid	August 2020	

Sensitive Land Use	Version	Update Cycle
Ancient Woodland		
Natural England	April 2020	Bi-Annually
Areas of Adopted Green Belt		
Bury Metropolitan Borough Council	June 2020	As notified
Manchester City Council	June 2020	As notified
Oldham Metropolitan Borough Council	June 2020	As notified
Rochdale Metropolitan Borough Council	June 2020	As notified
Salford City Council	June 2020	As notified
Areas of Unadopted Green Belt		
Bury Metropolitan Borough Council	June 2020	As notified
Manchester City Council	June 2020	As notified
Oldham Metropolitan Borough Council	June 2020	As notified
Rochdale Metropolitan Borough Council	June 2020	As notified
Salford City Council	June 2020	As notified
Areas of Outstanding Natural Beauty		
Natural England	June 2019	Bi-Annually
Environmentally Sensitive Areas		
Natural England	January 2017	
Forest Parks		
Forestry Commission	April 1997	Not Applicable
Local Nature Reserves		
Natural England	April 2020	Bi-Annually
Marine Nature Reserves		
Natural England	July 2019	Bi-Annually
National Nature Reserves		
Natural England	July 2019	Bi-Annually
National Parks		
Natural England	April 2017	Bi-Annually
Nitrate Sensitive Areas		
Natural England	April 2016	Not Applicable
Nitrate Vulnerable Zones		
Environment Agency - Head Office	December 2017	Bi-Annually
Department for Environment, Food and Rural Affairs (DEFRA - formerly FRCA)	October 2015	
Ramsar Sites		
Natural England	August 2020	Bi-Annually
Sites of Special Scientific Interest		
Natural England	May 2020	Bi-Annually
Special Areas of Conservation		
Natural England	July 2020	Bi-Annually
Special Protection Areas		
Natural England	September 2020	Bi-Annually

Data Suppliers


A selection of organisations who provide data within this report

Data Supplier	Data Supplier Logo
Ordnance Survey	
Environment Agency	
Scottish Environment Protection Agency	
The Coal Authority	
British Geological Survey	
Centre for Ecology and Hydrology	
Natural Resources Wales	
Scottish Natural Heritage	
Natural England	
Public Health England	
Ove Arup	
Stantec UK Ltd	

Useful Contacts

Contact	Name and Address	Contact Details
1	**British Geological Survey - Enquiry Service** British Geological Survey, Environmental Science Centre, Keyworth, Nottingham, Nottinghamshire, NG12 5GG	Telephone: 0115 936 3143 Fax: 0115 936 3276 Email: enquiries@bgs.ac.uk Website: www.bgs.ac.uk
2	**Environment Agency - National Customer Contact Centre (NCCC)** PO Box 544, Templeborough, Rotherham, S60 1BY	Telephone: 03708 506 506 Email: enquiries@environment-agency.gov.uk
3	**Rochdale Metropolitan Borough Council - Environmental Health Department** P O Box 32, Telegraph House, Ballie Street, Rochdale, Greater Manchester, OL16 1JH	Telephone: 01706 864139 Fax: 01706 864185 Website: www.rochdale.gov.uk
4	**Environment Agency - Head Office** Rio House, Waterside Drive, Aztec West, Almondsbury, Bristol, Avon, BS32 4UD	Telephone: 01454 624400 Fax: 01454 624409
5	**Ordnance Survey** Adanac Drive, Southampton, Hampshire, SO16 0AS	Telephone: 03456 05 05 05 Email: customerservices@ordnancesurvey.co.uk Website: www.ordnancesurvey.gov.uk
6	**Health and Safety Executive** 5S.2 Redgrave Court, Merton Road, Bootle, L20 7HS	Website: www.hse.gov.uk
7	**Rochdale Metropolitan Borough Council** Municipal Offices, Smith Street, Rochdale, Greater Manchester, OL16 1XG	Telephone: 01706 647474 Fax: 01706 59475 Website: www.rochdale.gov.uk
8	**The Coal Authority - Property Searches** 200 Lichfield Lane, Mansfield, Nottinghamshire, NG18 4RG	Telephone: 0345 762 6848 Fax: 01623 637 338 Email: groundstability@coal.gov.uk Website: www2.groundstability.com
9	**Natural England** County Hall, Spetchley Road, Worcester, WR5 2NP	Telephone: 0300 060 3900 Email: enquiries@naturalengland.org.uk Website: www.naturalengland.org.uk
10	**Rochdale Metropolitan Borough Council** PO Box 15, Town Hall, Rochdale, Greater Manchester, OL16 1AB	Telephone: 01706 647474 Fax: 01706 59475 Website: www.rochdale.gov.uk
11	**Oldham Metropolitan Borough Council** Civic Centre, P O Box 55, West Street, Oldham, Lancashire, OL1 1XN	Telephone: 0161 911 3000 Fax: 0161 678 4550 Website: www.oldham.gov.uk
-	**Public Health England - Radon Survey, Centre for Radiation, Chemical and Environmental Hazards** Chilton, Didcot, Oxfordshire, OX11 0RQ	Telephone: 01235 822622 Fax: 01235 833891 Email: radon@phe.gov.uk Website: www.ukradon.org
-	**Landmark Information Group Limited** Imperium, Imperial Way, Reading, Berkshire, RG2 0TD	Telephone: 0844 844 9952 Fax: 0844 844 9951 Email: customerservices@landmarkinfo.co.uk Website: www.landmarkinfo.co.uk

Please note that the Environment Agency / Natural Resources Wales / SEPA have a charging policy in place for enquiries.



©Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

Groundwater Vulnerability

General

Specified Site | Specified Buffer(s) | Bearing Reference Point | Slice | Map ID


Agency and Hydrological

Bedrock Aquifers	Superficial Aquifers
High Vulnerability, Principal Aquifer	High Vulnerability, Principal Aquifer
High Vulnerability, Secondary Aquifer	High Vulnerability, Secondary Aquifer
Medium Vulnerability, Principal Aquifer	Medium Vulnerability, Principal Aquifer
Medium Vulnerability, Secondary Aquifer	Medium Vulnerability, Secondary Aquifer
Low Vulnerability, Principal Aquifer	Low Vulnerability, Principal Aquifer
Low Vulnerability, Secondary Aquifer	Low Vulnerability, Secondary Aquifer

Unproductive Aquifer

Soluble Rock

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck

LANDMARK INFORMATION GROUP

Bedrock Aquifer Designation

General


Specified Site | Specified Buffer(s) | Bearing Reference Point | Slice | Map ID

Agency and Hydrological

Geological Classes

- Principal Aquifer
- Secondary A Aquifer
- Secondary B Aquifer
- Secondary Undifferentiated
- Unproductive Strata
- Unknown
- Unknown (Lakes and Landslip)

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck®

LANDMARK INFORMATION GROUP®

Superficial Aquifer Designation

General


Specified Site | Specified Buffer(s) | Bearing Reference Point | Slice | Map ID

Agency and Hydrological

Geological Classes

- Principal Aquifer
- Secondary A Aquifer
- Secondary B Aquifer
- Secondary Undifferentiated
- Unproductive Strata
- Unknown
- Unknown (Lakes and Landslip)

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck

LANDMARK INFORMATION GROUP

Sensitive Land Uses


General

Specified Site | Specified Buffer(s) | Bearing Reference Point
Slice | Map ID

Sensitive Land Uses

- Ancient Woodland
- Area of Adopted Green Belt
- Area of Unadopted Green Belt
- Area of Outstanding Natural Beauty
- Environmentally Sensitive Area
- Forest Park
- Local Nature Reserve
- Marine Nature Reserve
- National Nature Reserve
- National Park
- Nitrate Sensitive Area
- Nitrate Vulnerable Zone
- Ramsar Site
- Site of Special Scientific Interest
- Special Area of Conservation
- Special Protection Area
- World Heritage Sites

Site Sensitivity Context Map - Slice A




Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown Copyright. All Rights Reserved. License Number 100022432.

Envirocheck®

LANDMARK INFORMATION GROUP®

General

- Specified Site
- Specified Buffer(s)
- Bearing Reference Point
- Map ID
- Several of Type at Location

Agency and Hydrological

- Contaminated Land Register Entry or Notice (Location)
- Contaminated Land Register Entry or Notice
- Discharge Consent
- Enforcement or Prohibition Notice
- Integrated Pollution Control
- Integrated Pollution Prevention Control
- Local Authority Integrated Pollution Prevention and Control
- Local Authority Pollution Prevention and Control
- Local Authority Pollution Prevention and Control Enforcement
- Pollution Incident to Controlled Waters
- Prosecution Relating to Authorised Processes
- Prosecution Relating to Controlled Waters
- Registered Radioactive Substance
- River Network or Water Feature
- River Quality Sampling Point
- Substantiated Pollution Incident Register
- Water Abstraction
- Water Industry Act Referral

Geological

- BGS Recorded Mineral Site

Industrial Land Use

- Contemporary Trade Directory Entry
- Fuel Station Entry


Waste

- BGS Recorded Landfill Site (Location)
- BGS Recorded Landfill Site
- EA Historic Landfill (Buffered Point)
- EA Historic Landfill (Polygon)
- Integrated Pollution Control Registered Waste Site
- Licensed Waste Management Facility (Landfill Boundary)
- Licensed Waste Management Facility (Location)
- Local Authority Recorded Landfill Site (Location)
- Local Authority Recorded Landfill Site
- Registered Landfill Site
- Registered Landfill Site (Location)
- Registered Landfill Site (Point Buffered to 100m)
- Registered Landfill Site (Point Buffered to 250m)
- Registered Waste Transfer Site (Location)
- Registered Waste Transfer Site
- Registered Waste Treatment or Disposal Site (Location)
- Registered Waste Treatment or Disposal Site

Hazardous Substances

- COMAH Site
- Explosive Site
- NIHHS Site
- Planning Hazardous Substance Consent
- Planning Hazardous Substance Enforcement

Site Sensitivity Map - Slice A



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU


Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


385500
386000
386500
387000
387500
388000
407500
407000
406500
406000
405500
405000
A25
A20
A15
A10
A5
A1
A2
A3
A4
A5
Hollins
Stanycliffe
MIDDLETON
Lime Field
Kitchen Wood
Alkrington Wood
River Irk
Wince Brook
Education Facility
Medical Care
Library
Police Station
Bus Station
Sports/Leisure Centre
PO
PW
Library
Education Facility
Education Facility
Education Facility

Historical Mapping Legends

Ordnance Survey County Series and Ordnance Survey Plan 1:2,500



County Boundary (Geographical)

County & Civil Parish Boundary


Administrative County & Civil Parish Boundary

Co. Boro. Bdy. County Borough Boundary (England)

Co. Burgh Bdy. County Burgh Boundary (Scotland)

B P B S	Boundary Post or Stone	P.C.B	Police Call Box
B.R.	Bridle Road	P	Pump
E.P	Electricity Pylon	S.P	Signal Post
F.B.	Foot Bridge	St.	Sluice
F.P.	Foot Path	Sp.	Spring
G.P	Guide Post or Board	T.C.B	Telephone Call Box
M.S	Mile Stone	Tr.	Trough
M.P M.R	Mooring Post or Ring	W	Well

Ordnance Survey Plan, Additional SIMs and Supply of Unpublished Survey Information 1:2,500 and 1:1,250



County Boundary (Geographical)

County & Civil Parish Boundary

Civil Parish Boundary


Admin. County or County Bor. Boundary

L B Bdy London Borough Boundary

Symbol marking point where boundary mereing changes

BH	Beer House	P	Pillar, Pole or Post
BP, BS	Boundary Post or Stone	PO	Post Office
Cn, C	Capstan, Crane	PC	Public Convenience
Chy	Chimney	PH	Public House
D Fn	Drinking Fountain	Pp	Pump
El P	Electricity Pillar or Post	SB, S Br	Signal Box or Bridge
FAP	Fire Alarm Pillar	SP, SL	Signal Post or Light
FB	Foot Bridge	Spr	Spring
GP	Guide Post	Tk	Tank or Track
H	Hydrant or Hydraulic	TCB	Telephone Call Box
LC	Level Crossing	TCP	Telephone Call Post
MH	Manhole	Tr	Trough
MP	Mile Post or Mooring Post	Wr Pt, Wr T	Water Point, Water Tap
MS	Mile Stone	W	Well
NTL	Normal Tidal Limit	Wd Pp	Wind Pump

Large-Scale National Grid Data 1:2,500 and 1:1,250



Civil parish/community boundary

District boundary

County boundary

Boundary post/stone

Boundary mereing symbol (note: these always appear in opposed pairs or groups of three)


Bks	Barracks	P	Pillar, Pole or Post
Bty	Battery	PO	Post Office
Cemy	Cemetery	PC	Public Convenience
Chy	Chimney	Pp	Pump
Cis	Cistern	Ppg Sta	Pumping Station
Dismtd Rly	Dismantled Railway	PW	Place of Worship
El Gen Sta	Electricity Generating Station	Sewage Ppg Sta	Sewage Pumping Station
El P	Electricity Pole, Pillar	SB, S Br	Signal Box or Bridge
El Sub Sta	Electricity Sub Station	SP, SL	Signal Post or Light
FB	Filter Bed	Spr	Spring
Fn / D Fn	Fountain / Drinking Ftn.	Tk	Tank or Track
Gas Gov	Gas Valve Compound	Tr	Trough
GVC	Gas Governer	Wd Pp	Wind Pump
GP	Guide Post	Wr Pt, Wr T	Water Point, Water Tap
MH	Manhole	Wks	Works (building or area)
MP, MS	Mile Post or Mile Stone	W	Well

Envirocheck®
LANDMARK INFORMATION GROUP®

Historical Mapping & Photography included:

Mapping Type	Scale	Date	Pg
Lancashire And Furness	1:2,500	1893	2
Lancashire And Furness	1:2,500	1909	3
Lancashire And Furness	1:2,500	1922 - 1932	4
Ordnance Survey Plan	1:1,250	1954 - 1955	5
Ordnance Survey Plan	1:2,500	1955	6
Ordnance Survey Plan	1:1,250	1960 - 1978	7
Ordnance Survey Plan	1:2,500	1968	8
Ordnance Survey Plan	1:1,250	1968 - 1983	9
Additional SIMs	1:1,250	1978 - 1992	10
Additional SIMs	1:1,250	1983 - 1991	11
Large-Scale National Grid Data	1:1,250	1992	12
Large-Scale National Grid Data	1:1,250	1994	13
Large-Scale National Grid Data	1:1,250	1996	14

Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark® INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck

LANDMARK INFORMATION GROUP®


Lancashire And Furness

Published 1893


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®


Lancashire And Furness

Published 1909


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck®

LANDMARK INFORMATION GROUP®


Lancashire And Furness

Published 1922 - 1932


Source map scale - 1:2,500

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®


Ordnance Survey Plan

Published 1954 - 1955


Source map scale - 1:1,250

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

0 100 m

Envirocheck®

LANDMARK INFORMATION GROUP®


Ordnance Survey Plan

Published 1960 - 1978


Source map scale - 1:1,250

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck®

LANDMARK INFORMATION GROUP®

Ordnance Survey Plan

Published 1968 - 1983

Source map scale - 1:1,250

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas and by 1896 it covered the whole of what were considered to be the cultivated parts of Great Britain. The published date given below is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas.


Map Name(s) and Date(s)

SD8606NE 1968 1:1,250

SD8706NW 1970 1:1,250

SD8606SE 1983 1:1,250

Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100


Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


386600
386800
387000
406400
406200
406000
Playing Field
MELLALIEU STREET
Durnford High School
Tennis Courts
Durnford Junior High School
MIRFIELD DRIVE
EMERSON DRIVE
JUBILEE PARK
Bandstand
Boulder Stone
Flood
St John's Ambulance Hall
Health Centre
Library
Middleton Parish Church School
DURNFORD STREET
LONG STREET
Nursery
Exeter Court
GREY STREET
Long Street Methodist Church
Sunday School
Middleton Conservative Club
Bowling Green
Shelter
CEMETERY STREET
Ashworth Arms Hotel
Car Park
Public Baths
MARKET STREET
Chisholm Court
Albion Inn
Garage
Works
Parkfield
Parkfield County Primary School
Pavilion
Rowling Green
Recreation Ground
Reservoir
Rose Mill
Middleton Railway
Well (Site of)
Mound
Sandy Road
Rochdale Road
King Street
Union Street
Milton Street
Oldham Road
Manchester Road
Wood Street
Old Hall Street
Fountain Street
Corporation Street
Ashworth Way
Great Ancoats Way
Harley Road
Weavers Road
Trinity Street
Henry Street
Archer Park
Cross Street
Factory Street
Bent Lane
Scholars Way
Whitaker Street
Church Street
Queen Street
Victoria Street
Harrop Street
Cemetery Street
Market Place
Car Park
Old Road
Cinema
Fire Station
Monument
Aller. Gdns
Tennis Court
Bowling Green
Sub Sta
Fd
Pav
Ch
PH
Fire Sta
Cinema
Monument
Car Park
Public Baths
Albion Inn
Chisholm Court
Parkfield County Primary School
Middleton Conservative Club
Ashworth Arms Hotel
Middleton Parish Church School
Long Street Methodist Church
Sunday School
Rose Mill
Middleton Railway
Well (Site of)
Mound
Bandstand
Boulder Stone
Flood
Library
Health Centre
St John's Ambulance Hall
Nursery
Exeter Court
Tennis Courts
Durnford High School
Durnford Junior High School
Reservoir
Works
Garage



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®


Additional SIMs

Published 1983 - 1991


Source map scale - 1:1,250

The SIM cards (Ordnance Survey's `Survey of Information on Microfilm') are further, minor editions of mapping which were produced and published in between the main editions as an area was updated. They date from 1947 to 1994, and contain detailed information on buildings, roads and land-use. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®


Large-Scale National Grid Data

Published 1992


Source map scale - 1:1,250

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®
LANDMARK INFORMATION GROUP®


Large-Scale National Grid Data

Published 1996


Source map scale - 1:1,250

'Large Scale National Grid Data' superseded SIM cards (Ordnance Survey's 'Survey of Information on Microfilm') in 1992, and continued to be produced until 1999. These maps were the fore-runners of digital mapping and so provide detailed information on houses and roads, but tend to show less topographic features such as vegetation. These maps were produced at both 1:2,500 and 1:1,250 scales.

Map Name(s) and Date(s)



Historical Map - Segment A13



Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	100

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

Historical Mapping Legends

Ordnance Survey County Series 1:10,560

Gravel Pit
Sand Pit
Other Pits
Quarry
Shingle
Orchard
Osiers
Reeds
Marsh
Mixed Wood
Deciduous
Brushwood
Fir
Furze
Rough Pasture
Arrow denotes flow of water
Trigonometrical Station
Site of Antiquities
Bench Mark
Pump, Guide Post, Signal Post
Well, Spring, Boundary Post
·285 Surface Level
Sketched Contour
Instrumental Contour
Main Roads
Fenced
Un-Fenced
Minor Roads
Fenced
Un-Fenced
Sunken Road
Raised Road
Road over Railway
Railway over River
Railway over Road
Level Crossing
Road over River or Canal
Road over Stream
Road over Stream
County Boundary (Geographical)
County & Civil Parish Boundary
Administrative County & Civil Parish Boundary
Co. Boro. Bdy. County Borough Boundary (England)
Co. Burgh Bdy. County Burgh Boundary (Scotland)
R.D. Bdy. Rural District Boundary
Civil Parish Boundary

Ordnance Survey Plan 1:10,000

Chalk Pit, Clay Pit or Quarry
Gravel Pit
Sand Pit
Disused Pit or Quarry
Refuse or Slag Heap
Lake, Loch or Pond
Dunes
Boulders
Coniferous Trees
Non-Coniferous Trees
Orchard
Scrub
Coppice
Bracken
Heath
Rough Grassland
Marsh
Reeds
Saltings
Building
Direction of Flow of Water
Shingle
Sand
Glasshouse
Pylon
Electricity Transmission Line
Pole
Sloping Masonry
Cutting
Embankment
Standard Gauge Multiple Track
Road Under
Road Over
Level Crossing
Foot Bridge
Standard Gauge Single Track
Siding, Tramway or Mineral Line
Narrow Gauge
Geographical County
Administrative County, County Borough or County of City
Municipal Borough, Urban or Rural District, Burgh or District Council
Borough, Burgh or County Constituency
Shown only when not coincident with other boundaries
Civil Parish
Shown alternately when coincidence of boundaries occurs

BP, BS	Boundary Post or Stone	Pol Sta	Police Station
Ch	Church	PO	Post Office
CH	Club House	PC	Public Convenience
F E Sta	Fire Engine Station	PH	Public House
FB	Foot Bridge	SB	Signal Box
Fn	Fountain	Spr	Spring
GP	Guide Post	TCB	Telephone Call Box
MP	Mile Post	TCP	Telephone Call Post
MS	Mile Stone	W	Well

1:10,000 Raster Mapping


Gravel Pit
Refuse tip or slag heap
Rock
Rock (scattered)
Boulders
Boulders (scattered)
Shingle
Mud
Sand
Sand Pit
Slopes
Top of cliff
General detail
Underground detail
Overhead detail
Narrow gauge railway
Multi-track railway
Single track railway
County boundary (England only)
Civil, parish or community boundary
District, Unitary, Metropolitan, London Borough boundary
Constituency boundary
Area of wooded vegetation
Non-coniferous trees
Non-coniferous trees (scattered)
Coniferous trees
Coniferous trees (scattered)
Positioned tree
Orchard
Coppice or Osiers
Rough Grassland
Heath
Scrub
Marsh, Salt Marsh or Reeds
Water feature
Flow arrows
MHW(S) Mean high water (springs)
MLW(S) Mean low water (springs)
Telephone line (where shown)
Electricity transmission line (with poles)
BM 123.45 m Bench mark (where shown)
Triangulation station
Point feature (e.g. Guide Post or Mile Stone)
Pylon, flare stack or lighting tower
Site of (antiquity)
Glasshouse
General Building
Important Building

Envirocheck®
LANDMARK INFORMATION GROUP®

Historical Mapping & Photography included:

Mapping Type	Scale	Date	Pg
Lancashire And Furness	1:10,560	1848	2
Lancashire And Furness	1:10,560	1894	3
Lancashire And Furness	1:10,560	1910	4
Lancashire And Furness	1:10,560	1923	5
Lancashire And Furness	1:10,560	1932	6
Lancashire And Furness	1:10,560	1938	7
Ordnance Survey Plan	1:10,000	1956	8
Ordnance Survey Plan	1:10,000	1965 - 1966	9
Ordnance Survey Plan	1:10,000	1977 - 1978	10
Ordnance Survey Plan	1:10,000	1982 - 1984	11
Ordnance Survey Plan	1:10,000	1990	12
10K Raster Mapping	1:10,000	1999	13
Street View	Variable		14

Historical Map - Slice A




Order Details

Order Number: 262182483_1_1
Customer Ref: 2020/001
National Grid Reference: 386810, 406190
Slice: A
Site Area (Ha): 0.08
Search Buffer (m): 1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP
Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®


Lancashire And Furness

Published 1848


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)



Historical Map - Slice A



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



Envirocheck®

LANDMARK INFORMATION GROUP®

Lancashire And Furness

Published 1894


Source map scale - 1:10,560

The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

096NE
1894
1:10,560

Historical Map - Slice A



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000


Site Details


Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


385600
385800
386000
386200
386400
386600
386800
387000
387200
387400
387600
387800
388000
407400
407200
407000
406800
406600
406400
406200
406000
405800
405600
405400
405200
405000
MIDDLETON
WOOD SIDE
STANYCLIFFE
WHITE BROW
HIGHER BOARSHAW
MIDDLETON PARK
ALKRINGTON PARK
ALKRINGTON GARDEN VILLAGE
Alkrington Wood
Golf Course
Nut Cottage
Partington's Farm
Red Lion Inn
Sand Pit
Tree Stubs
Hebers House
Moiety Farm
Sazon Nook
Wood End Cottage
Cricket Ground
Pavilion
Glebe Farm
Allotment Gardens
Black Bull Inn
Reservoir
Reservoirs
Boarshaw Fold
Boarshaw Bleach Works
Football Ground
Recreation Ground
Phenix Bleach Works
Boarshaw Mill
Wood Side Farm
High Barn Farm
Wood Side Terrace
Wood Side Cottage
Grammar School
Church Army Mission Hall
Chronos Mill
John Lee Fold Farm
Hilton Fold Farm
Tram Depot
Stanycliffe Hall
South Stanycliffe
Stanycliffe Bridge
Higher Fold
Tone Hall
Football & Athletic Ground
Parkfield Works
Irlidale Bleach Wks
Lyndhurst
Rhodes House
Rhodes Ho.
Lever Bridge
Kitchen Wood
Alkrington Hall
Alkrington Cottage
Highbarns Farm
Ramsden Farm
Lancashire Fold
Round Thorn
Alkrington Mount
Hardfield Farm
Old Shaft
Boat Ho.
Reservoir
Sunny Brow
Beech House
Westdene
Dunraven
Aster Dene
Frayle's Dene
Old Sand Pit
Ash Cottage
Recreation Ground
Tanks
Dunsnae Farm
Langley Hall
U. M. Ch.
Rises
Hebers
Parkfield
Lime Field
Lane
Green
Weir
Pit
Spr.
Ch.
Sch.
Vic.
Vicarage
Dye Wks
Mill
Dyehouse
Spa Cottage
Stocks
Ho.
Hall
Tanks
Reservoirs
Reservoir
Boro. Bk.
Union
Old Sand Pit
Ledge
Wood
Rises
Old David's
Tram Depot
Hilton Fold Farm
John Lee Fold
Dye Wks
Townley Mill
Dyehouse
Vicarage
Dunraven
Westdene
Aster Dene
Sunny Brow
Beech House
Parkfield Works
Lyndhurst
Irlidale Bleach Wks


385600
385800
386000
386200
386400
386600
386800
387000
387200
387400
387600
387800
388000
407400
407200
407000
406800
406600
406400
406200
406000
405800
405600
405400
405200
405000
Langley Hall
Nut Cottage
Partington's Farm
TOP OF HEBERS
Red Lion Inn
Hebers
Hebers House
Two Shuts
Batty Farm
MIDDLETON
Saxon Nook
Wood End Cottage
Cricket Ground
Allotment Gardens
WOOD SIDE
Playing Field
High Barn Farm
Wood Side Farm
Wood Side Cottage
Demesne Farm
Cooper Fold
STANYCLIFFE
Stanycliffe Hall
South Stanycliffe
Stanycliffe Bridge
Higher Fold
White Brook
Glebe Farm
Reservoir
Boarshaw Farm
Boarshaw Mill
Cromer Mill
Cromer Dr.
Reservoir
Bradley Hall Recreation Ground
Milnrow Rd.
Tennyson Road
School
Jubilee Park
Middleton & Thornham Cemetery
John Lee Fold
Manchester Golf Course
Acker Dam
Sunny Brow
Recreation Ground
Frank's Dam
Ash Cottage
Rhodes Ho. (Golf Club)
Bleach Works
Reservoirs
Lower Bridge
Kitchen Wood
Alkrington Hall
Reservoir
Alkrington Wood
ALKRINGTON GARDEN VILLAGE
ALKRINGTON PARK
Pike Fold
Old Shaft
Round Thorn
Hard Meadow
Howdfield Farm
Old David's Farm
Conge Ball
Playing Field
Ramsden Farm
Stocks
Wingate Brook
Hall Ball
Dye Wks
Ch.
Sch.
Mill
Reservoirs
Allot. Gdns.
Rec. Ground
Pav.
Tennis Courts
Bowling Green
Pond
Quarry
Works
Club
Vic.
Meth. Ch.
Pub.
Rest.
Cott.
Farm
Hall
Ho.
Spr.
Stn.
Sta.
Yd.
Dr.
Rd.
St.
Ave.
Cres.
Pl.
Ct.
Gdns.
Terr.
Fm.
Cl.
Grn.
Ln.
Bk.
Br.
Wk.
Pk.
Cem.
Golf Course
Boro. Bdy.
F.P.
B.M. 480·46
B.M. 473·16
B.M. 458·07
B.M. 457·46
B.M. 413·26
B.M. 355·14
B.M. 355·90
B.M. 346·72
B.M. 332·4
B.M. 366·88
B.M. 308·42
B.M. 297·26
B.M. 358·49
B.M. 307·30
B.M. 290·66
B.M. 333·28
B.M. 335·34
B.M. 262·91
B.M. 262·00
B.M. 249·73
B.M. 245·93
B.M. 248·42
B.M. 239·36
B.M. 304·65
B.M. 295·66
B.M. 311·06
B.M. 328·80
B.M. 307·30
B.M. 313·66
B.M. 266·1
B.M. 285·10
B.M. 308·58
B.M. 328·87
B.M. 359·87
B.M. 339·87
B.M. 346·87
B.M. 343·87
B.M. 345·87
B.M. 355



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®

Ordnance Survey Plan

Published 1956

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SD80NE
1956
1:10,560

SD80SE
1956
1:10,560

Historical Map - Slice A



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®

Ordnance Survey Plan

Published 1977 - 1978

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SD80NE
1977
1:10,000

SD80SE
1978
1:10,000

Historical Map - Slice A



Order Details


Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk



© Crown copyright and Landmark Information Group Limited 2020. All Rights Reserved.

Envirocheck®

LANDMARK INFORMATION GROUP®

Ordnance Survey Plan

Published 1982 - 1984

Source map scale - 1:10,000


The historical maps shown were reproduced from maps predominantly held at the scale adopted for England, Wales and Scotland in the 1840`s. In 1854 the 1:2,500 scale was adopted for mapping urban areas; these maps were used to update the 1:10,560 maps. The published date given therefore is often some years later than the surveyed date. Before 1938, all OS maps were based on the Cassini Projection, with independent surveys of a single county or group of counties, giving rise to significant inaccuracies in outlying areas. In the late 1940`s, a Provisional Edition was produced, which updated the 1:10,560 mapping from a number of sources. The maps appear unfinished - with all military camps and other strategic sites removed. These maps were initially overprinted with the National Grid. In 1970, the first 1:10,000 maps were produced using the Transverse Mercator Projection. The revision process continued until recently, with new editions appearing every 10 years or so for urban areas.

Map Name(s) and Date(s)

SD80NE
1984
1:10,000

SD80SE
1982
1:10,000

Historical Map - Slice A



Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000


Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk


MIDDLETON
Hollins
Stanycliffe
Langley
Lime Field
Alkrington Wood
Pike Fold Golf Course
North Manchester Golf Course
John Lee Fold
Ramsden Farm
Industrial Estate
Playing Field
Cricket Ground
Burial Ground
Leisure Park
Rhodes House (Golf Club)
Lever Bridge
Kitchen Wood
Bird Sanctuary
Alkrington Hall
Civic Hall
Langley Childrens Project
Council Offices
Training Centre
Top of Hebers
Allotment Gardens
Parkfield House
Stanycliffe Bridge
Dismid Riv
Wince Brook
River Irk
Frank's Dam
Asker Dam
Cobler's Dam (disused)
Rochdale Canal
Middleton Way
Manchester Old Road
Oldham Road
Middleton Road
Rochdale Road
Milton Street
Queen Street
Wellington Street
Wood Street
Alexandra Road
Whitley Road
Waverley Road
Fenshore Road
Sherborne Road
Borrowdale Road
Clayworth Avenue
Mellalieu Street
Dubford Street
Grey Street
Pearl Bank
Mount Road
Kingsway
Penrhyn Avenue
Rhos Ave
Ruthin Avenue
Rookway
Alkrington Hall Road
Alkrington Green
Alkrington Close
Alkrington Drive
Alkrington Wood Drive
Alkrington Wood Walk
Mill Fold Road
Mill Street
Factory Street
Preston Street
Dale Street
Oldham Road
Hall Street
Wood Cottage
Depot
Works
Mill
Offices
Pol Sta
Bus Sta
Ind Est
Recn Gd
Pav
Sch
Hall
Liby
Wks
PO
Weir
Weirs
Reservoir
Reservoirs
Outfall
Sluices
Issues
Spreads
Collects
Drains
Sinks
Path
Track
FB
Rope Line
Allot Gdns
Mills
Club
Playing Field
Council Office
Langley School
Hollins School
Stanycliffe School
Alkrington Hall
Bus Sta
Pol Sta
Civic Hall
Parkfield House
Lever Bridge
Kitchen Wood
Alkrington Wood
Wood Cottage
Ramsden Farm



Envirocheck®

LANDMARK INFORMATION GROUP®

Street View


Published 2020

Source map scale - 1:10,000

Street View is a street-level map for the whole of Great Britain produced by the Ordnance Survey. These maps are provided at a nominal scale of 1:10,000

Map Name(s) and Date(s)

Street View Map - Slice A



Order Details

Order Number:	262182483_1_1
Customer Ref:	2020/001
National Grid Reference:	386810, 406190
Slice:	A
Site Area (Ha):	0.08
Search Buffer (m):	1000

Site Details

Former Citizens Advice Bureau, Milton Street, Middleton, M24 5TU

Landmark INFORMATION GROUP

Tel: 0844 844 9952
Fax: 0844 844 9951
Web: www.envirocheck.co.uk

APPENDIX D
RISK ASSESSMENT METHODOLOGY

CLR11 outlines the framework to be followed for risk assessment in the UK. The framework is designed to be consistent with UK legislation and policies including planning. Under CLR11, three stages of risk assessment exist: preliminary, generic quantitative and detailed quantitative. An outline conceptual model should be formed at the preliminary risk assessment stage that collates all the existing information pertaining to a site in text, tabular or diagrammatic form. The outline conceptual model identifies potentially complete (termed possible) pollutant linkages (contaminant–pathway–receptor) and is used as the basis for the design of the site investigation. The outline conceptual model is updated as further information becomes available, for example as a result of the site investigation.

Production of a conceptual model requires an assessment of risk to be made. Risk is a combination of the likelihood of an event occurring and the magnitude of its consequences. Therefore, both the likelihood and the consequences of an event must be taken into account when assessing risk. RSK has adopted guidance provided in CIRIA C552 for use in the production of conceptual models.

The likelihood of an event can be classified on a four-point system using the following terms and definitions based on CIRIA C552:

- highly likely: the event appears very likely in the short term and almost inevitable over the long term or there is evidence at the receptor of harm or pollution
- likely: it is probable that an event will occur or circumstances are such that the event is not inevitable, but possible in the short term and likely over the long term
- low likelihood: circumstances are possible under which an event could occur, but it is not certain even in the long term that an event would occur and it is less likely in the short term
- unlikely: circumstances are such that it is improbable the event would occur even in the long term.

The severity can be classified using a similar system also based on CIRIA C552. The terms and definitions relating to severity are:

- severe: short term (acute) risk to human health likely to result in ‘significant harm’ as defined by the Environment Protection Act 1990, Part IIA. Short-term risk of pollution of sensitive water resources. Catastrophic damage to buildings or property. Short-term risk to an ecosystem or organism forming part of that ecosystem (note definition of ecosystem in ‘Draft Circular on Contaminated Land’, DETR 2000)
- medium: chronic damage to human health (‘significant harm’ as defined in ‘Draft Circular on Contaminated Land’, DETR 2000), pollution of sensitive water resources, significant change in an ecosystem or organism forming part of that ecosystem

- mild: pollution of non-sensitive water resources. Significant damage to crops, buildings, structures and services ('significant harm' as defined in 'Draft Circular on Contaminated Land', DETR 2000). Damage to sensitive buildings, structures or the environment
- minor: harm, not necessarily significant, but that could result in financial loss or expenditure to resolve. Non-permanent human health effects easily prevented by use of personal protective clothing. Easily repairable damage to buildings, structures and services.

Once the probability of an event occurring and its consequences have been classified, a risk category can be assigned according to the table below.

		Consequences			
		Severe	**Medium**	**Mild**	**Minor**
Probability	**Highly likely**	Very high	High	Moderate	Moderate/low
	Likely	High	Moderate	Moderate/low	Low
	Low likelihood	Moderate	Moderate/low	Low	Very low
	Unlikely	Moderate/low	Low	Very low	Very low

Definitions of these risk categories are as follows together with an assessment of the further work that may be required:

- Very high: there is a high probability that severe harm could occur or there is evidence that severe harm is currently happening. This risk, if realised, could result in substantial liability; urgent investigation and remediation are likely to be required.
- High: harm is likely to occur. Realisation of the risk is likely to present a substantial liability. Urgent investigation is required. Remedial works may be necessary in the short term and are likely over the long term.
- Moderate: it is possible that harm could arise, but it is unlikely that the harm would be severe and it is more likely that the harm would be relatively mild. Investigation is normally required to clarify the risk and determine the liability. Some remedial works may be required in the longer term.
- Low: it is possible that harm could occur, but it is likely that if realised this harm would at worst normally be mild.
- Very low: there is a low possibility that harm could occur and if realised the harm is unlikely to be severe.