PLAN 1

4a - Beech tree -
on boundary between 5/7
Request - Remove lower
branches both sides of
fence.

5a Beech tree
on boundary between 5/7
Request - Remove lower
branches both sides
of fence



1a - Suppressed Beech tree
by 2a and 2 others
pine to its left.
on boundary between
7 & 9 Hillkirk Drive
Request REMOVAL

2a - Scots pine next to
1a very tall tree
overhanging boundary
7 & 9
Request trim right hand
branches

3a Beech tree - right union
Request - remove lower
branches to reduce
weight.

Photo 1 - 7 HILLTIRK DRIVE



2a
Beech Tree / Scots Pine damage caused to both trees due to branches trying to occupy the same space. Many dead branches.. need to reduce weight on right hand side

1a - Suppressed Beech Tree close to fence 7 & 9 request removal of this tree

Split trunk to right

Scots Pine very tall see photo 2.

Secondary split trunk to right

These split trunks make the tree both forward leaning and right hand side leaning and heavy towards 7/9 Hilltirk Drive.

Photo 2.

Shows height of scots pine in relation to 7 HILLTHIRK DRIVE (Similar to 9 HILLTHIRK DRIVE).



Photo 3.



3. Beechtree.

Prune lower branches to higher the crown. and reduce weight on tight union.

4 branches at front
4 branches at rear.

Tight union

Photo 4



4. Beech tree - close to fence 7/5 Hilltirk Drive

Prune back lowest branches to higher the crown and remove branches hanging over 5 Hilltirk Drive.

5. Beech tree - close to fence 7/5 Hilltirk Drive

Prune split trunk branch and lower branches to higher crown and remove branches overhanging fence.