

Trial Pit Log

Trialpit No

HP01

Sheet 1 of 1

Project Name:	UNICORN HOUSE, CHEETHAM ROAD
---------------	------------------------------

Project No.
GRO-25231

Co-ords: -

Level:

Date _____

15/07/2025

Location: MIDDLETON

Dimensions
(m):

1

Depth
0.35

0.5

Scale
1:25

Logged
AT


Client: SIGNATURE ESTATES NORTH WEST LTD

Water Strike	Samples and In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description			
	Depth	Type	Results							
				0.15			MADE GROUND: Dark grey TARMAC.	1		
				0.35			MADE GROUND: Grey sandy fine to coarse angular to subrounded GRAVEL of concrete, brick, ceramic, pipe, sandstone, and siltstone. Sand is fine to coarse.		2	
				End of pit at 0.35 m		3				
							4			
										5

Remarks:	1. Location cleared by specialised utility clearance. 2 No groundwater encountered. 3. Pit sides stable. 4. Trial pit terminated at 0.35m bgl due to concrete obstruction and suspected communications line. 5. Trial pit backfilled with arisings.
----------	---

Stability:



				Trial Pit Log			Trialpit No SUDS1 Sheet 1 of 1	
Project Name: UNICORN HOUSE, CHEETHAM ROAD		Project No. GRO-25231		Co-ords: - Level:		Date 15/07/2025		
Location: MIDDLETON				Dimensions (m): Depth 2.00		Scale 1:25 Logged AT		
Client: SIGNATURE ESTATES NORTH WEST LTD				2				
Water Strike	Samples and In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description	
	Depth	Type	Results					
	0.50	ES		0.25			MADE GROUND: Light grey CONCRETE	
							MADE GROUND: Grey brown sandy fine to coarse angular to subrounded GRAVEL of concrete, brick, sandstone, and siltstone. Sand is fine to coarse.	
							Orange brown gravelly fine to coarse SAND. Gravel is angular to subrounded fine to coarse of sandstone, siltstone, and flint.	
	1.00	ES		0.80				
				2.00			End of pit at 2.00 m	
1 2 3 4 5								
Remarks: 1. Location cleared by specialised utility clearance. 2 No groundwater encountered. 3. Pit sides stable. 4. Trial pit terminated at 2.00m begl. 5. Trial pit backfilled with arisings.								
Stability:								

Trial Pit Log

Trialpit No
SUDS2
Sheet 1 of 1

Project Name:	UNICORN HOUSE, CHEETHAM ROAD	Project No.	GRO-25231	Co-ords:	-	Date	15/07/2025
Location:	MIDDLETON	Dimensions (m):	2	Depth	2.20	Scale	1:25
Client:	SIGNATURE ESTATES NORTH WEST LTD	Logged	AT				

Water Strike	Samples and In Situ Testing			Depth (m)	Level (m)	Legend	Stratum Description	
	Depth	Type	Results					
	0.50	ES		0.25			MADE GROUND: Light grey CONCRETE	
				0.80			MADE GROUND: Grey brown sandy fine to coarse angular to subrounded GRAVEL of concrete, brick, sandstone, and siltstone. Sand is fine to coarse.	
	1.00	ES					Orange brown gravelly fine to coarse SAND. Gravel is angular to subrounded fine to coarse of sandstone, siltstone, and flint.	1
				2.20			End of pit at 2.20 m	2
								3
								4
								5

Remarks: 1. Location cleared by specialised utility clearance. 2 No groundwater encountered. 3. Pit sides stable. 4. Trial pit terminated at 2.20m begl. 5. Trial pit backfilled with arisings.

Stability:

