

Appendix D Photographic Records

Cable Percussive Borehole Photographs

BH01



Photograph 1 – Photograph of the Hummocky Glacial Deposits between 0.4-1.2m bgl in BH01.



Photograph 2 – Photograph of the Hummocky Glacial Deposits between 4.0-4.45m bgl in BH01.



Photograph 3 – Photograph of the Hummocky Glacial Deposits between 10.00 – 10.45m in BH01 10.00 – 10.45m.



Photograph 4 – Photograph of the Hummocky Glacial Deposits between 13.0 – 13.45m in BH01.


BH02



Photograph 5 – Photograph of the Hummocky Glacial Deposits between 0.40m and 1.00m in BH02.



Photograph 6 – Photograph from the Hummocky Glacial Deposits between 8.0 – 8.5m in BH02.



Photograph 7 – Photograph of Hummocky Glacial Deposits between 11.0 and 11.5m bgl in BH02.


BH03



Photograph 8 – Photograph of the Hummocky Glacial Deposits between 0.50 – 1.0m in BH03.



Photograph 9 – Photograph of the Hummocky Glacial Deposits between 3.0 – 3.5m bgl in BH03.




Photograph 10 – Photograph of the Hummocky Glacial Deposits between 5.0 – 5.5m bgl in BH03.


BH04



Photograph 11 – Photograph the Hummocky Glacial Deposits between 1.2 – 1.65m in BH04.



Photograph 12 – Photograph of the Hummocky Glacial Deposits between 6.0 - 6.45m bgl in BH04.



Photograph 13 – Photograph of the Hummocky Glacial Deposits between 13.5 and 13.95m depth bgl in BH04.

BH05



Photograph 14 – Photograph of the Hummocky Glacial Deposits between 1.2 – 1.65m depth bgl in BH05.



Photograph 15 Photograph of the Hummocky Glacial Deposits between 8.0 – 8.45m depth bgl in BH05.



Photograph 16 – Photograph of the Hummocky Glacial Deposits between 14.0 – 14.45m depth bgl in BH05.


BH06



Photograph 17 – Photograph of Hummocky Glacial Deposits between 0.4 – 1.2m depth bgl in BH06.



Photograph 18 – Photograph of the Hummocky Glacial Deposits between of 4.5 – 4.95m bgl in BH06.




Photograph 19 – Photograph of Hummocky Glacial Deposits between 12.0 – 12.45m depth bgl in BH06.

BH07



Photograph 20 – Photograph of the Hummocky Glacial Deposits between 0.4 – 1.2m depth bgl in BH07.



Photograph 21 – Photograph of the Hummocky Glacial Deposits between 4.5 – 4.95m depth bgl in BH07.

BH08



Photograph 22 – Photograph of the Hummocky Glacial Deposits between 0.40m and 1.2m depth bgl in BH08.



Photograph 23 – Photograph of the Hummocky Glacial Deposits between 8.0 – 8.45m depth bgl in BH08.



Photograph 24 – Photograph of the Hummocky Glacial Deposits between 13.5 – 13.95m depth bgl on BH08.

BH09



Photograph 25 – Photograph of the Hummocky Glacial Deposits between 3.0 – 3.45m depth bgl in BH09.



Photograph 26 – Photograph of the Hummocky Glacial Deposits between 8.0 – 8.45m depth bgl in BH09.

BH10



Photograph 27 – Photograph of the Hummocky Glacial Deposits between 0.4 – 1.2m depth bgl in BH10.



Photograph 28 – Photograph of the Hummocky Glacial Deposits between 6.0 – 6.45m depth bgl in BH10.

BH11



Photograph 29 – Photograph of the Hummocky Glacial Deposits between 0.4 – 1.2m depth bgl in BH11.



Photograph 30 – Photograph of the Hummocky Glacial Deposits between 6.0 – 6.45m depth bgl in BH11.



Photograph 31 – Photograph of the Hummocky Glacial Deposits between 12.0 – 12.45m depth bgl in BH11.

Dynamic (Windowless) Sampling Borehole Photographs

WS01



Photograph 32 – Photograph of the Topsoil encountered in WS01.



Photograph 33 – Photograph of the Hummocky Glacial Deposits between 0.4 – 1.2m depth bgl in WS01.



Photograph 34 – Photograph of the Hummocky Glacial Deposits between 1.2 – 5.0m in WS01.

WS02



Photograph 35 – Photograph of the Topsoil encountered in WS02.



Photograph 36 – Photograph of the Hummocky Glacial Deposits between 0.4 – 1.2m depth bgl in WS02.



Photograph 37 – Photograph of the Hummocky Glacial Deposits between 1.2 – 5.0m depth bgl in WS02.

WS03



Photograph 38 – Photograph of the Topsoil encountered in WS03.



Photograph 39 – Photograph of the Hummocky Glacial Deposits between 1.2 – 5.0m depth bgl in WS03.

WS04



Photograph 40 – Photograph of the Hummocky Glacial Deposits between 1.2 – 5.45m depth bgl in WS04.

Site Photographs

General Site Photos



Photograph 1 – Photograph from the northeast of the site, adjacent to BHI, facing west



Photograph 2 – Photograph from the northeast of the site, ~20m north of BH02, facing southwest



Photograph 3 – Photograph from the east of the site, ~20m south of BHI, facing south



Photograph 4 – Photograph from the north of the site from BH01 looking southwest



Photograph 5 – Photograph from the eastern boundary of site looking northwest



Photograph 6 – Photograph from BHK, facing east, with BH06 pictured



Photograph 7 – Photograph from the position of TP17, facing west, with the location of BH04 ~15m in front



Photograph 8 – Photograph of the western valley, facing south, with TP20 pictured in progress



Photograph 8 – Photograph of the western valley of the site, facing north



Photograph 9 – Photograph from BH05, facing BH03 (west).



Photograph 10 – Photograph of BHD, facing north.



Photograph 11 – Photograph of the western valley, facing northeast.



Photograph 12 – Photograph of the field in the southern area of the site, the location of BH09, facing south.



Photograph 13 - Photograph of the eastern boundary of the site, facing south, the locations of TP04, 05 & 06.



Photograph 14 – Photograph from ~20m north of BH08, facing northeast.



Photograph 15 – Photograph from the top of the southeastern field, facing south.



Photograph 15 – Photograph of a southern field, from ~20m west of TP12, facing west



Photograph 16 – Photograph from the location of BH11, facing north



Photograph 16 – Photograph of the southern fishing lakes, from the location of BHN, facing west

Trial Pit Photographs

TP01



Photograph 1 – Photograph of TP01.



Photograph 2 – Photograph of the topsoil encountered in TP01.



Photograph 3 – Photograph of the Hummocky Glacial Deposits encountered in TP01.

TP02



Photograph 4 – Photograph of TP02.



Photograph 5 – Photograph from the Topsoil encountered in TP02.



Photograph 6 – Photograph of the Hummocky Glacial Deposits encountered in TP02.

TP03



Photograph 7 – Photograph of TP03.



Photograph 8 – Photograph of the Made Ground encountered in TP03.



Photograph 9 – Photograph of the Hummocky Glacial Deposits encountered in TP03.

TP04



Photograph 10 – Photograph of TP04.



Photograph 11 – Photograph of the Topsoil encountered in TP04.



Photograph 12 – Photograph of the Hummocky Glacial Deposits encountered in TP04.

TP05



Photograph 13 – Photograph of TP05.



Photograph 14 – Photograph of the Topsoil encountered in TP05.



Photograph 15 - Photograph of the Hummocky Glacial Deposits encountered in TP05.

TP06



Photograph 16 – Photograph of TP06.



Photograph 17 – Photograph of the Topsoil encountered in TP06.



Photograph 18 – Photograph of the Hummocky Glacial Deposits encountered in TP06.

TP07



Photograph 19 – Photograph of TP07.



Photograph 20 – Photograph of the Made Ground encountered in TP07.



Photograph 21 – Photograph of the Hummocky Glacial Deposits encountered in TP07.

TP08



Photograph 22 – Photograph of TP08.



Photograph 23 – Photograph of the Topsoil deposits encountered in TP08.



Photograph 24 – Photograph of the Hummocky Glacial Deposits encountered in TP08.

TP09



Photograph 25 – Photograph of the Topsoil encountered in TP09.



Photograph 26 – Photograph of the Hummocky Glacial Deposits encountered in TP09.

TP10



Photograph 27 – Photograph of TP10



Photograph 28 – Photograph of the Topsoil deposits encountered in TP10.



Photograph 29 – Photograph of the Made Ground encountered in TP10.



Photograph 30 – Photograph of the Hummocky Glacial Deposits encountered in TP10.

TP11



Photograph 30 – Photograph of TP11.



Photograph 31 – Photograph of the Topsoil encountered in TP11.



Photograph 32 – Photograph of the Made Ground deposits encountered in TP11



Photograph 33 – Photograph of the Hummocky Glacial Deposits encountered in TP11.

TP12



Photograph 34 – Photograph of TP12.



Photograph 35 – Photograph of the Topsoil encountered in TP12.



Photograph 36 – Photograph of the Hummocky Glacial Deposits encountered in TP12.

TP13



Photograph 37 – Photograph of TP13.



Photograph 38 – Photograph of the Topsoil encountered in TP13.



Photograph 39 – Photograph of the Made Ground encountered in TP13.



Photograph 40 – Photograph of the Hummocky Glacial Deposits encountered in TP13.

TP14



Photograph 41 – Photograph of TP14.



Photograph 42 – Photograph of the Made Ground encountered in TP14.



Photograph 43 – Photograph of the Hummocky Glacial Deposits encountered in TP14.

TP15



Photograph 44 – Photograph of TP15.



Photograph 45 – Photograph of the Hummocky Glacial Deposits encountered in TP15.

TP16



Photograph 46 – Photograph of TP16.



Photograph 47 – Photograph of Topsoil encountered in TP16..



Photograph 48 – Photograph of the Hummocky Glacial Deposits encountered in TP16.

TP17



Photograph 49 – Photograph of TP17.



Photograph 50 – Photograph of the Topsoil encountered in TP17.



Photograph 51 – Photograph of the Alluvium encountered in TP17

TP18



Photograph 52 – Photograph of the Topsoil deposits encountered in TP18.



Photograph 53 – Photograph of the Hummocky Glacial Deposits encountered in TP18.

TP19



Photograph 54 – Photograph of TP19.



Photograph 55 – Photograph of the Made Ground encountered in TP19.



Photograph 56 – Photograph of the Alluvium and Hummocky Glacial Deposits encountered in TP19.

TP20



Photograph 57 – Photograph of TP20.



Photograph 58 – Photograph of Made Ground encountered in TP20.



Photograph 59 – Photograph of Hummocky Glacial Deposits encountered in TP20.

TP21



Photograph 60 – Photograph of TP21.



Photograph 61 – Photograph of the Topsoil encountered in TP21.



Photograph 62 – Photograph of the Hummocky Glacial Deposits encountered in TP21.

TP22



Photograph 63 – Photograph of TP22.



Photograph 64 – Photograph of the Topsoil encountered in TP22.



Photograph 65 – Photograph of the Hummocky Glacial Deposits encountered in TP22

TP23



Photograph 66 – Photograph of TP23.

TP24



Photograph 67 – Photograph of TP24, with TP23 in the background.

TP25



Photograph 68 – Photograph of TP25.



Photograph 69 – Photograph of TP25 arisings with Hummocky Glacial Deposits left, and Topsoil right.

TP26



Photograph 70 – Photograph of TP26, with Topsoil pictured left.



Photograph 71 – Photograph of Hummocky Glacial Deposits encountered in TP26.