

A photograph of a residential property. In the foreground, a narrow public footpath leads from the bottom left towards the center. To the left of the path is a dense hedge and a large tree with dark red leaves. To the right of the path is a wooden fence and a large tree with green leaves. In the background, a brick house with a chimney is visible. The sky is overcast.

Sycamore T13

21 Norwich Avenue

Public footpath



Co-dominant stems
with included bark union

Crack

T13

Broken boundary fence

