



© TRIANGLE ARCHITECTS LIMITED

THIS DRAWING IS THE SUBJECT OF COPYRIGHT WHICH VESTS IN TRIANGLE ARCHITECTS LIMITED. IT IS AN INFRINGEMENT OF COPYRIGHT TO REPRODUCE THIS DRAWING, BY WHATEVER MEANS, INCLUDING ELECTRONIC, WITHOUT THE EXPRESS WRITTEN CONSENT OF TRIANGLE ARCHITECTS LIMITED WHICH RESERVES ALL ITS RIGHTS.

TRIANGLE ARCHITECTS LIMITED ASSERTS ITS RIGHTS TO BE IDENTIFIED AS THE AUTHOR OF THIS DESIGN.

DRAWING NOT TO BE SCALED. FIGURE DIMENSIONS TO BE WORKED TO IN ALL CASES.

THE CONTRACTOR IS RESPONSIBLE FOR CHECKING DIMENSIONS, TOLERANCES & REFERENCES.

ANY DISCREPANCY TO BE VERIFIED WITH THE ARCHITECT BEFORE PROCEEDING WITH THE WORKS.

REPORT ERRORS & OMISSIONS TO ARCHITECT.

WHERE AN ITEM IS COVERED BY DRAWINGS OF DIFFERENT SCALE, THE LARGER SCALE DRAWING TO BE WORKED TO. DO NOT SCALE FROM THE DRAWING. FIGURED DIMENSIONS TO BE WORKED TO IN ALL CASES.

CHECK ALL DIMENSIONS ON SITE.

DRAWING TO BE READ IN CONJUNCTION WITH THE HEALTH & SAFETY PLAN, AND ALL RELEVANT RISK ASSESSMENTS AND THE FOLLOWING DRAWINGS:

Site Constraints Notes


- 01 Car Park
- 02 Former Playground
- 03 Grass *level drops at south edge
- 04 Public footpath *right of way might need to be retained?
- 05 Bus Stop
- 06 Existing sheds to be removed *owners need to be consulted
- 07 Site slopes down from west to east
- 08 Current car park access
- 09 Frequent traffic on Whitworth Road
- 10 Cycle lane
- 11 Shops & dwellings
- 12 Shops, possibly dwellings on first floor
- 13 Advertising sign
- 14 Substation
- 15 Existing access to rear gardens

Site Constraints Legend

- ★ Principal corner *key view from Whitworth Road corridor
- Trees
- SP Lampost/Telegraph pole
- LP/TP Signpost
- Services cover (drain/electric/telecoms etc.) *Indicative only, utilities survey information required

Tree Schedule

- | | |
|----|---|
| T1 | Large tree, appears in good condition, and is in a good location at the end of Derwent St. *suggest retaining this tree |
| T2 | Small tree/cluster of trees |
| T3 | Small tree, poor condition |
| T4 | Small tree |
| T5 | Small/medium tree, appears okay condition and good location next to bus stop, *suggest retaining if possible |
| T6 | Large tree, appears in good condition, *suggest retaining this tree |



Revision:	Date:	By:	Remarks:
P01	22.03.22	JS	Issued for planning with updated redline boundary.

TRIANGLE
ARCHITECTS

Tel: 0161 272 3500
E-mail: studio@trianglearchitects.co.uk
Web: www.trianglearchitects.co.uk
Twitter: @TriangleArch

Raven House,
113 Fairfield Street,
Manchester,
M12 6EL

Drawing Purpose:	Revision:	Scale @A3: 1 : 500	Client:
INFORMATION	P01	Date: June 2021	Cornerstone Place
Project: Origin: Vol/Sys: Level: Type: Role: Drg No:	Drawn: JS	Checked: AJD	Project No. / Project Name:
WHI - TRI - ZZ - ZZ - DR - A - 3001			21-032 / Whitworth Road, Rochdale
			Drawing Name:
			Site Constraints Diagram