

Application to discharge conditions.


Condition:	Supplier / Description	Photograph / details
Nr. 3. Roof slates	Supplied by Lansdowne roofing supplies Ltd Lansdowne Rd, Chadderton, Oldham OL9 9EF	

23/00694/LBC – The Old Manor, Ogden Lane, Newhey, Milnrow, Rochdale, OL16 3TD

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
		

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
Nr. 4. Windows	Manufactured by Marlin Joinery Unit 5 Roman Road Royton Oldham OL2 5PJ	21:29 prontojoinery.co.uk  ← → + 32 ...

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
		

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
		

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
		

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
		

23/00694/LBC – The Old Manor, Ogden Lane, Newhey, Milnrow, Rochdale, OL16 3TD

Application to discharge conditions.

Condition:	Supplier / Description	Photograph / details
		 A screenshot of a mobile application interface. At the top, the status bar shows the time 11:25, 4G signal, and 64% battery. Below this is a header bar with a back arrow, the text 'Huddersfield' and '15 February 10:59', an 'Edit' button, and a menu icon. The main content area shows a photograph of a white-framed window looking out onto a green landscape with trees. Below the photo is a horizontal strip of smaller thumbnail images. At the bottom is a navigation bar with four icons: a share icon, a heart icon, an information icon, and a trash icon.