

RTH.06
Decoration Schedule
Rochdale Town Hall - Phase 3

File Name					
RTH-DIA-XX-XX-SH-A-6500-DecorationsSchedule					
Date	Prepared by	Approved by	Status Code	Version Number	Purpose of issue
05/04/2023	CZS	ARF	D1	P01	For Costing
24/04/2023	CZS	ARF	D1	P02	For Costing
15/01/2024	CZS		S0	P03	Draft - For Discussion
24/05/2024	CZS		CR	C01	For Construction
22/07/2024	CZS	DAC	CR	C02	For Construction
16/09/2024	CZS	DAC	CR	C03	For Construction
15/11/2024	CZS	DAC	S4	P04	For LBC updates

Simon Malam
simon.malam@insall-architects.co.uk
Tel: 01244 350 063

Chester Office
Donald Insall Associates
Bridgegate House, 5 Bridge Place, Chester, CH1 1SA
www.insall-architects.co.uk

This report and all intellectual property rights in it and arising from it are the property of or are under licence to Donald Insall Associates or the RDA. Neither the whole nor any part of this report, nor any drawing, plan, other document or any information contained within it may be reproduced in any form without the prior written consent of Donald Insall Associates or the RDA as appropriate. All material in which the intellectual property rights have been licensed to Donald Insall Associates or the RDA and such rights belong to third parties may not be published or reproduced at all in any form, and any request for consent to the use of such material for publication or reproduction should be made directly to the owner of the intellectual property rights therein.

RTH.06
Decoration Schedule
Rochdale Town Hall - Phase 3

Notes

Generally:

To be read in conjunction with M52; M60
Control Samples: In accordance with NBS Clause M60/300.
Ceiling Structure: includes exposed trusses, beams, corbels, purlins, ribs.
Walls: includes arches (new and existing), plastered cills.
Masonry: includes stone, brick, blockwork, concrete.
Walls include window reveals where applicable.

Colours:

Colours: Generally referred to by room.
Stone Window Surrounds: Previously painted window surrounds where noted - Stone Colour: "Sandstone".
Window surrounds will be painted different from reveals (plastered reveal same colour as walls, window tracery stone colour specified)
Dry Riser & historic internal grilles will be decorated RAL 7022.

Windows:

All windows powdercoated unless overhauled.
Where windows are replaced, the black sealant is to be painted in same colour as window masonry internally as per Phase 2.

Intumescent Paint:

All New Steelwork that was installed in P3 and is to be left exposed is to be intumescently painted.
Individual existing structural exposed steels are noted in the schedule.
Structural Exposed Steels: includes beams, columns, lintels, ties - all sections and profiles.
Existing exposed joinery that is non-loadbearing is to be redecorated.
Existing exposed joinery that is loadbearing is to be redecorated in upgrade.
New exposed joinery that is loadbearing is to be decorated in upgrade or designed to allow for suitable charring factor.

New Joinery:

Softwood: Skirting, Architraves, Doors: M60/150
Hardwood: Skirting, Architraves, Doors: M60/132
New Bespoke Oak Screens: M60/125
Internal Hardwood Doors: M60/125
External Hardwood Doors: M60/110A
Internal Softwood Doors: M60/150 - Basement Doors: White. Doors to WCs: Dark Green: F4261C. Other Flush Doors: To match adjacent walls.
Loft Hatches: New/replaced loft hatches are all specified as to be concealed - ie without an timber architrave, so decorations to ceilings also apply to the lid of the loft hatch.

**Clear Finishing
Existing Joinery:**

Existing Clear Finished Joinery (Incl Panelling, Architraves, Linings, Dados, Capping, Skirting, Integrated benches.:
- Cleaning to existing joinery will be undertaken by volunteers after the project.
- Clear Finishing to all existing retained clear finished joinery: M60/131.

All joinery repairs listed in RTH-DIA-XX-XX-SH-A-6101-HistoricDoorsRepairSchedule & repairs to existing joinery are to be finished in to match the adjacent existing using M60/132.

Only previously decorated or SW joinery is to be painted, unless specifically noted as item under joinery features.

**Surface Spread of
Flame Approach:**

For information only the approach to which type of paint is to be applied to walls and ceilings (including features) is noted here:

	To achieve		
European Class	B-s3, d2	C-s3, d2	D-s3, d2
Description	Escape Corridors, circulation routes and escape stairs	Rooms with an area equal or over 30sqm	Rooms with an area under 30sqm
Bcontrol confirmed exempt as use not changed and just re-painting	paint system 3/4	paint system 3/4	paint system 3/4
Newly skimmed walls which will be painted (ie where a new lining or skimmed over as large repairs/alterations)	paint system 3/4	paint system 3/4	paint system 3/4
Existing wall patch repaired plaster, which need re-painting	paint system 1	paint system 2	paint system 3/4
Walls that will have lining paper	paint system 1	paint system 2	paint system 3/4

Surface			Masonry				Building Control - For Information		Plaster				Clear Finish Joinery				Painted joinery			Painted Metalwork		
Room Ref	Room Name	Colour Notes:	Walls	Vaults / Exposed Slab Ceilings	Note: In Window plane only (whole tracery), for reveals and sills refer walls	Decorative Features	Substrate (For information)	Notes for Surface Spread of Flame (For information)	Walls		Ceilings	Features	Door Sets	Dado	Skirtings	Features	Door Sets	Skirtings	Features	Windows	Structural Exposed Steel	Features
									Lining Paper NBS M52/110	Paint	Paint											
Third Floor																						
Riser	Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster	Riser<30sqm	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
T1	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1	M60/151 - Paint System 1 to rendered skirtings	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	M60/631	NA	NA
T1a	Corridor	Dry Riser: RAL 7022	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Dry Riser: M60/116 RAL 7022
T2	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope
T3	Out of scope	Dry Riser: RAL 7022	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Dry Riser: M60/1126 RAL 7022
Second Floor																						
S10	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Window Surrounds –Stone Colour: Sandstone Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	M60/631	NA	NA
S11a	Corridor	Skirting - Dark Green: F4261C Ceiling - Lightest Green: F1730H Walls - Light Green: F3680P	NA	NA	NA	NA	Patch Repaired Plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls)	M60/151 - Paint System 3	NA	Existing M60/131 Repairs M60/132	NA	NA	NA	As Skirtings to previously painted doors and DS11a.2 M60/150	M160/150 Dark Green (F4261C)	Glazed screen partition decorated M60/150 Dark Green: F4261C	NA	NA	NA
S11b	Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch Repaired Plaster & some new walls	<30sqm Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
S11c	Corridor	Skirting - Dark Green: F4261C Ceiling - Lightest Green: F1730H Walls - Light Green: F3680P	NA	NA	M60/172	NA	Patch Repaired Plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 4(To New Walls)	M60/151 - Paint System 3	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132 to DS10.1	NA	NA	NA	M60/150 to all other than DS10.1	NA	NA	M60/631	NA	NA
S11d	Office	Skirting - Dark Green: F4261C Walls - Mid Green: F4460V Ceiling - Lightest Green: F1730H	NA	NA	NA	NA	Patch repaired plaster	<30sqm	NA	M60/151 - Paint System 3	M60/151 - Paint System 3	NA	NA	NA	NA	NA	M160/150 As Skirtings	M160/150 Dark Green (F4261C)	Window surround, architrave and apron M60/150 Dark Green: F4261C	M60/631	NA	NA
S11e	Office	Skirting - Dark Green: F4261C Walls - Mid Green: F4460V Ceiling - Lightest Green: F1730H	NA	NA	NA	NA	Patch repaired plaster	<30sqm	NA	M60/151 - Paint System 3	M60/151 - Paint System 3	NA	NA	NA	NA	NA	M160/150 As Skirtings	M160/150 Dark Green (F4261C)	Timber panels to East wall M60/150 Dark Green: F4261C Window architraves and apron M60/150 Dark Green: F4261C	M60/631	NA	NA
S12	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600 Cornice - Crown Dark Beige 1510 – Y20R Balustrades: To largely take on the existing scheme as follows refer sketch in appendix for detail. Existing: Cream Areas – Crown Light Beige B5760U Red Areas – Crown Dark Red 4550 – Y90R Blue / Green Areas - Crown Darkest Green F3080R Gold Areas – Repaint with Polyvine acrylic metallic paint in Bright Gold	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	M60/631	NA	NA
S13a	Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix. Dry Riser: RAL 7022	NA	NA	NA	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls above panelling) M60/151 - Paint System 3(To New Walls above panelling)	M60/151 - Paint System 3 ceiling M60/151 - Paint System 1 to cornice	NA	Existing M60/131 Repairs M60/132	NA	Panelling: Existing M16/131 Repairs M60/132	Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	NA	NA	Dry Riser: M60/1126 RAL 7022
S13b	Council Chamber Gallery	Walls - Refer to drawings 0020, 0021 & 0022	NA	NA	NA	NA	Heritage room	>30sqm	NA	M60/151 - Paint System 2	LCS	LCS	M60/126	LCS	LCS	LCS	LCS	LCS	LCS	LCS	NA	LCS
S13c	Stair & Rack B	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
S14a	Lift Lobby	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Skirting - Dark Green: F4261C	NA	NA	NA	NA	Patch repaired plaster & some new walls	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1	NA	NA	NA	NA	NA	M160/150 As Skirtings	M160/150 Dark Green (F4261C)	NA	NA	NA	NA
S14b	Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Skirting - Dark Green: F4261C	NA	NA	NA	NA	Patch repaired plaster & some new walls	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1	NA	NA	NA	NA	NA	M160/150 As Skirtings	M160/150 Dark Green (F4261C)	NA	NA	NA	NA
S14c	Accessible WC	Walls - Light Green: F3680P Ceiling - Mid Green: F4460V IPS - Dark Green: F4261C	NA	NA	NA	NA	New Plaster	<30sqm	NA	M60/151 - Paint System 4	M60/151 - Paint System 3	NA	NA	NA	NA	NA	M160/150 Dark Green (F4261C)	NA	IPS: M60/150 Dark Green (F4261C)	NA	NA	NA
S14d	Male toilets	Walls - Light Green: F3680P Ceiling - Mid Green: F4460V IPS - Dark Green: F4261C	NA	NA	NA	NA	New Plaster	<30sqm	NA	M60/151 - Paint System 4	M60/151 - Paint System 3	NA	NA	NA	NA	Vanity Unit: M60/127	M160/150 Dark Green (F4261C)	NA	IPS: M60/150 Dark Green (F4261C)	NA	NA	NA
S14e	Female toilets	Walls - Light Green: F3680P Ceiling - Mid Green: F4460V IPS - Dark Green: F4261C	NA	NA	M60/172	NA	Patch repaired plaster and new plaster	<30sqm	NA	M60/151 - Paint System 4	M60/151 - Paint System 3	NA	NA	NA	NA	NA	M160/150 Dark Green (F4261C) Riser Doors To Match Walls M60/150	NA	IPS: M60/150 Dark Green (F4261C)	M60/631	NA	NA
S14f	Office	Skirtings - Dark Green: F4261C Walls - Light Green: F3680P Ceiling - Lightest Green: F1730H	NA	NA	M60/172	NA	Patch repaired plaster and new plaster	>30sqm	NA	M60/151 - Paint System 2	M60/151 - Paint System 2	NA	NA	NA	NA	NA	M160/150 As Skirtings	M160/150 Dark Green (F4261C)	NA	M60/631	NA	NA
S16	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs – Stone Colour: Sandstone Ceiling - Light Beige: B57600	NA	NA	M60/172	NA	Patch repaired plaster and new plaster	Escape Route / Circulation	NA	M60/151 - Paint System 3(To South Wall)M60/151 - Paint System 1 (To Other Existing Walls)	M60/151 - Paint System 1	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	Stair: Existing Except Treads: M16/131 Repairs Except Treads: M60/132 New Except Treads: M60/125 Existing Treads: M60/179 New Treads: M60/180A	NA	NA	NA	M60/631	NA	Balustrade & Spindles M60/116 RAL 7022

Room Ref	Room Name	Colour Notes:	Masonry				Building Control - For Information		Plaster			Features	Clear Finish Joinery				Painted joinery			Painted Metalwork			
			Walls	Vaults / Exposed Slab Ceilings	Window Surrounds Note: In Window plane only (whole tracery), for reveals and sills refer walls	Decorative Features	Substrate (For information)	Notes for Surface Spread of Flame (For information)	Lining Paper NBS M52/110	Paint	Paint		Door Sets	Dado	Skirtings	Features	Door Sets	Skirtings	Features	Windows	Structural Exposed Steel	Features	
First Floor																							
F10	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	NA	NA	NA	
F11a	Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix.	NA	NA	NA	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1 -Including Cornice	NA	Existing M60/131 Repairs M60/132	NA	NA	Existing M16/131 Repairs M60/132	Benches: Existing M16/131 Repairs M60/132 Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	NA	NA	
F11b	Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster & some new walls	<30sqm Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA	
F11c	Corridor	Skirting - Dark Green: F4261C Ceiling - Lightest Green: F1730H Walls - Light Green: F3680P	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 3- new cornice	Rendered skirtings M60/151 - Paint System 1	M60/126	NA	M60/126	NA	NA	NA	M60/631	NA	NA		
F11d	Office	Skirtings - Dark Green: F4261C Walls - Light Green: F3680P Ceiling - Lightest Green: F1730H Cornice - Lightest Green: F1730H	NA	NA	M60/172	NA	Patch repaired plaster	<30sqm	NA	M60/151 - Paint System 3	M60/151 - Paint System 3-Including Cornice	NA	NA	NA	NA	NA	M160/150 As Skirtings	M160/150 Dark Green (F4261C)	Window surround, architrave and apron M60/150 Dark Green: F4261C	M60/631	NA	NA	
F11e	Green Room	Skirtings - Dark Green: F4261C Walls - Light Green: F3680P Ceiling - Lightest Green: F1730H Cornice - Lightest Green: F1730H	NA	NA	M60/172	NA	Patch repaired plaster	<30sqm	NA	M60/151 - Paint System 4	M60/151 - Paint System 3-Including Cornice	NA	DF11e.2 Existing M60/131 Repairs M60/132	NA	NA	Vanity Unit legs and apron: M60/127	DF11e.1 M160/150 As Skirtings	M60/150 Dark Green: F4261C	Part glazed timber partition screen in M60/150 Dark Green: F4261C. Window architraves and apron M60/150 Dark Geen: F4261C Vanity units/Desks M60/150 Dark Green: F4261C Picture rail M60/150 Dark Green: F4261C	M60/631	NA	NA	
F12	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600 Cornice - Crown Dark Beige 1510 – Y20R Balustrades: To largely take on the existing scheme as follows refer sketch in appendix for detail. Existing: Cream Areas – Crown Light Beige B5760U Red Areas – Crown Dark Red 4550 – Y90R Blue / Green Areas - Crown Darkest Green F3080R Gold Areas – Repaint with Polyvine acrylic metallic paint in Bright Gold	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	Existing M16/131 Repairs M60/132	Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	M60/631	NA	Dry Riser: M60/116 RAL 7022
F13a	Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix.	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1 - Including Cornice	NA	Existing M60/131 Repairs M60/132	NA	NA	Existing M16/131 Repairs M60/132	Benches: Existing M16/131 Repairs M60/132 Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	M60/631	NA	NA
F13b	Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix.	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1 - Including Cornice	NA	DF13b.2 Existing M60/131 Repairs M60/132 DF13b.1 New M60/125	NA	NA	Existing M16/131 Repairs M60/132	Benches: Existing M16/131 Repairs M60/132 Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	M60/631	NA	NA
F14a	New Mayors Parlour	Walls above paneling - Lincrusta paper in William Morris Fruits - (WM1981FR). Decoration/colours as per sample provided.	NA	NA	Hirst Specialist cleaned to reveal existing decorative scheme.	NA	Heritage Room	>30sqm	NA	Above Timber Paneling : Lyncrsta William Morris Fruits - (WM1981FR). Decoration/colours as per sample provided.	LCS Specialist cleaned	NA	Existing M60/131 Repairs M60/132	NA	NA	Existing M16/131 Repairs M60/132	Benches: Existing M16/131 Repairs M60/132 Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	M60/631	NA	
F14b	Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) with single line Mid Red (030 40 40) highlight to upper moulding. Refer to images in Appendix Simplified cornice in dark green & mid red.	NA	NA	NA	NA	Patch repaired plaster & some new walls	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 3 to new suspended ceiling and new cornice New cornice	NA	Existing M60/131 Repairs M60/132	NA	NA	Existing M16/131 Repairs M60/132	Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	NA	NA	NA
F14c.1	Lift & WC Lobby	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) with single line Mid Red (030 40 40) highlight to upper moulding. Refer to images in Appendix Simplified cornice in dark green & mid red.	NA	NA	M60/172	NA	Patch repaired plaster & some new walls	escape route/circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1 to existing repaired ceilings and cornice, M60/151 - Paint System 3 to new suspended ceiling and new cornice	NA	DF14b.2: Existing M60/131 Repairs M60/132	NA	NA	Existing M16/131 Repairs M60/132	Panelling: Existing M16/131 Repairs M60/132 New: M60/125	NA	NA	NA	NA	NA	NA

Surface		Colour Notes:	Masonry				Building Control - For Information		Plaster				Clear Finish Joinery				Painted joinery			Painted Metalwork		
Room Ref	Room Name		Walls	Vaults / Exposed Slab Ceilings	Window Surrounds	Decorative Features	Substrate (For information)	Notes for Surface Spread of Flame (For information)	Walls		Ceilings	Features	Door Sets	Dado	Skirtings	Features	Door Sets	Skirtings	Features	Windows	Structural Exposed Steel	Features
			Lining Paper NBS M52/110	Paint	Paint																	
F14c.2	Lift & WC Lobby	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix. WC Cubicles: Walls - Light Green: F3680P Ceiling - Mid Green: F4460V IPS: Dark Green: F4261C Cornice: NA	NA	NA	M60/172	NA	Patch repaired plaster & some new walls	escape route/circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1 to existing repaired ceilings and cornice, M60/151 - Paint System 3 to new suspended ceiling and new cornice	NA	New HW doors: M60/125	NA	Existing M16/131 Repairs M60/132	Panelling: Existing M16/131 Repairs M60/132 New: M60/125	Riser Doors To Match Walls M60/150	NA	IPS: M60/150 Dark Green (F4261C)	M60/631	NA	NA
F14c.3	Lift & WC Lobby	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice - Dark Green (F4261C) with single line Mid Red (030 40 40) highlight to upper moulding. Refer to images in Appendix Simplified cornice in dark green & mid red. WC Cubicles: Walls - Light Green: F3680P Ceiling - Mid Green: F4460V IPS: Dark Green: F4261C Cornice: NA	NA	NA	M60/172	NA	Patch repaired plaster & some new walls	escape route/circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1 to existing repaired ceilings and cornice, M60/151 - Paint System 3 to new suspended ceiling and new cornice	NA	New HW doors: M60/125	NA	Existing M16/131 Repairs M60/132	NA	NA	IPS: M60/150 Dark Green (F4261C)	M60/631	NA	NA	
F14d	Mayors BOH	Skirtings - Dark Green: F4261C Walls - Light Green: F3680P Ceiling - Lightest Green: F1730H Cornice - Lightest Green: F1730H	NA	NA	M60/172	NA	Patch repaired plaster	<30sqm	NA	M60/151 - Paint System 3	M60/151 - Paint System 3 - New cornice	NA	Existing M60/131 Repairs M60/132	NA	NA	Counter legs and apron: M60/127	Riser Doors To Match Walls M60/150	M60/150 Dark Green: F4261C	NA	M60/631	NA	NA
F15a	Council Chamber	Walls - Refer to drawings 0020, 0021 & 0022	NA	NA	M160/171	NA	Patch repaired plaster in Heritage Room	>30sqm	NA	M60/151 - Paint System 2	LCS	LCS	Existing M60/131 Repairs M60/132	Existing M16/131 Repairs M60/132	Existing M16/131 Repairs M60/132 New: M60/125	Panelling: Existing M16/131 Repairs M60/132 New: M60/125	NA	NA	NA	M60/172	NA	LCS
F15b	Mayors Corridor	Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1 , M60/151 - Paint System 3 to new cornice	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	Existing M16/131 Repairs M60/132	Panelling around vents: Existing M16/131 Repairs M60/132	NA	NA	NA	M60/631	NA	NA
F16	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs – Stone Colour: Sandstone	NA	NA	M60/172	NA	Patch repaired plaster and new plaster	Escape Route / Circulation	NA	M60/151 - Paint System 3(To South Wall)M60/151 - Paint System 1 (To Other Existing Walls)	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	Stair: Existing Except Treads: M16/131 Repairs Except Treads: M60/132 New Except Treads: M60/125 Existing Treads: M60/179 New Treads: M60/180A	NA	NA	NA	M60/631	NA	Balustrade & Spindles M60/116 RAL 7022

Surface		Colour Notes:	Masonry				Building Control - For Information		Plaster				Clear Finish Joinery				Painted joinery			Painted Metalwork		
Room Ref	Room Name		Walls	Vaults / Exposed Slab Ceilings	Window Surrounds Note: In Window plane only (whole tracery), for reveals and sills refer walls	Decorative Features	Substrate (For information)	Notes for Surface Spread of Flame (For information)	Walls		Ceilings	Features	Door Sets	Dado	Skirtings	Features	Door Sets	Skirtings	Features	Windows	Structural Exposed Steel	Features
									Lining Paper NBS M52/110	Paint	Paint											
Mezzanine Floor																						
M10	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	NA	NA	NA
M11a	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M11b	Corridor	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
M11c	Corridor	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
M11d	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M12	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600 Cornice - Crown Dark Beige 1510 – Y20R Balustrades: To largely take on the existing scheme as follows refer sketch in appendix for detail. Existing: Cream Areas – Crown Light Beige B5760U Red Areas – Crown Dark Red 4550 – Y90R Blue / Green Areas - Crown Darkest Green F3080R Gold Areas – Repaint with Polyvine acrylic metallic paint in Bright Gold	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	Panelling: Existing M16/131 Repairs M60/132	NA	NA	NA	M60/631	NA	NA
M13a	Lobby/Corridor	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster and some new walls	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
M13b	Out Of Scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out Of Scope	Out Of Scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out Of Scope	Dry riser - M60/1126 Bal. 2020
M13c	Lift Lobby	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster and some new walls	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
M13d	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out of scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M13e	Room Beside Lift	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster and some new walls	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
M14a	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M14b	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M14c	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M15	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope	Out Of Scope
M16	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	New fire rated plasterboard lining	>30sqm storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	Out Of Scope
Riser	Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster	Riser<30sqm	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA

Surface	Room RefRoom Name		Colour Notes:	Masonry			Building Control - For Information		Plaster				Clear Finish Joinery				Painted joinery			Painted Metalwork		
				Walls	Vaults / Exposed Slab Ceilings	Window Surrounds Note: In Window plane only (whole tracery), for reveals and sills refer walls	Decorative Features	Substrate (For information)	Notes for Surface Spread of Flame (For information)	Walls		Ceilings	Features	Door Sets	Dado	Skirtings	Features	Door Sets	Skirtings	Features	Windows	Structural Exposed Steel
									Lining Paper NBS M52/110	Paint	Paint											
Ground Floor																						
G09f	Corridor areas	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope
G10a	Stair	Skirting – Darkest Green: F30 80R Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	NA	NA	NA
G10b	Lobby	Skirting - Dark Green: F4261C Ceiling - Lightest Green: F1730H Cornice - Lightest Green: F1730H Walls - Light Green: F3680P	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 1	NA	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	M60/130	NA	M60/631	NA	NA
G11a	Corridor	Skirting - Dark Green: F4261C Ceiling - Lightest Green: F1730H Cornice - Lightest Green: F1730H Walls - Light Green: F3680P	NA	NA	NA	NA	Patch repaired plaster and some new walls	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1	NA	NA	NA	NA	NA	M160/150 Dark Green (F4261C)	M160/150 Dark Green (F4261C)	NA	NA	NA	NA
G11d	Changing Places	Ceiling: Mid Green: F4460V Walls: Light Green: F3680P	NA	NA	M60/172	NA	Patch repaired plaster and some new walls	<30sqm	NA	M60/151 - Paint System 4	M60/151 - Paint System 3	NA	NA	NA	NA	NA	M160/150 Dark Green (F4261C)	NA	NA	M60/631	NA	NA
G12	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs –Stone Colour: Sandstone Ceiling - Light Beige: B57600 Cornice - Crown Dark Beige 1510 – Y20R Balustrades: To largely take on the existing scheme as follows refer sketch in appendix for detail. Existing: Cream Areas – Crown Light Beige B5760U Red Areas – Crown Dark Red 4550 – Y90R Blue / Green Areas - Crown Darkest Green F3080R Gold Areas – Repaint with Polyvine acrylic metallic paint in Bright Gold	NA	NA	M60/172	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	M60/631	NA	NA
G13a	Corridor	Skirting - Dark Green: F4261C Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Dry Riser: RAL 7022 Cornice: Cornice: Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix	NA	NA	NA	NA	Patch repaired plaster	Escape Route / Circulation	NA	M60/151 - Paint System 1	M60/151 - Paint System 3	NA	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	M160/150 Dark Green (F4261C)	NA	NA	NA	Dry Riser: M60/1126 RAL 7022
G14c	Lift Lobby	Skirting - Dark Green: F4261C Walls - Light Beige: B57600 Ceiling - Dark Beige: 1510 – Y20R Cornice: Cornice: Dark Green (F4261C) upper and lower profiles with single line Mid Red (030 40 40) highlight to each. Dark Beige (1510-Y20R) to central section of cornice. Refer to images in Appendix	NA	NA	M60/172	NA	Patch repaired plaster and some new walls	Escape Route / Circulation	NA	M60/151 - Paint System 1 (To Existing Walls) M60/151 - Paint System 3(To New Walls)	M60/151 - Paint System 1	NA	NA	NA	NA	NA	Riser Doors To Match Walls M60/150	M160/150 Dark Green (F4261C)	NA	M60/631	NA	NA
G16	Stair	Skirting – Crown Dark Red 4550 – Y90R (include returns where new skirting returns into screen) Walls - Light Beige: B57600 Underneath of Stairs – Stone Colour: Sandstone	NA	NA	M60/172	NA	Patch repaired plaster and new plaster	Escape Route / Circulation	NA	M60/151 - Paint System 3(To South Wall)M60/151 - Paint System 1 (To Other Existing Walls)	NA	Rendered skirtings M60/151 - Paint System 1	Existing M60/131 Repairs M60/132	NA	NA	NA	NA	NA	NA	NA	Balustrade & Spindles M60/116 RAL 7022	
Riser	Riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Patch repaired plaster	Riser <30sqm	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA
Basement Floor																						

Surface			Colour Notes:	Masonry			Building Control - For Information		Plaster				Clear Finish Joinery				Painted joinery			Painted Metalwork		
Room Ref	Room Name	Walls		Vaults / Exposed Slab Ceilings	Window Surrounds Note: In Window plane only (whole tracery), for reveals and sills refer walls	Decorative Features	Substrate (For information)	Notes for Surface Spread of Flame (For information)	Walls		Ceilings	Features	Door Sets	Dado	Skirtings	Features	Door Sets	Skirtings	Features	Windows	Structural Exposed Steel	Features
									Lining Paper NBS M52/110	Paint	Paint											
B12	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	M60/114 Beam over door	NA	
B13b	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space and base of riser	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	M60/114 Beam over openings to B14a	NA	
B13c	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	M60/114 beams over openings to B13d	NA	
B13d	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	M60/114 Beams over openings to B13c	NA	
B13e	Escape corridor	Ceiling: White Walls: White	M60/172	NA	NA	NA	Existing masonry	Escape Route / Circulation	NA	NA	M60/173	NA	NA	NA	NA	NA	Out of scope	NA	NA	NA	NA	
B13f	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space	NA	NA	NA	NA	NA	NA	NA	NA	Out of scope	NA	NA	NA	M60/114 over MEP opening to B1d	NA
B14a	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space	NA	NA	NA	NA	NA	NA	NA	NA	Out of scope	NA	NA	NA	M60/114 diagonal steel, beams over MEP opening to riser and beams over door to B12	NA
B14b	Corridor	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Unused Space	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA	NA	NA	NA	NA	NA	NA	NA	
B14c	Lift Lobby	Ceiling: White Walls: White	M60/172	M60/173	NA	NA	Existing masonry	Escape Route / Circulation	NA	NA	NA	NA	NA	NA	NA	NA	Out of scope	NA	NA	NA	NA	
B14d	Plant	Out of scope	Out of scope	Out of scope	NA	NA	Existing masonry	Open plant space	NA	NA	NA	NA	NA	NA	NA	NA	Out of scope	NA	NA	NA	NA	
B14e	Unused Room	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Unused Room	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA	NA	NA	Out of scope	NA	NA	Out of scope	NA	
B14f	Plant and Lift Kit Room	Ceiling: White Walls: White	M60/172	M60/173	M60/172	NA	Existing masonry	Plant & Lift Kit Room & Base of riser	NA	NA	NA	NA	NA	NA	NA	NA	Out of scope	NA	NA	M60/631	M60/114 to beam supporting vaults	NA
B14g	Unused Room/Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Unused room	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA	NA	NA	NA	NA	NA	Out of scope	NA	
B14h	Unused Room	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Unused room	Out of scope	Out of scope	Out of scope	Out of scope	NA	NA	NA	NA	Out of scope	NA	NA	Out of scope	NA	
B15a	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	
B15b	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	
B15c	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	
B15d	Corridor	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Storage	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	NA	
B17d	Corridor	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Escape Route / Circulation	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	M60/114 to beams over openings to B17e & B17c	NA
B17e	Plant	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Existing masonry	Open plant space	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	Out of scope	M60/114 to beams over openings to B13f & B17d	NA

RTH.06
Decoration Schedule
Rochdale Town Hall - Phase 3

Appendix

**Reference Colour
Scheme Images:**



SCHEME 2

Colour Palette:

Dark Red: 4550 – Y90R
Mid Red: 030 40 40
Bright Red: 2070 – Y80R
Charcoal: 8500 - N
Lightest Green: F1730H
Light Green: F3680P
Mid Green: F4460V
Dark Green: F4261C
Darkest Green: F30 80R
Dark Beige: 1510 – Y20R
Light Beige: B57600
Stone Colour: "sandstone"
Gold Paint: TBC – samples required

RTH.06
Decoration Schedule
Rochdale Town Hall - Phase 3

Appendix

**Reference Colour
Scheme Images:**



Colour Palette:

Dark Red: 4550 – Y90R
Mid Red: 030 40 40
Bright Red: 2070 – Y80R
Charcoal: 8500 - N
Lightest Green: F1730H
Light Green: F3680P
Mid Green: F4460V
Dark Green: F4261C
Darkest Green: F30 80R
Dark Beige: 1510 – Y20R
Light Beige: B57600
Stone Colour: "sandstone"
Gold Paint: TBC – samples required

RTH.06
Decoration Schedule
Rochdale Town Hall - Phase 3

Appendix

**Reference Colour
Scheme Images:**

Ornate cornice in dark green, mid red, & dark beige



Colour Palette:

- Dark Red: 4550 – Y90R
- Mid Red: 030 40 40
- Bright Red: 2070 – Y80R
- Charcoal: 8500 - N
- Lightest Green: F1730H
- Light Green: F3680P
- Mid Green: F4460V
- Dark Green: F4261C
- Darkest Green: F30 80R
- Dark Beige: 1510 – Y20R
- Light Beige: B57600
- Stone Colour: "sandstone"
- Gold Paint: TBC – samples required

RTH.06
Decoration Schedule
Rochdale Town Hall - Phase 3

Appendix

**Reference Colour
Scheme Images:**

Simplified cornice in dark green & mid red.



Colour Palette:

- Dark Red: 4550 – Y90R
- Mid Red: 030 40 40
- Bright Red: 2070 – Y80R
- Charcoal: 8500 - N
- Lightest Green: F1730H
- Light Green: F3680P
- Mid Green: F4460V
- Dark Green: F4261C
- Darkest Green: F30 80R
- Dark Beige: 1510 – Y20R
- Light Beige: B57600
- Stone Colour: "sandstone"
- Gold Paint: TBC – samples required