

	
Item: 1 Description: Replacement tree in relation to discharging condition Nr6.	Item: 2 Description: Replacement tree in relation to discharging condition Nr6.
	
Item: 3 Description: New bin store in relation to discharging condition Nr7.	Item: 4 Description: Additional car parking spaces in relation to discharging condition Nr4.
	
Item: 5 Description: Additional car parking spaces (including accessible bays) in relation to discharging condition Nr4.	Item: 6 Description: Existing cycle storage retained and relocated in relation to discharging condition Nr5. The cycle storage had to be relocated as the car park would be locked to pupils and members of the public.

	
Item: 7 Description: One birch tree that was to be removed was retaining as it didn't hinder the works (in relation to condition Nr6).	