
EXISTING BUILDING
OH CABLE CARRIES ON OUT OF SITE BOUNDARY
SURVEYED WHERE POSSIBLE DUE TO POOR VISIBILITY
SURVEYED WHERE POSSIBLE DUE TO POOR VISIBILITY
TARMAC
CONCRETE TILES
BENCH
OLD MILLS HILL
BAYTREE LANE
BAYTREE LANE
GAS MONITORING POINTS
GAS MONITORING POINTS
GAS MONITORING UNDER CONSTRUCTION AT TIME OF SURVEY
GAS MONITOR UNDER CONSTRUCTION
GAS MONITORING POINTS
RED BRICK
RED BRICK
DAMSON GREEN
BRAMBLES
GRASS
GRASS
CONCRETE
CO OPERATIVE RD
COMBINED MANHOLE NOT LOCATED AT TIME OF SURVEY WITHIN THIS AREA
POSSIBLE OVERFLOW RELEASE WITHIN CHAMBER - SURCHARGED
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
EXISTING BUILDING
ME1C
ME1B
ME1A
ME1
JME1
JME2
SW1
SW2
SW3
SW4
SW5
SW6
SW7
SW8
SW9
SW10
SW11
SW12
SW13
SW14
SW15
SW16
SW17
SW18
SW19
SW20
SW21
SW22
SW23
SW24
SW25
SW26
SW27
SW28
SW29
SW30
SW31
SW32
SW33
SW34
SW35
SW36
SW37
SW38
SW39
SW40