


Image 01 - Gallery 02
Photograph c.1903



Notes:
Gallery 02 original exposed pipes heating system visible to walls at floor level. Image also shows the original entrance from the stair lobby.

Image 02 - Gallery 02
Photograph c.1915



Notes:
Gallery 02 original exposed pipes heating system visible to walls at floor level + extract at roof level. Image also shows the rear partition in it's original position, further back and in line with the end skylight.

Image 03 - Gallery 03
Photograph c.1915



Notes:
Gallery 03 original heating system - pipes covered by panelled 'shelf' to floor/ lower level forming consistent datum for exhibition wall space.

Image 04 - Gallery 04
Photograph c.1915



Notes:
Gallery 04 original heating system - pipes covered by panelled 'shelf' to floor/ lower level forming consistent datum for exhibition wall space. Ceiling extract visible at roof level.

