

Week 4 – W/E 06.09.2024 – Stage Floor lifted to reveal oriel window support frame



Upper oriel support frame exposed for inspection



Vertical mullion support steel and corroding fixings into the stone



Copings removed for re-bedding and lining



Skylight protected and flat roof inspected/works agreed



Loose/spalling stone facings removed and sample provided for stonework



Oriel Roof stripped to reveal structure



Gutter stonework uncovered for inspection



Chimney dismantled to sound brickwork and flues inspected



Oriel roof structure supported and exposed