

Packer Spout, Broadfield Slopes, Rochdale.
Photographs accompanying the survey drawings.



The condition survey of Packer Spout, Rochdale, was carried out on 11th October 2022. These photographs taken during the survey, are to be read with the condition survey drawings.

Stair 1.



Photograph 1



Photograph 2



Photograph 3



Photograph 4

Stair 2.



Photograph 5



Photograph 6



Photograph 7



Photograph 8



Photograph 9

Stair 3.



Photograph 10



Photograph 11

Stair 4



Photograph 12




Photograph 13

Stair 5.



Photograph 14



Photograph 15

Stair 6 and semi-circular wall.



Photograph 16



Photograph 17



Photograph 18



Photograph 19

Stair 7.



Photograph 20

Stair 8.



Photograph 21

Stair 9.



Photograph 22



Photograph 23



Photograph 24



Photograph 25

Upper Path.




Photograph 25

Lower walls and copings.



Photograph 26



Photograph 27



Photograph 28



Photograph 29 (above). Photograph 30 (below).





Photograph 31



Photograph 32



Photograph 33



Photograph 34




Photograph 35

Upper walls.



Photograph 36



Photograph 37



Photograph 38



Photograph 39



Photograph 40



Photograph 41



Photograph 42



Photograph 43



Photograph 44



Photograph 45



Photograph 46



Photograph 47

Upper paved areas.




Photograph 48



Photograph 49



Photograph 50



Photograph 51



Photograph 52

Fountain.



Photograph 53



Photograph 54



Photograph 55