Photographic Log – Supporting Information for Listed Building Consent Application for:

Birchinley Hall Farm, Wild House Lane, Milnrow



Photo 1: Existing Door and Combination Window Frame to be removed and replaced to match door in photo 3.



Photo 2: Rotten base to door – presenting security risk and allowing water to penetrate



Photo 3: Existing Main Entrance Door to Property to be retain and new door to match this door.



Photo 4: Existing Side Door to be removed and replaced with Window blank to maintain appearance of door from outside.



Photo 5: Existing Window to be removed, reveal removed below and new French windows to be inserted into existing structural opening. Reveals to be made good to match existing