

Exhibition Boards Substructure - Boards Removed
Photographs - February 2024



Image 01/04 -
Section of Exhibition boarding removed to reveal location of typical vent (gallery 04). However, a further board has been installed over the original T&G to block openings.



Image 02/04 -
Closer look at existing Steel/Timber substructure, installed to hold the contemporary exhibition boards.



Image 03/04 -
Exhibition boards contemporary installation date noted on concealed timber support (30/05/1977).



Image 04/04 -
Timber battens elements removed leaving steel structure fixed to original brickwork walls.