



EARTH ENVIRONMENTAL & GEOTECHNICAL
Houldsworth Mill Business & Arts Centre, Houldsworth Street,
Stockport, SK5 6DA

Tel: 0161 975 6088
Email: info@earthenvironmental.co.uk
Web: www.earthenvironmental.co.uk

HAND DUG VALIDATION PIT LOG

Project Name: Dobfield Road, Rochdale

Date: 15/10/2024

Project No.: A5182

Client: Jared Bullock


Hole Number: VP1

Logged By: A Horne

Total Depth: 0.60m

Remarks: N/A

Schematic Profile:



Legend	Depth (m)	Description
	0.00-0.20	TOPSOIL: Grass over dark brown sandy slightly gravelly CLAY. Gravel is fine to medium subangular to subrounded of sandstone and wood.
	0.20-0.60	MADE GROUND: Brown sandy gravelly CLAY. Gravel is fine to coarse angular to subangular of sandstone, brick and mudstone.

Validation pit terminated at 0.60m.

ES at 0.40

-No membrane located.

Photos:



VP1: Overview of Excavation.



VP1: Internal view of excavation.



EARTH ENVIRONMENTAL & GEOTECHNICAL
Houldsworth Mill Business & Arts Centre, Houldsworth Street,
Stockport, SK5 6DA
Tel: 0161 975 6088
Email: info@earthenvironmental.co.uk
Web: www.earthenvironmental.co.uk

HAND DUG VALIDATION PIT LOG

Project Name: Dobfield Road, Rochdale

Date: 15/10/2024

Project No.: A5182

Client: Jared Bullock


Hole Number: VP2

Logged By: A Horne

Total Depth: 0.75m

Remarks: N/A

Schematic Profile:



Legend	Depth (m)	Description
	0.00-0.20	TOPSOIL: Grass over dark brown sandy slightly gravelly CLAY. Gravel is fine to medium subangular to subrounded of sandstone and wood.
	0.20-0.75	MADE GROUND: Brown sandy gravelly CLAY. Gravel is fine to coarse angular to subangular of sandstone, brick and mudstone.

Validation pit terminated at 0.75m.

ES at 0.10, 0.40

-No membrane located.

Photos:



VP2: Overview of Excavation.



VP2: Internal view of excavation.



EARTH ENVIRONMENTAL & GEOTECHNICAL
Houldsworth Mill Business & Arts Centre, Houldsworth Street,
Stockport, SK5 6DA
Tel: 0161 975 6088
Email: info@earthenvironmental.co.uk
Web: www.earthenvironmental.co.uk

HAND DUG VALIDATION PIT LOG

Project Name: Dobfield Road, Rochdale

Date: 15/10/2024

Project No.: A5182

Client: Jared Bullock


Hole Number: VP3

Logged By: A Horne

Total Depth: 0.65m

Remarks: N/A

Schematic Profile:



Legend	Depth (m)	Description
	0.00-0.15	TOPSOIL: Grass over dark brown sandy slightly gravelly CLAY. Gravel is fine to medium subangular to subrounded of sandstone and wood.
	0.15-0.65	Dark brown slightly sandy slightly gravelly CLAY. Gravel fine to coarse subangular to subrounded of sandstone and mudstone.

Validation pit terminated at 0.65m.

ES at 0.10

-No membrane located.

Photos:



VP3: Overview of Excavation.



VP3: Internal view of excavation.



EARTH ENVIRONMENTAL & GEOTECHNICAL
Houldsworth Mill Business & Arts Centre, Houldsworth Street,
Stockport, SK5 6DA
Tel: 0161 975 6088
Email: info@earthenvironmental.co.uk
Web: www.earthenvironmental.co.uk

HAND DUG VALIDATION PIT LOG

Project Name: Dobfield Road, Rochdale

Date: 15/10/2024

Project No.: A5182

Client: Jared Bullock


Hole Number: VP4

Logged By: A Horne

Total Depth: 0.60m

Remarks: N/A

Schematic Profile:



Legend	Depth (m)	Description
	0.00-0.21	TOPSOIL: Grass over dark brown sandy slightly gravelly CLAY. Gravel is fine to medium subangular to subrounded of sandstone and wood.
	0.21-0.70	Dark brown slightly sandy slightly gravelly CLAY. Gravel fine to coarse subangular to subrounded of sandstone mudstone and slate.

Validation pit terminated at 0.60m.

ES at 0.60

-No membrane located.

Photos:



VP4: Overview of Excavation.



VP4: Internal view of excavation.



EARTH ENVIRONMENTAL & GEOTECHNICAL
Houldsworth Mill Business & Arts Centre, Houldsworth Street,
Stockport, SK5 6DA
Tel: 0161 975 6088
Email: info@earthenvironmental.co.uk
Web: www.earthenvironmental.co.uk

HAND DUG VALIDATION PIT LOG

Project Name: Dobfield Road, Rochdale

Date: 15/10/2024

Project No.: A5182

Client: Jared Bullock


Hole Number: VP5

Logged By: A Horne

Total Depth: 0.70m

Remarks: N/A

Schematic Profile:



Legend	Depth (m)	Description
	0.00-0.25	TOPSOIL: Grass over dark brown sandy slightly gravelly CLAY. Gravel is fine to medium subangular to subrounded of sandstone and wood.
	0.25-0.65	Greyish brown slightly sandy very gravelly CLAY. Gravel fine to coarse angular to subangular of slate, sandstone and mudstone.
	0.65-0.70	Brown very sandy slightly gravelly CLAY. Gravel fine to medium subangular to subrounded of sandstone.

Validation pit terminated at 0.70m.

ES at 0.20, 0.50

-No membrane located.

Photos:



VP5: Overview of Excavation.



VP5: Internal view of excavation.