


Existing suspended ceiling partially covering top portion of the window



Alternative view of existing suspended ceiling covering top part of window compared to rest of showroom beyond



Existing steelwork is boxed in & painted grey. Proposed steelwork will be boxed in and painted to match the existing, at the same height.



LD25150 Gymbound Existing Steelwork & Suspended Ceiling Detail